

3M™ Motor Lead Inline Splice 5331, 5332, 5333 & 5334


for 5/8 kV Non-Shielded and Shielded Cables
(Ribbon, Wire and UniShield® Cables)

Instructions

Cable Size Range:
Feeder: #8 AWG – 500 kcmil
Motor Lead: #10 AWG – 500 kcmil
Copper Conductors

⚠ CAUTION

Working around energized systems may cause serious injury or death. Installation should be performed by personnel familiar with good safety practice in handling electrical equipment. De-energize and ground all electrical systems before installing product.



Kit Contents

- 3 Cold Shrink Tube
- 12 Adapters
- 3 Rolls Scotch® Stress Control Tape 2220
- 3 Bags Solvent Cleaning Cloth
- 6 Tubes Silicone Grease
- 3 Rolls Scotch® Linerless Rubber Splicing Tape 130C
- 3 Instruction Sheets

Requires Vinyl Tape that is not in kit

*Quantity varies with kit number

Kit Selection Table

Kit Number	Cable Size Range (AWG/kcmil)		Max Bolt Length
	Feeder	Motor Lead	
5331	8 – 4	10 – 4	3/4 in.
5332	2 – 1/0	4 – 1/0	1 1/4 in.
5333	1/0 – 250	2 – 250	1 1/2 in.
5334	250 – 500	4/0 – 500	1 1/2 in.

Table 1

Adapter Selection Chart for Cable Size Ranges

Kit Number	Adapter Size	Cable Size Range (AWG / kcmil)	Insulation O.D. Range
	Length X I.D.		
5331	4 in. X .24 in I.D.	10 – 6	.30 – .46 in.
	3 1/2 in. X .30 in I.D.	6 – 4	.37 – .51 in.
5332	3 1/2 in. X .30 in I.D.	4 – 2	.43 – .57 in.
	3 1/2 in. X .42 in I.D.	2 – 1/0	.52 – .65 in.
5333	4 in. X .50 in I.D.	2 – 2/0	.53 – .71 in.
	4 1/8 in. X .60 in I.D.	3/0 – 250	.70 – .88 in.
5334	5 in. X .60 in I.D.	4/0 – 350	.75 – .98 in.
	5 in. X .84 in I.D.	350 – 500	.94 – 1.12 in.

Table 2

Instructions for 5/8 kV Inline Non-Shielded Feeder Cables

1.0 Prepare Cable According to Standard Procedures

NOTE: The Scotch® Stress Control Tape 2220 will not be used for non-shielded cable.

- 1.1 Check to be sure cables fit within cable kit range as shown in *Table 1*.
- 1.2 Remove cable insulation for length recommended by terminal lug manufacturer; if no information is available, remove for depth of lug barrel.
- 1.3 Clean insulation for approximately 6" using solvent saturated cloth provided in kit.

2.0 Install Lugs

- 2.1 Install and crimp lugs per manufacturer's direction. See back page if 3M™ Scotchlok™ Lugs are used.
- 2.2 FOR 8kV ONLY. Fill lug/insulation gaps with Scotch® Linerless Rubber Splicing Tape 130C (*Figure 1*).




Figure 1

3.0 Slide on Adapters, Cold Shrink and Bolt Lugs Together

- 3.1 Determine proper adapter size for each cable from *Table 2*.
- 3.2 Apply silicone grease to the inside at one end of the adapters. (If necessary grease cables). Slide (grease end first) onto lugs and cables just far enough to clear the lug holes (*Figure 2*).

HINT: When installing adapters, the use of a clean cloth or rag to grip them will aid in their movement.

- 3.3 Slide the Cold Shrink Insulator onto the smallest cable. The direction of the loose core end tab should be where it is most easily removed later (*Figure 2*).




Figure 2

3.4 Remove silicone grease from lugs. Bolt lugs together (see *Table 1* for maximum bolt length). See *Figure 3* for proper lug/bolt arrangement.




Figure 3

3.5 Cover the lugs and bolt with four half-lapped layers of Scotch® Linerless Rubber Splicing Tape 130C (*Figure 4*).




Figure 4

3.6 Slide adapters toward the bolt(s) as far as possible (*Figure 5*).




Figure 5

4.0 Install Cold Shrink Insulator

4.1 Center Cold Shrink insulator over connected lugs and remove core by unwinding counter-clockwise (*Figure 6*).

TIP: An occasional tug of the strand while unwinding will aid in core removal.




Figure 6

NOTE: The Cold Shrink may extend beyond the adapters and may not make contact with the cable insulation. Although this will not result in a leak problem, (seal is made at adapter) it can be cut off flush with end of adapter if desired.

Instructions for 5/8 kV Inline Shielded Feeder Cables (Ribbon, Wire Shielded and UniShield® Cables)

5.0 Prepare Cable According to Standard Procedures

5.1 Check to be sure cables sizes fit within cable kit range as shown in *Table 1*.

For Non-Shielded Motor Lead Cable

5.2 Remove cable insulation for length recommended by terminal lug manufacturer; if no information is available, remove for depth of lug barrel.

5.3 Clean insulation for approximately 6" using solvent saturated cloth provided in kit.

For Shielded Feeder Cable

For Ribbon Shielded Cable see *Figures 7a, 8a and 9a*.

For Wire Shielded Cable see *Figures 7b, 8b and 9b*.

For UniShield® Cable see *Figures 7c, 8c and 9c*.

5.4 Prepare cable by removing jacket and shielding per dimensions as shown in *Figures 7 and 8*, depending on type of cable shielding.

NOTE: If practice calls for grounding shield, do not cut shield wires. See *grounding*.

5.5 Remove cable insulation for length recommended by terminal lug manufacturer; if no information is available, remove for depth of lug barrel. See *Figure 7a, 7b and 7c*, depending on type of cable shielding.




Figure 7a




Figure 7b




Figure 7c

5.6 Clean cable insulation by using solvent saturated cloths. **Do not allow solvent to touch cable semi-con.** If abrasive must be used to remove imbedded semi-con from cable insulation, use a non-conductive, 120 grit aluminum oxide, such as in the Scotch® Cable Prep Kit CC-2.

6.0 Install Stress Relief

6.1 Apply two half-lapped layers of Scotch® Stress Control Tape 2220 for 1/4" onto the cable semi-con (1/2" onto UniShield® jacket) and extend two inches onto cable insulation (wrap tape silver side out). *Figures 8a, 8b or 8c,* depending on type of cable shielding.




Figure 8a




Figure 8b




Figure 8c

- 6.2 Wrap two half-lapped layers of vinyl tape over the Scotch® Stress Control Tape 2220 and one inch onto cable jacket. (1/2" beyond cut off, bent back shield wires for wire and UniShield® cables. Figures 9a, 9b or 9c, depending on type of cable shielding).




Figure 9a




Figure 9b




Figure 9c

NOTE: Grounding

If practice calls for grounding the splice a 3M™ Ground Strap Assembly Kit (GS-1, GS-2 and GS-3) is available from your local distributor for use on ribbon shield cable. Follow procedure for these kits for grounding. For UniShield and wire shield cable, a ground strap assembly kit is not necessary. Simply fold the wires back over jacket and use them to connect to the system ground.

7.0 Install Lugs

- 7.1 Install and crimp lugs per manufacturer’s direction; see back page if 3M™ Scotchlok™ Lugs are used.
- 7.2 FOR 8kV ONLY. Fill lug/insulation gaps with Scotch® Linerless Rubber Splicing Tape 130C (Figure 10).




Figure 10

8.0 Slide on Adapters, Cold Shrink and Bolt Lugs Together

- 8.1 Determine proper adapter size for each cable form (*Table 2*).
- 8.2 Apply silicone grease to the inside at one end of the adapters. (If necessary grease cables). Slide (grease end first) onto lugs and cables just far enough to clear the lug holes (*Figure 11*).

HINT: When installing adapters, the use of a clean cloth or rag to grip them will aid in their movement.

- 8.3 Slide the Cold Shrink Insulator onto the smallest cable. The direction of the loose core end tab should be where it is most easily removed later (*Figure 11*).




Figure 11

- 8.4 Remove silicone grease from lugs. Bolt lugs together (see *Table 1* for maximum bolt length). See *Figure 12* for proper lug/bolt arrangement.




Figure 12

- 8.5 Wrap rubber tape over bolts to round off sharp edges. Apply a minimum of four layers over each bolt end. Use medium tension when applying (*Figure 13*).




Figure 13

8.6 FOR 8 kV ONLY. Cover the lugs and bolt with four half-lapped layers of Scotch® Linerless Rubber Splicing Tape 130C (Figure 14).




Figure 14

8.7 Slide adapters toward the bolt(s) as far as possible (Figure 15).




Figure 15

9.0 Install Cold Shrink Insulator

9.1 Center Cold Shrink over connected lugs and remove core by unwinding counter-clockwise. (Figure 16).

TIP: An occasional tug of the strand while unwinding will aid in core removal.




Figure 16

Tooling Index

Lug and Crimping Information for 3M™ Scotchlok™ Copper Lugs	
30014 thru 30045 One hole 	31145 thru 31166 Two hole 

Copper Lugs

Cable Size	Stud Size	3M™ Scotchlok™ Copper Lug Number	CRIMPING TOOL-DIE SETS (NUMBER OF CRIMPS)							
			Burdny Corporation				Thomas & Betts Corporation			Square D Co. Anderson Div.
			MD6	MY29	Y34A	Y35, Y39, Y45*, Y46*	TBM 5	TBM 8	TBM 15	VC6-3 VC6-FT**
6	10 1/ 5/164	30014 30015 30016	—	6 AWG (1)	—	U5CRT (1)	Blue (1)	Blue (1)	—	Universal (1)
4	10 1/4 3/8	30018 30019 30021	W161 (1)	4 AWG (1)	A4CR (1)	U4CRT (1)	Grey (1)	Grey (1)	—	Universal (1)
2	1/4 5/16 3/8	30022 30023 30024	W162 (2)	2 AWG (1)	A2CR (1)	U2CRT (2)	Brown (1)	Brown (1)	33 (1)	Universal (2)
1	5/16 3/8	30027 30028	—	1 AWG (1)	A1CR (1)	U1CRT (2)	Green (1)	Green (1)	37 (1)	Universal (2)
1/0	5/16 3/8	30031 30032	W163 (2)	1/0 (1)	A25R (1)	U25RT (1)	Pink (2)	Pink (2)	42H (2)	Universal (1)
2/0	3/8	30036	W241 (2)	2/0 (1)	A26R (1)	U26RT (2)	Black (2)	Black (2)	45 (1)	Universal (1)
3/0	1/2	30041	W243 (2)	3/0 (1)	A27R (1)	U27RT (2)	Orange (2)	Orange (2)	50 (1)	Universal (2)
4/0	1/2 1/2	30045 31145	BG (3) BG (4)	4/0 (1) 4/0 (2)	—	U28RT (2) U28RT (3)	Purple (2) Purple (3)	Purple (2) Purple (3)	54H (2) 54H (3)	Universal (2) Universal (3)
250	1/2	31149	W166 (4)	250 (2)	A29R (2)	U29RT (3)	Yellow (2)	Yellow (2)	62 (2)	Universal (2)
300	1/2	31153	—	—	A30R (2)	U30RT (3)	—	White (3)	66 (3)	Universal (3)
350	1/2	31156	—	—	A31R (2)	U31RT (3)	—	Red (4)	71H (4)	—
400	1/2	31160	—	—	A32R (2)	U32RT (3)	—	Blue (4)	76H (4)	—
500	1/2	31166	—	—	A34R (2)	U34RT (3)	—	Brown (4)	87H (4)	—

Y45 and Y46 accept all Y35 dies ("U" series). For Y45 use PT6515 adapter. For Y46 use PUADP adapter.

**Anderson VC6-3 and VC6-FT require no die set.

3M and Scotchlok are trademarks of 3M Company. Scotch is a registered trademark of 3M Company. UniShield is a registered trademark of General Cable Technologies Corporation.

Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one (1) year from the time of purchase. **3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.** If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. **Except where prohibited by law, 3M will not be liable for any indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.**



Electrical Markets Division

6801 River Place Blvd.
Austin, TX 78726-9000
800-245-3573
Fax 800-245-0329
www.3M.com/electrical

Please Recycle. Printed in USA.
© 3M 2009. All Rights Reserved.
78-8096-4636-3-D