

MX-43 Instruction Manual Temperature Calibrator for Moisture Analyzer MX-50

Safety Information

It recommends that you read the safety and operation instructions before using the thermometer.

Repair: Do not disassemble the instrument to

avoid damage and fire.

Troubleshooting: Contact the local A&D dealer to repair the

instrument.

Description

Caution A potentially hazardous situation which, if not avoided, may result in minor or moderate injury.

Caution for Battery Handling

- Do not charge it. Do not short terminals. Do not disassemble it. Do not burn or through it into fire.
- Dispose it according to the regulations.

-1-WM:PD4000521

3. Specifications

General(Thermometer)

3 1/2 digit LCD with maximum reading of 1999 Display: Battery: 9V battery (NEDA 1604,IEC 6F22)

Battery Life: 200 hours typ. with carbon zinc battery

Ambient operation:

0°C ~ 50°C (32°F ~ 122°F)

Ambient relative humidity:

0% ~ 80%RH, 0°C ~ 35°C (32°F ~ 95°F)

0% ~ 70%RH, 35°C ~ 50°C (95°F ~ 122°F)

Storage temperature:

-20°C ~ 60°C $(-4^{\circ}F \sim 140^{\circ}F)$

Storage relative humidity: 0% ~ 80%RH

Dimensions: 147(H)×70(W)×39(D) mm

Mass: Approximately 210g (7.4oz.)

4. Operation and Functions

4.1. Select a Unit

Press the °C key to use the unit of Celsius in the temperature calibration of the moisture analyzer.

- The last unit is stored in the thermometer.
- Pressing the F key, a Fahrenheit value is displayed.

Note

- When the measurement value is out of range or the sensor is not connected, "OL" is displayed.
- The OFFSET volume is sealed because it is calibrated.

4.2. Selecting the Display Resolution

Press the 1° key to change the resolution in the temperature calibration of the moisture analyzer.

Pressing the 1° or 0.1° key, the display resolution can be selected. Resolution: 0.1°C (0.1°F) or 1°C (1°F) -3-

2. Introduction

The temperature calibrator consists of a digital thermometer and a sensor pan with a K-type thermocouple in the center. The instrument displays the temperature data used at the calibration of the drying temperature.


Install the battery before use.

Refer to "5. Battery Replacement".

Refer to the "Calibration of Drying Temperature for MX-50" for the temperature calibration method.

Caution

Do not input a voltage that exceeds 24VAC or 60VDC, to avoid getting an electric shock.



4.3. Hold Mode

Do not use the hold function in the temperature calibration of the moisture analyzer.

- Press the HOLD key to hold the data. Then the "D-H" indicator is displayed and the present reading value is displayed and stops all further measurements.
- Press the HOLD key again to cancel the hold function. Then the thermometer resumes measurement.

4.4. MAX mode

Do not use the MAX function in the temperature calibration of the moisture analyzer.

- Pressing the MAX key, the maximum value is updated and is displayed always. Pressing the MAX key again, the MAX function is canceled,
- Pressing the HOLD key while the maximum value is displayed, the value is not updated. Pressing the HOLD key again, the value is updated.

5. Battery Replacement

Caution Remove the sensor from the thermometer before battery replacement, to avoid affecting the circuit.

Procedure of Battery Replacement

When the battery needs replacement, $\stackrel{\square}{\boxminus}$ is displayed. Remove the three screws at the bottom case.

Remove the bottom case and replace the battery with a

Close the bottom case and replace the three screws.

- 4 -