

AC Machines: Synchronous Machine

Alternators On Load

Prof. Sidhartha Panda

Department of Electrical Engineering

VSSUT, Burla

Alternators On Load

❖ On no-load: $E_{ph} = 2.22K_w\phi Z_{ph}f = 2.22K_cK_d\phi Z_{ph}f$ Volts

$$K_c = \cos \frac{\alpha}{2} \quad K_d = \frac{\sin \frac{m\beta}{2}}{m \sin \frac{\beta}{2}} \quad m = \frac{\text{slots}}{\text{poles} \times \text{phases}} \quad \beta = \frac{180^\circ}{\text{slots/pole}}$$

❖ Whenever the load on the alternator is varied, the terminal voltage will also vary.

❖ This variation in terminal voltage is mainly due to three reasons:

- ✓ Voltage drop due to armature resistance (IR_a)
- ✓ Voltage drop due to armature leakage reactance (IX_L)
- ✓ Voltage drop due to armature reaction.

Alternators On Load


Voltage drop due to armature resistance (IR_a)

- ❖ The armature winding resistance per phase will cause a IR_a voltage drop per phase.
- ❖ The voltage drop due to armature resistance is in phase with the armature current I

Voltage drop due to armature leakage reactance (IX_L)

- ❖ When current flows through armature conductors, the flux will start to flow through the armature core.
- ❖ Some flux will take different paths and do not cross the air gap which is called leakage flux.
- ❖ Leakage flux depends on the current flowing through the conductor.
- ❖ This leakage flux will set up an emf because of self-inductance.
- ❖ This emf leads the armature current I by 90° .


Alternators On Load: Leakage Flux



- ❖ The armature winding is said to possess a leakage reactance X_L .
- ❖ The voltage drop due to this reactance is IX_L .
- ❖ The generated emf has to overcome the voltage drop due to leakage reactance to give its output.
- ❖ $E = V + I(R_a + jX_L)$

Alternators On Load: Phasor Diagram


- ❖ The voltage phasor is taken as the reference phasor.
- ❖ The armature current lags behind the voltage by an angle Φ .
- ❖ Hence the current phasor is drawn at an angle Φ from the voltage phasor.
- ❖ The phasor for armature resistance drop is drawn parallel to the current phasor from the extremity of Voltage phasor V .
- ❖ Leakage reactance drop is drawn perpendicular to the current phasor from the extremity of IR_a phasor.
- ❖ Join 0 and the extremity of IX_L phasor to get E .



Production of Rotating Magnetic Field

- ❖ When a 3-phase winding is energized from a 3-phase supply, a rotating magnetic field is produced.
- ❖ This field is such that its poles do not remain in a fixed position on the stator but go on shifting their positions around the stator.
- ❖ For this reason, it is called a rotating field.
- ❖ Consider a three phase windings displaced in space by 120° , supplied by a three phase a.c supply.
- ❖ The three phase currents are also displaced from each other by 120° .
- ❖ The flux produced by each phase current is also sinusoidal in nature and all three fluxes are separated from each other by 120° .
- ❖ If the phase sequence of the windings is 1-2-3, then the mathematical equation for the instantaneous values of the fluxes Φ_1 , Φ_2 and Φ_3

Production of Rotating Magnetic Field



As windings are identical and supply is balanced the amplitude of each flux is same i.e. Φ_m . The waveforms of three fluxes are shown in figure.

The mathematical equation for the instantaneous fluxes Φ_1 , Φ_2 and Φ_3

$$\Phi_1 = \Phi_m \sin(\omega t) = \Phi_m \sin \theta$$

$$\Phi_2 = \Phi_m \sin(\omega t - 120^\circ) = \Phi_m \sin(\theta - 120^\circ)$$

$$\Phi_3 = \Phi_m \sin(\omega t - 240^\circ) = \Phi_m \sin(\theta - 240^\circ)$$

- ❖ The resultant flux Φ_T at any instant is given by phasor combination of Φ_1 , Φ_2 and Φ_3 at that instant.
- ❖ Let us find out Φ_T at four different instants 1, 2, 3 and 4

Production of Rotating Magnetic Field

Case (i) $\theta = 0^\circ$

- ✓ $\Phi_1 = \Phi_m \sin 0^\circ = 0$
- ✓ $\Phi_2 = \Phi_m \sin (-120^\circ) = -0.866 \Phi_m$
- ✓ $\Phi_3 = \Phi_m \sin (-240^\circ) = +0.866 \Phi_m$
- ✓ And $\Phi_T = \Phi_1 + \Phi_2 + \Phi_3$

✓ BD is perpendicular drawn from B on ' Φ_T '


$$OD = DA = \frac{\phi_T}{2}$$

In ΔOBD , $\angle BOD = 30^\circ$

$$\cos 30^\circ = \frac{OD}{OB} = \frac{\left(\frac{\phi_T}{2}\right)}{0.866 \phi_m}$$

$$\phi_T = 2 \times 0.866 \phi_m \times \cos 30^\circ$$

$$\phi_T = 1.5 \phi_m$$




Production of Rotating Magnetic Field


Case (ii) $\theta = 60^\circ$

- ✓ $\Phi_1 = \Phi_m \sin 60^\circ = +0.866 \Phi_m$
- ✓ $\Phi_2 = \Phi_m \sin (-60^\circ) = -0.866 \Phi_m$
- ✓ $\Phi_3 = \Phi_m \sin (-180^\circ) = 0$
- ✓ And $\Phi_T = \Phi_1 + \Phi_2 + \Phi_3$


The magnitude of the resultant is same as before but it is rotated in space by 60° in clockwise direction, from its previous position



Case (iii) $\theta = 120^\circ$



Case (iv) $\theta = 180^\circ$



Production of Rotating Magnetic Field

- ❖ The resultant of the three alternating fluxes, separated from each other by 120° , has a constant amplitude of $1.5 \Phi_m$, where Φ_m is the maximum amplitude of an individual flux due to any phase.
- ❖ The resultant always keeps on rotating with a certain speed in space
- ❖ Hence we can include that the three phase stationary winding when connected to a three phase a.c. supply produces a rotating magnetic field.
- ❖ The speed of the resultant is 180° in space, for 180° electrical of the fluxes for a 2 pole.
- ❖ If the winding is wound for P poles, then resultant will complete $2/p$ revolutions for 360° electrical of the fluxes.
- ❖ So resultant flux bears a fixed relation between the speed of rotation (N_s), supply frequency (f) and the number of poles (P) for which winding is wound.
- ❖ So for a rotating magnetic field: $N_s = 120.f/P$ r.p.m.

Production of Rotating Magnetic Field

- ❖ The resultant of the three alternating fluxes, separated from each other by 120° , has a constant amplitude of $1.5 \Phi_m$, where Φ_m is the maximum amplitude of an individual flux due to any phase.
- ❖ The resultant always keeps on rotating with a certain speed in space
- ❖ Hence we can include that the three phase stationary winding when connected to a three phase a.c. supply produces a rotating magnetic field.
- ❖ The speed of the resultant is 180° in space, for 180° electrical of the fluxes for a 2 pole.
- ❖ If the winding is wound for P poles, then resultant will complete $2/p$ revolutions for 360° electrical of the fluxes.
- ❖ So resultant flux bears a fixed relation between the speed of rotation (N_s), supply frequency (f) and the number of poles (P) for which winding is wound.
- ❖ So for a rotating magnetic field: $N_s = 120.f/P$ r.p.m.

Armature Reaction in Alternators


- ❖ Armature reaction in alternator is defined as the effect of armature flux on the main flux produced by the field poles.
- ❖ Armature reaction depend on the type of load applied to the alternator (UPF, ZPF lag/lead, Lag/lead)

Unity Power Factor (UPF): Purely Resistive Load

- ❖ When a resistive load with a unity power factor is connected to the alternator, the load current will start to flow through the armature winding.
- ❖ As it is a pure resistive load, the armature current will be in phase with the induced voltage.
- ❖ The armature current will produce its own flux in the conductor, which will also be in phase with the induced voltage.
- ❖ Since the induced emf lags behind the main field flux by 90° , the armature flux produced will also be delayed by 90° with respect to the main flux.

Armature Reaction in Alternators


Unity Power Factor (UPF):



- ❖ As the armature flux act on the main field flux perpendicularly, the distribution of main field flux under a pole face does not remain uniformly distributed.
- ❖ Flux density at the trailing tip of the pole is increased while flux at the leading tip of the pole decreases.
- ❖ The armature flux will cross and distorts the main field flux at one point, thereby weakening the main flux.
- ❖ This is said to be a **cross magnetizing effect**.

Armature Reaction in Alternators


Zero Power Factor Lag (ZPF Lag):



- ❖ When a pure inductive load with zero lagging power factor is connected to the alternator, the armature current will be delayed by 90° and so the armature flux produced will also be shifted by 90° with respect to the poles.
- ❖ The armature flux will be in direct opposition to the main flux.
- ❖ This effect of armature reaction on this load (ZPF Lag) is said to be a **demagnetizing effect**.

Armature Reaction in Alternators

Zero Power Factor Lead (ZPF Lead):



- ❖ When a pure capacitive load with zero leading power factor is connected, the load current will be advanced by 90° and so the armature flux produced will also be advanced by 90° with respect to emf induced.
- ❖ So the armature flux will be in phase with the main field flux, resulting in strengthening of the field flux.
- ❖ Thus the main flux gets increased in this loading condition.
- ❖ This effect of armature reaction on this load (ZPF Lead) is said to be a **magnetizing effect**.

Armature Reaction in Alternators



- ❖ When an alternator supplies a load at the unity power factor, the effect of armature reaction is partly cross magnetizing and partly distorting.
- ❖ The effect of armature reaction is demagnetizing when an alternator supplies a load at a lagging power factor.
- ❖ When an alternator supplies a load at the leading power factor, the effect of armature reaction is magnetizing.
- ❖ When an alternator supplies a load at the intermediate power factor, the effect of armature reaction is partly distorting and partly demagnetizing.
- ❖ The effects of armature reaction may cause the generated emf to vary.
- ❖ The voltage drop due to armature reaction may be assumed as there is a presence of fictitious reactance X_a called armature reactance reaction.
- ❖ The voltage drop due to the armature reaction is represented as IX_a .

Armature Reaction in Alternators

- ❖ The leakage reactance X_L and armature reaction reactance X_a together called synchronous reactance X_S . ($X_S = X_L + X_a$)
- ❖ Thus the voltage drop in an alternator under loaded conditions is the total sum of voltage drop due to armature resistance, armature leakage reactance, and armature reaction reactance.
- ❖ $V = I R_a + j I X_L + j I X_a = I (R_a + j X_L + j X_a) = I (R_a + j (X_L + X_a))$
- ❖ $V = I (R_a + j X_S) = I Z_S$
- ❖ Where Z_S is known as the **synchronous impedance** of an alternator.
- ❖ **Phasor Diagrams:**
 - ✓ E_0 is the no-load voltage. It is the maximum voltage induced in the armature without giving any load.
 - ✓ E is the load voltage. It is the induced voltage after overcoming the armature reaction. E is vectorially less than the no-load voltage.
 - ✓ I is the armature current per phase
 - ✓ V is the terminal voltage. .

Armature Reaction in Alternators

Unity Power Factor (UPF):





$$(OD)^2 = (OC)^2 + (CD)^2 = (OA + AC)^2 + (CD)^2$$

$$E_a^2 = (V + I_a R_a)^2 + (I_a X_s)^2$$

$$E_a = \sqrt{(V + I_a R_a)^2 + (I_a X_s)^2}$$

Armature Reaction in Alternators

Lagging Power Factor:





$$OD^2 = OG^2 + GD^2 = (OF + FG)^2 + (GC + CD)^2$$

$$E_a^2 = (V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_s)^2$$

$$E_a = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi + I_a X_s)^2}$$

Armature Reaction in Alternators

Leading Power Factor:



$$OD^2 = OG^2 + GD^2 = (OF + FG)^2 + (GC - CD)^2$$

$$E_a^2 = (V \cos \phi + I_a R_a)^2 + (V \sin \phi - I_a X_s)^2$$

$$E_a = \sqrt{(V \cos \phi + I_a R_a)^2 + (V \sin \phi - I_a X_s)^2}$$