

LECTURE-24

FREE ENERGY COMPOSITION DIAGRAM FOR BINARY ALLOYS SYSTEMS: The free energy of each of phase's presents on a phase diagram can be plotted as a function of composition at a series of temperature. The phases co-exist in equilibrium are those correspond to the lowest free energy of the system.




Fig. Free energy – composition relationships for an isomorphous system at three temperatures, Ref-Raghavan, V. (2012). *Physical metallurgy: principles and practice*. PHI Learning Pvt. Ltd.




Fig. - Free energy vs. composition relationships for a simple eutectic system at different temperature,
 Ref-Raghavan, V. (2012). *Physical metallurgy: principles and practice*. PHI Learning Pvt. Ltd.

Continued...

Binary Phase Diagram: The most commonly used phase diagrams are those that depict the equilibrium between two components. These are known as binary phase diagrams.

Example: (Fe-Fe₃C) phase diagram, (Cu – Ni) phase diagram.

For graphical representation of the binary phase relationships, we need a map with three axes corresponding to temperature, pressure & composition. For binary phase diagrams, we ignore the pressure variable & the vapor phase. As one of the variables has been arbitrarily omitted the phase rule for condensed phases (i.e. liquid & solids) only is written as

$$F = C - P + 1 \quad (276)$$

Continued...

Isomorphous system: An Isomorphous system defined as the simplest binary phase diagram for a system that exhibiting complete liquid as well as solubility.

Example: Cu – Ni phase diagram

M. pt of Cu \rightarrow 1083 $^{\circ}$ C, M. pt of Ni \rightarrow 1455 $^{\circ}$ C




Fig-The Copper-Nickel phase diagram, showing complete solubility both in the liquid and in the solid states.

Continued...

- ❑ The liquid & solid regions are separated by a two-phase region, where both the phase co-exists.
- ❑ The boundary between two-phase region & the liquid is called liquidous line. The boundary between the two-phase region & the solid is called solidus line.
- ❑ **Solvus Line:** It is the solid-state phase boundary between the terminal solid solution & the two-phase region.

EXPERIMENTAL DETERMINATION OF PHASE DIAGRAMS: A variety of physical techniques are used for the experimental determination of phase diagrams. Among these the most important techniques are

1. Thermal analysis.
2. Microscopic examination.
3. X-ray diffraction.

Continued...

Determination of Liquidus and Solidus:

- Thermal analysis is the most important method for determination of the liquid-solid transformations
- This method based on evolution or absorption of heat occurs during a phase change
- When the temperature of an alloy sample is plotted as a function of time during heating or cooling, abrupt changes in slope of plot occur at points corresponding to the start or finish of a phase change

Cooling Curves: Curves of single composition for different conditions using thermal analysis explained below.

Case – I: [*For pure metal without super cooling*] In this case, evolution of latent heat due to start of solidification is equal to heat loss due to surroundings (refer fig. (a)). **Example:** Pure metals like Fe, Cu, Ni etc.




Fig-Thermal analysis. Cooling curves (a) for a pure metal without supercooling, (b) for a pure metal with supercooling, (c) for a solid solution alloy, (d) for a hypoeutectic alloy, Ref-Raghavan, V. (2012). *Physical metallurgy: principles and practice*. PHI Learning Pvt. Ltd.

Continued...

Case – II: *[For a pure metal with super-cooling]*

- In this case, evolution of latent heat due to the solidification less than heat lost to the surroundings and this process is known as Super-cooling (refer fig. (b)).
- Once Solidification starts heat evolution raise the sample temperature back to freezing point

Case – III: *[For a solid solution alloys]*

- From fig. (c) we have, first arrest indicating abrupt decrease in the cooling rate occurs as the liquidus temperature T_l is crossed. Since, over a range of temperature the solidification occurs. So there is no horizontal part.
- The second arrest is observed at the solidus temperature T_s , when the cooling rate starts to increase again.

Continued...

Case – IV: [For a hypothetical alloy or pro-eutectic binary alloy]

- From fig. (d) we have, Peritectic alloy also shows the similar behavior as pro-eutectic or hyper-eutectic alloy.
- First arrest occurs at the liquidus temperature & the cooling rate decreases.
- At the eutectic temperature T_e , the cooling curve becomes horizontal as invariant eutectic reaction occurs isothermally. The cooling rate increases again when the eutectic solidification is complete.

Continued...

Following precautions are taken to determining cooling curves

- ☐ Local fluctuations of temperature in the furnace should be avoided.
- ☐ For the achievement of near equilibrium conditions, the rate of cooling must be slow as feasible.
- ☐ To reduce super cooling, the molten alloy should be stirred for uniform temperature.
- ☐ Composition analysis must be accurate.
- ☐ No contamination must occur from the crucible, thermocouple sheath etc.

Continued...

- Solidus is determined by approximate lines in cooling curve, as coring tends to lower the solidus temperature.
- A more accurate determination can be carried out by holding the solidified alloy for a long time for homogenization just below the approximate solidus temperature determined from cooling curve.
- The alloy heated again to find the breaking in the heating curve. This break is at a higher temp than that determined during cooling as coring effects are removed by homogenization.

Continued...

Coring: Above solidus temperature same liquid remains without transfer to solid is known as coring.

- ❑ Thermal analysis can be replaced with microscopic examination; the alloy is heated close to the solidus & quenched to ascertain microscopically the appearance of the first chilled liquid.
- ❑ Using the break in the cooling & heating curves for a series of compositions covering the entire binary range, the liquidus & solidus boundaries can be fully determined.

Continued...

Determination of the Solvus:




Fig-Determination of Solvus boundaries by the metallographic & X-ray methods, Ref- Raghavan, V. (2012). *Physical metallurgy: principles and practice*. PHI Learning Pvt. Ltd.

Continued...

- The common methods for determining the Solvus are microscopic examination & X-ray diffraction.
- A series of small ingots of alloys of different compositions are prepared and homogenized. They are then annealed at various temperatures for prolonged time (a few days) and quenched.
- In such cases, subsequent metallographic and X-ray studies at room temperature disclose the appearance of second phase at some known composition.
- In other cases, at high temperature phase may decompose on quenching, If this happens room temperature, X-ray studies are not suitable. So a high temperature X-ray camera used.
- But even after the decomposition during quenching the metallographic method may be useful, if the transformed phase is in an easily recognizable form.
- A phase boundary is first bracketed between two compositions and then exact location of boundary is determined by studying a few more alloys of closely varying composition in the boundary region.