

FT-112 Quick Guide-Calibration



Important note:

This Quick Guide does NOT replace the technical manual but merely serves as a guide for commissioning of the weighing terminal type FT-112.


1. Mechanical installation must be carried out in accordance with the requirements

Refer to Technical Manual, chapter 4.3


2. Electrical Connection

Refer to Technical Manual, chapter 4.4

Load cell connection:





4 -wire load cell connection



6- wire load cell connection

3. Programming and calibration

Refer to Technical Manual, chapter 6.1.

Display	Operation
[123.456 kg]	Press  key until [PASSWORD :] prompt appears
[PASSWORD]	Enter your 4 digit password by pressing keys sequentially. (Default is 1111)
[PASSWORD ****]	Press  key.
[1-INTERFACE]	You entered to the programming main menu and the first main block [1-INTERFACE] prompt appears.

Change the parameter blocks by pressing  and  keys. After reaching the desired block press  key.

3.1 Scale definition

Select parameter [523] (Max / d) and press  key.

[CAP] Define the scale capacity by pressing the numerical keys and confirm with  key.







[d] Select the scale resolution by pressing the  key and confirm with  key

3.2 Calibration

3.2.1 Calibration with test weights

Refer to Technical Manual, chapter 6.5



- Press 2 x  key until parameter-block [6-- Calb / Adjust] appears. Select parameter 611.
- Press  key to start the calibration, the message „Unload the Pan“ appears
- Unload the scale and confirm with  key
- Place the suggested weight on the scale or change it by the numerical keys
- After the successful calibration, the next parameter appears on the display
- Press  or  until the message [SAVE] appears to leave the menu. Confirm with  key

The calibration with test weights has been successfully completed- the scale is now ready to use!

3.2.2 Electronic calibration (eCal)

Note: Define the scale capacity and resolution before starting the eCal (Refer to chapter 3.1)!









Fig.: Final Data summary
(attached to every load cell)

Enter the parameter [613] and confirm with  key

[Total LC Capacity] Enter total load cell capacity via numerical keys.
Example: If the scale has 4 load cells with 1000kg =>Enter: 4000

[Average LC OUT] Enter load cell output in mV/V via numerical keys. The rated output is defined on Final Data Summary, which is attached to every load cell

Example for a scale with 4 load cells:
WZ1 = 2,0010; WZ2 = 1,9998; WZ3 = 1,9986; WZ4 = 2,0002 =>
(2,0010 + 1,9998 + 1,9986 + 2,0002) / 4 => Enter: 1,9999 (average value of all load cell)

[Zero Adjustment] Confirm with  key if the scale is empty to do the zero calibration
After the successful calibration, the next parameter appears on the display
Press  or  until the message [SAVE] appears to leave the menu.
Confirm with  key

The electronic calibration eCal has been successfully completed- the scale is now ready to use!