
1.2-Axis High Speed Programmable Motion Controller

Features

- Max. 4Mpps high-speed operation
- 4 operation modes: Jog, Continuous, Index, Program mode
- 12 control command and 64 steps of operations
- Parallel I/O terminal built in which is connectable on PLC
- Operation program by exclusive switch, making and editing parameter
- Easy to operation of X, Y stage with joy stick
- RS232C port for all types
- Teaching and monitoring function by using teaching unit (PMC-2TU-232)



Software (atMotion)

atMotion is the windows software designed to operate motion control for motion device.

- Compatible with Microsoft Windows 98, NT, XP (32-bit, 64-bit), Vista (32-bit, 64-bit),
 - 7 (32-bit, 64-bit), 8 (32-bit, 64-bit) and 10 (32-bit, 64-bit)
- Supports 1200, 2400, 4800, 9600, 19200, 38400, 57600, 115200 bps communication speeds
- Available to use on all OS supported COM ports (COM1 to COM256)
- Multilingual support (korean, english)
- Provides the calculator for convenience (calculates PPS, center of interpolation, end coordinates)

F

User Manuals


- Please refer to user manual for detailed instructions and specifications.
- Visit our web site (www.autonics.com) to download user manual and software [atMotion].
- User manual describes installing software, setting parameter and program, operation mode, and multi- axis operation, etc. to operate motion controller.

Ordering Information

РМС	_	2ŀ	IS -	- US	SB		
					Communication type	232	RS232C
						USB	USB / RS232C
			Axis/T	уре		1HS	1-Axis high speed stand-alone
						2HS	2-Axis high speed stand-alone
Iten	n					DMO	
L						PMC	Programmable Motion Controller

Specifications

Model		PMC-1HS-232	PMC-1HS-USB	PMC-2HS-232	PMC-2HS-USB		
Control axis		1-Axis		2-Axis (each axis can	2-Axis (each axis can be independently programmed)		
Motor for control		Pulse string input stepper n	notor or servo motor				
Power su	upply	24VDC== ±10%					
Power co	onsumption	Max. 6W					
Operatio	n mode	Jog / Continuous / Index / F	Program mode				
Positionii	ng type	Absolute position / Increme	ntal position				
Index ste	p numbers	64 steps per each axis					
Positionii	ng range	-8,388,608 to 8,388,607 (available pulse scaling function)					
Drive speed numbers		4					
Drive spe	eed	1 pps to 4 Mpps (1 to 8,000 × Magnification 1 to 500)					
Pulse ou	tput method	2 Pulse output (line driver output)					
Home search mode		High speed near home search (step1) \rightarrow Low speed home search (step2) \rightarrow Low speed encoder Z-phase search (step3) \rightarrow High speed offset movement (step4) Configuring the detection method and Enable/Disable in each step.					
	Memory	EEPROM					
D	Step	64 steps					
Program function	Control	ABS, INC, HOM, IJP, OUT,	OTP, JMP, REP, RPE,	TP, JMP, REP, RPE, END, TIM, NOP (12)			
TUTICUOT	Start	Power ON program auto-start function					
	Home search	Power ON home search auto-start function					





PMC-2TU-232

1.2-Axis High Speed Programmable Motion Controller

Specifications

	•					Photoelectric		
Мо	del	PMC-1HS-232	PMC-1HS-USB	PMC-2HS-232	PMC-2HS-USB	Sensors		
Common output		1 point		2 point		(B) Fiber		
Control interface		Parallel I/F	Parallel I/F					
Env	riron Ambient temperature	0 to 45°C	0 to 45°C					
-me	nt Ambient humidity	35 to 85%RH	35 to 85%RH					
	Common	User manual & CD				(C) Door/Area Sensors		
1 F	Power connector	CN1: MC1,5/2-ST-3.5 (PH	HOENIX): 1					
	RS232C connector	CN2: RS-232C communication cable (1.5m): 1						
ory	P I/F connector	CN3: 20P MIL standard, 2.54mm connector: 1						
ccesso	X axis input/output connector	CN4: 16P MIL standard, 2.54mm connector: 1 (2HS: 2)				(E) Pressure		
A	Y axis input/output connector	—		CN5: 16P MIL standard, 2	2.54mm connector 1	Sensors		
	USB connector	 	USB communication cable (1m): 1	<u> </u>	USB communication cable (1m): 1	(F) Rotary Encoders		
Weight ^{≋1}		Approx. 386g (approx. 96.8g)	Approx. 421.6g (approx. 96.9g)	Approx. 393.6g (approx. 100.2g)	Approx. 432.2g (approx. 100.4g)	(G) Connectors/ Connector Cables/ Sensor Distributio		
				Sensor Distribution				

×1: The weight includes packaging. The weight in parenthesis is for unit only.

*Environment resistance is rated at no freezing of condensation.

Standard Operation Method

There are four methods to operate the motion controller.


- Operation by PC
- Connect a PC and the controller with communication cable and run dedicated program (PMC).
- Operation by Parallel I/F
- Connect a sequence controller or switch to Parallel I/F.
- Operation by teaching unit (PMC-2TU-232) Connect a teaching unit cable and install JOG output, HOME search and program by an operation button.
- Operation by serial communication (dedicated communication protocol) Using serial communication protocol, operate according to program writing by user.

Command type Code Description ABS Move absolute position

Program Commands

	1,000	
Drive commands	INC	Move incremental position
	HOM	Home search
	IJP	Jump input condition
I/O commands	OUT	ON/OFF of output port
	OTP	ON pulse from output port
	JMP	Jump
Program control commands	REP	Start repetition
Program control commands	RPE	End repetition
	END	End program
Othere	TIM	Timer
Others	NOP	No operation
	· · · ·	· · ·

Unit Descriptions



Connector No.	Description
CN1	Power connector
CN2	RS232C connector (Connect to PMC-2TU-232)
CN3	Parallel I/F connector
CN4	X-Axis I/O connector
CN5	Y-Axis I/O connector
CN6	USB connector
	when do not have I/O comparter (CNIE) of V avia

%PMC-1HS type does not have I/O connector (CN5) of Y axis.

(A)

Boxes/Sockets

Temperature Controllers

(I) SSRs / Power Controllers

(J) Counters

(K) Timers

(L) Panel Meters

(M) Tacho / Speed / Puls Meters

(N) Display Units

(O) Sensor Controllers

(P) Switching Mode Powe Supplies

(Q) Star epper Mc & Drivers & Controller

(R) Graphic/ Logic Panels

(S) Field Network Devices

(T) Software


Power Connector (CN1)

Pin No.	Signal name	
1	24VDC	
2	GND (0V)	

RS232C Serial I/F Connector (CN2)

Pin No.	Signal name	Input/Output	Description		
1	TXD	Output	Receiving data		
2	RXD	Input	Transmitting data		
3	GND	—	Ground		
4	—	—	No-connection		
5	—	—	No-connection		
6	—	—	No-connection		

%The internal connection diagram of RS232C communication cable is shown as below.



Parallel I/F Connector (CN3)


The Parallel I/F connector which is connected with a sequencer or mechanical contacts operates motion controller same as PC program. When input signal is ON, the input signal terminal and GEX terminal are connected by mechanical contacts or open collector output etc. and open collector output transistor is ON when the output signal is ON.


Pin No.	Signal name	Input/Output	Description
1	RESET	Input	Reset
2	HOME	Input	Home search start
3	STROBE	Input	Drive start
4	X/JOG Y+	Input	X-axis designate/JOG 2 mode Y+
5	Y/JOG Y-	Input	Y-axis designate/JOG 2 mode Y-
6	STEPSL0/RUN+/JOG X+	Input	Step designate 0/Run+/JOG 2 mode X+
7	STEPSL1/RUN-/JOG X-	Input	Step designate 1/Run-/JOG 2 mode X-
8	STEPSL2/SPD0	Input	Step designate 2/Drive speed designate 0
9	STEPSL3/SPD1	Input	Step designate 3/Drive speed designate 1
10	STEPSL4/JOG	Input	Step designate 4/JOG designate
11	STEPSL5/STOP	Input	Step designate 5/Drive stop
12	MODE0	Input	Operation mode designate 0
13	MODE1	Input	Operation mode designate 1
14	X DRIVE/END	Output	X-axis drive/Drive end pulse
15	Y DRIVE/END	Output	Y-axis drive/Drive end pulse
16	X ERROR	Output	X-axis error
17	YERROR	Output	Y-axis error
18	GEX	0V	Ground
19	GEX	0V	Ground
20	VEX	+24V	Power supply for sensor (24VDC, max. 100mA)

<CN3 Pin No.>

20 ■ 19	
18 ■ 17	
16∎∎15	
14∎∎13	
12∎∎11	
10 ■ 9	
8∎∎7	
6∎∎5	
4∎∎3	
2■■1	-

Input/Output Connections (CN3)





< CN3 control output connections >

X, Y-Axis Input/Output Connector (CN4, CN5)

CN4 and CN5 are I/O signals for X-Axis and Y-Axis respectively. The pin arrangement of CN4 and CN5 are equal. PMC-1HS does not have CN5. 'n' in the table means X for CN4 and Y for CN5.

Pin No.	Signal name	Input/Output	Description
1	nP+P	Output	Drive pulse in the CW + direction
2	nP+N	Output	Drive pulse in the CW + direction
3	nP-P	Output	Drive pulse in the CCW - direction
4	nP-N	Output	Drive pulse in the CCW - direction
5	n OUT0	Output	General output 0/DCC
6	n INPOS	Input	Finish the servo inposition
7	n ALARM	Input	Servo alarm
8	GEX	0V	Ground
9	n STOP2	Input	Encoder Z-phase
10	n STOP1	Input	Home
11	n STOP0	Input	Near Home
12	n LMT+	Input	+ direction limit
13	n LMT-	Input	- direction limit
14	EMG	Input	Emergency stop
15	GEX	0V	Ground
16	VEX	+24V	Power supply for sensor (24VDC, Max. 100mA)

Drive pulse output of motion controller which is input to motor driver is line driver output.

Motor driver

(≰ば)

<CN4, CN5 Pin No.>





(M) Tacho / Speed / Pulse Meters

(A) Photoelectric Sensors

(B) Fiber Optic Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encoders

(G) Connectors/ Connector Cables/ Sensor Distribution Boxes/Sockets

(H) Temperature Controllers

(I) SSRs / Power Controllers

(J) Counters

(K) Timers

(L) Panel Meters

(N) Display Units

(P) Switching Mode Power Supplies

(O) Sensor Controllers

(Q) Stepper Moto & Drivers & Controllers

(R) Graphic/ Logic Panels

(S) Field Network Devices

(T) Software

< Example of motor driver connection >

XCN4, 5 input/output is same as CN3 input/output connections.

CN4, CN5


2

nP-P 3


nP+P

nP+N

nP-N




Connections




< Basic configuration of the motion controller (configuration only for X-axis) >

Dimensions




(unit: mm)

Teaching unit PMC-2TU-232 (sold separately)



Teaching Unit PMC-2TU-232 (sold separately)


Teaching unit (PMC-2TU-232) is a device to arrange the operation mode, parameter and operation program without PC and it is also able to install start the operation program, HOME search and JOG operation. Connect to RS232C connector (CN2) using a cable (1.5m)



Teaching unit consists of data edit mode and drive operation mode. The register number is displayed on REG of data edit mode and dp (drive operation) is displayed in drive operation mode and it will be a drive operation status when applying power. Use DP key to convert the status of data edit mode and drive operation mode.

Mode	Operation	REG display
Data edit	 Record operation mode parameter and operation program Installation of index drive 	Register number
Drive handling	Displaying the current position JOG operation HOME search Installation of program	dP (drive operation)

The front panel of the teaching unit shown as below;



1. Reset: Reset the controller and teaching unit.

- 2. X/Y display: Display the current axis.
- 3. Register number display/dp: Display the current register number when editing data and dp when operating drive.

4. Data display: Display the data of each register when data editing and the current position of the axis when operating drive. 5. Input key

- X/Y: Convert the axis and the sign of input value and it is used to change mode data when inputting mode.
- REG: Input the register number to display and it is returned to previous step pressing a key during data input.
- ↑↓: Increase or decrease the current register number.
- EXC: Install the current command, but, ABS, INC, OUT, OTP, HOM1 to 4 are only valid.
- DP: Convert the status of driver operation and data edit.
- WRT: Enter a value when editing data.
- 6. Display the key for drive operation:

Display the key function on a left and upside of the key as a yellow letter and the upper part operates X axis and the lower part operates Y axis.

hotoelectric	
Sensors	

(A)

(B) Fiber Optic Sensors (C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encoders

(G) Connectors/ Connector Cables/ Sensor Distribution Boxes/Sockets

Temperature Controllers

(I) SSRs / Power Controllers

(J) Counters

(K) Timers

(L) Panel Meters

(M) Tacho / Speed / Puls Meters

(N) Display Units

(O) Sensor Controllers

(P) Switching Mode Powe Supplies

(Q) Star epper Mc & Drivers & Controller

(R) Graphic/ Logic Panels

(S) Field Network Devices

(T) Software