

Humidity/Temperature Meter

THWD-2 INSTRUCTION MANUAL



1. SPECIFICATIONS

Display: LCD Dual display and Analog scale display.

Measurement Range:

Humidity: 1% ~ 99% RH

Temperature : -20°C \sim +60°C / -4°F \sim +140°F

Resolution: 0.1% RH, 0.1%, 0.1%

Accuracy (after calibration):

Humidity: \pm 3%RH (at 25°C, 30 ~ 99% RH). \pm 5%RH (at 25°C, 1 ~ 30% RH).

Temperature: ± 0.8℃, ± 1.5°F

Sensor Type:

Humidity: Precision capacitance sensor.

Temperature: Thermistor sensor.

Response Time:

Humidity: 45% RH \rightarrow 95% RH \leq 1 min.

95% RH → 45% RH ≤3 min.

Temperature: 10°C / 2 sec

Sampling Rate: 2 times per second.

Manual Data Memory Capacity: 99 sets.

Auto Power Off: 30 minutes.

Operation Temperature & Humidity:

 0° to 60° , below 95% RH. (no condensation)

Power Supply: Single 9V battery 006P 9V or IEC6F22, or


NEDA1604.

Battery Life: Approx. 200 hours.

Weight / Dimensions : $200g / 225(L) \times 50(W) \times 38(H)mm$

Accessories: Instruction manual, Battery and Soft case.


2. FRONT PANEL DESCRIPTION



- (1) Humidity & Temp. Sensor probe
- (2) Display
- (3) ① Power key: Press ① Power key to turn the meter on or off.
- (4). H Hold key:
 - a). Press H Hold key to freeze or unfreeze the display readings. In H mode, press DEW / WET / %RH key to select desired display readings.
 - b). Press and hold down H Hold key 2 seconds exchange the main display and second display reading. The setting change will be retained during power down.

- (5) DEW / WET / %RH key: Press DEW / WET / %RH key to cycle through the Humidity, DEW point and WET bulb temperature reading on the main display.
- (6) MX/ MN , ℃ / °F key :
- a). MX/MN key: Press MX/MN (MAX/MIN) key to cycle through the Maximum Humidity & Temperature → Maximum Humidity & Elapsed time (min: sec) → Maximum Humidity & Elapsed time (day: hour) → Maximum Temperature & Humidity reading → Maximum Temperature & Elapsed time (min: sec) → Maximum Temperature & Elapsed time (day: hour) → Minimum Temperature & Elapsed time (min: sec) → Minimum Temperature & Elapsed time (day: hour). Minimum Humidity & Temperature reading → Minimum Humidity & Elapsed time (min: sec) → Minimum Humidity & Elapsed time (day: hour). Press MX/MN key 2 seconds to exit MX/MN mode.
- b). °C/ °F key: Press and hold down °C/°F key for 5 seconds to switch between Celsius (°C) and Fahrenheit (°F) units.
- (7) MEM key: Manual data memory control key.
- (8) READ key: Manual memory data reading control key.

Second Display




2

3. MEASURING PROCEDURE

3-1 Humidity Measurement:

- ① Press the " ① " key to power on the meter.
- ② The display will show the humidity reading value (% RH) directly on the main display.
- When testing humidity value of a different environment, please wait a few minutes in order to obtain a stable (%RH) reading.




3-2 Temperature Measurement :

- ① Press the "①" key to power on the meter.
- ② Press and hold down °C/°F key for 5 seconds to switch between Celsius (°C) and Fahrenheit (°F) units.
- When the meter on, it is set to the temperature units that was in use when the meter was last turned off.



3-3 Dew Point Temperature Measurement:

- ① Press the " ① " key to power on the meter.
- ② Press DEW / WET / %RH key to select display dew point temperature reading on the main display.



3-4 Wet Bulb Temperature Measurement :

- ① Press the " ① " key to power on the meter.
- ② Press DEW / WET / %RH key to select display wet bulb temperature reading on the main display.



3-5 Maximum and Minimum Recorder Measurement:

① Press "MX/MN" key to enter the recorder mode and start elapsed timer. The auto power off function must be cancelled before this operation. ② MX/MN key : Press MX/MN (MAX/MIN) key to cycle through the Maximum Humidity & Temperature →



Maximum Humidity & Elapsed time (min : sec) →



Maximum Humidity & Elapsed time (day : hour) →



6

Maximum Temperature & Humidity reading →



Maximum Temperature & Elapsed time (min : sec) →



Maximum Temperature & Elapsed time (day : hour) →



Minimum Humidity & Temperature reading →



Minimum Humidity & Elapsed time (min : sec) →



Minimum Humidity & Elapsed time (day : hour) →



Minimum Temperature & Humidity reading →



Minimum Temperature & Elapsed time (min : sec) →



Minimum Temperature & Elapsed time (day: hour).



Press MX/MN key 2 seconds to exit MX/MN mode.


8

- ③ Under this mode, you can also get the Dew point or Wet Bulb Temperature by pressing the DEW/WET/%RH key.
- Press "MX/MN" key and hold down for 2 seconds to exit MX/MN mode.

3-6 Manual Data Memory and Read Mode:


A. Clear the manual memorized data

- ① Press " ① " key to turn off the meter.
- ② Press and hold down "MEM" key, then press " ① " key to turn on the meter. When LCD shows "CLr" which means the manual memorized data is erased.




B. Manual data memory

- ① Press "MEM" key each time, one set of reading to will be stored to the memory. At this moment, LCD will show the "M" mark and the memory address number. Total memory size is 99 sets.
- @ When memory is full, LCD will show "Full" mark.



C. Manual memory data READ

- ① Press "READ" key to enter READ mode, the LCD will show "R" mark and the memory address number.
- ② Press " READ" key to select the desired memory address number data for display.
- ③ Press DEW / WET / %RH key to display or not display DEW point or DEW point or WET bulb temperature reading on the main display.
- Tress READ key and hold down for 2 seconds to exit READ mode.



3-7 Setting Auto Power Off Mode:


The meter will be Auto power off if there is no key pressed in 30 minutes. Auto power off function is on each time you turn on the meter and is automatically disabled when in MX/MN mode.

Select different time frame of auto power off function via the following selection :

001: To disable auto power off function 002: In 1 minutes to be auto power off. 003: In 3 minutes to be auto power off. 004: In 5 minutes to be auto power off. 005: In 10 minutes to be auto power off.

006: In 15 minutes to be auto power off. 007: In 30 minutes to be auto power off. 008: In 59 minutes to be auto power off.

- ① Press ① key to turn off the meter.
- ② Press and hold down HOLD key then press ① key to turn on the meter. Wait until main display shows 001. (or any other time frame you wish.)
- Tress HOLD key to display the desired auto power off time.
- Press MAX/MIN key to select.



4. MAINTENANCE

4-1 Cleaning:

Periodically wipe the case with a damp cloth and mild detergent.

Do not use abrasives or solvents. Clean and dry as required.

4-2 Battery Replacement:

LCD display will show " BT " symbol when the battery power is not sufficient for accurate testing. Replace with new batteries of same value.

WARRANTY

Congratulations! Your new instrument has been quality crafted according to quality standards and contains quality components and workmanship. It has been inspected for proper operation of all of its functions and tested by qualified factory technicians according to the long-established standards of our company.

Your instrument has a limited warranty against defective materials and/or workmanship for <indicate length of the warranty> from the date of purchase provided that, in the opinion of the factory, the instrument has not been tampered with or taken apart.

Should your instrument fail due to defective materials, and/or workmanship during this <indicate length of the warranty> period, a no charge repair or replacement will be made to the original purchaser. Please have your dated bill of sale, which must identify the instrument model number and serial number and call the number listed below:

Repair Department ATP – Amprobe, TiF, Promax Miramar, FL Phone: 954-499-5400

800-327-5060 Fax: 954-499-5454

Website: www.amprobe.com

Please obtain an RMA number before returning product for repair.

Outside the U.S.A. the local representative will assist you. Above limited warranty covers repair and replacement of instrument only and no other obligation is stated or implied.



Miramar, FL Phone: 954-499-5400 Fax: 954-499-5454 www.amprobe.com

Aug-2002