

September 2006 Revised edition 10 Printed in Japan 3244A980-10 06-09H

Introduction

Thank you for purchasing the HIOKI "Model 3244 CARD HITESTER". To obtain maximum performance from the instrument, please read this manual first, and keep it handy for future reference

Accuracy

Accuracy is guaranteed for 1 year at 23°C±5°C, 80%RH or less, and no

$\begin{array}{c c c c c c c c c c c c c c c c c c c $	Function	Range	Accuracy *5	Remarks	Over load protection
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $		4.200 V 42.00 V 420.0 V	±0.7% rdg.±4 dgt. ±1.3% rdg.±4 dgt. ±1.3% rdg.±4 dgt.	11 MΩ approx. 10 MΩ approx. 10 MΩ approx. 10 MΩ approx.	500 V DC/ ACrms (sin)
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		42.00 V 420.0 V	±2.3% rdg.±8 dgt. ±2.3% rdg.±8 dgt.	 *1 11 MΩ approx. 10 MΩ approx. 10 MΩ approx. 	or 3 x 10 ⁶ V • Hz
	Ω	4.200 kΩ 42.00 kΩ 420.0 kΩ 4.200 MΩ	±2.0% rdg.±4 dgt. ±2.0% rdg.±4 dgt. ±2.0% rdg.±4 dgt. ±5.0% rdg.±4 dgt.	0.7 V (typ.) 0.5 V (typ.) 0.5 V (typ.) 0.5 V (typ.) 0.5 V (typ.)	250 V DC/ ACrms (sin)

ontinuity 420.0 Ω $\pm 2.0\%$ rdg. ± 6 dgt. $4 \times 4 \times 50$ $\Omega \pm 30$ Ω *1: Input impedance *2: Frequency range *3: Open terminal voltage

*4: Threshold level *5: rdg. Displayed value, dgt. Resolution

Safety Symbols

Maximum input voltage

Standards accuracy Safety

EMC

(for 1 minute)

Accessories

Jaiet	y Synn	0015		
Â	 The <u>A</u> symbol printed on the instrument indicates that the use should refer to a corresponding topic in the manual (marked with the <u>A</u> symbol) before using the relevant function. In the manual, the <u>A</u> symbol indicates particularly important information that the user should read before using the instrument. 			
	Indicates	a double	e-insulated device.	
			ect Current).	
\sim Indicates AC (Alter				
			is manual indicate the relative importance of	
cautions a			is manual indicate the relative importance of	
Indicates		hazard th	that incorrect operation presents an extreme at could result in serious injury or death to the	
WARNING hazard i user.		hazard thuser.	s that incorrect operation presents a significant that could result in serious injury or death to the	
CAUTION Indica		Indicates injury to	ates that incorrect operation presents a possibility of to the user or damage to the instrument.	
			advisory items related to performance or peration of the instrument.	
Specif	ficatio	n		
Measurement method		d	Double integration	
Display			3-1/2 digits, LCD, 4199 count max.	
Battery low display			B	
Range switching			Auto-range	
Sampling rate			2.5 times/second	
Operating temperature and			0 to 40°C (32 to 104 °F), 80%RH max	
humidity Storage temperature and			(no condensation) -20 to 60°C (-4 to 140 °F), 70%RH max	
humidity range		and	-20 to 60 C (-4 to 140 F), 70%RH max (no condensation)	
Temperature characteristics		eristics	Measurement accuracy x 0.1 /°C	
(50/60 Hz)			NMRR:40 dB or more [V] (50 or 60 Hz [~V])	
Noise rejection ratio			CMRR:100 dB or more [V],60 dB or more [~V]	
Power supply			Battery CR2032 (3 VDC) x 1	
Continuous operating time		time	Approx. 150 hours [V]	
Rated power			4.0 mW [===V], 0.15 mW [Auto-power Save] (Maximum rated power: 15 mVA continuity test at short-circuit)	
Dielectric strength			3.7 kVrms sin (for one minute) between input and case	
Dimensions and mass		s	Approx. 55W x 109H x 9.5D mm, Approx. 60 g (Approx. 2.17"W x 4.28"H x 0.37"D, Approx. 2.1 oz).	
NA 1 1 1 1			500 \/DO/A Omer (siz) == 0 + 40 ⁶ \/ + 11= (

500 VDC/ACrms (sin) or 3 x 10⁶ V • Hz [----V,~V]

500V

Instruction Manual, carrying case EN 61010-1:2001, EN61010-031:2002

anticipated transient overvoltage 4 kV

Pollution Degree 2, Measurement Category

EN 61326:1997+A1:1998+A2:2001+A3:2003

This instrument is designed to comply with IEC 61010 Safety Standards, and has been thoroughly tested for safety prior to shipment. However, mishandling during use could result in injury or death, as well as damage to the instrument. Be certain that you understand the instructions and precautions in the manual before use. We disclaim any responsibility for accidents or injuries not resulting directly from instrument/ defects.

Measurement categories (Overvoltage categories) This instrument complies with CAT II (500V) safety requirements. To ensure safe operation of measurement instruments, IEC 61010 establishes safety standards for various electrical environments, categorized as CAT I to CAT IV, and called measurement categories. These are defined as follows.

- CAT I : Secondary electrical circuits connected to an AC electrical outlet through a transformer or similar device.
- CAT II : Primary electrical circuits in equipment connected to an AC electrical outlet by a power cord (portable tools, household appliances, etc.)
- CAT III: Primary electrical circuits of heavy equipment (fixed installations) connected directly to the distribution panel, and feeders from the distribution panel to outlets.
- CAT IV: The circuit from the service drop to the service entrance, and to the power meter and primary overcurrent protection device (distribution panel).

Distribution Panel

Internal Wirine

CAT

Higher-numbered categories	
correspond to electrical	Service Entrance
environments with greater	Service Drop
momentary energy. So a	7 23
measurement device designed	CAT IV / Power Meter
for CAT III environments can	Power Meter

endure greater momentary energy than a device designed for CAT II.

Using a measurement instrument in an environment designated with a higher-numbered category than that for which the instrument is rated could result in a severe accident, and must be carefully avoided. Never use a CAT I measuring instrument in CAT II, III, or IV environments. The measurement categories comply with the Overvoltage Categories of the IEC60664 Standards.

Inspection

Safety

When you receive the instrument, inspect it carefully to ensure that no damage occurred during shipping. If damage is evident, or if it fails to operate according to the specifications, contact your dealer or Hioki representative

Precautions

Follow these precautions to ensure safe operation and to obtain the full benefits of the various functions.

Preliminary Checks

· Before using the instrument, make sure that the insulation on the test leads is undamaged and that no bare conductors are improperly exposed. Using the instrument in such conditions could cause an electric shock, so contact your dealer or Hioki representative for repair.

M WARNING

Do not allow the instrument to get wet, and do not take measurements with wet hands. This may cause an electric shock.

Do not use the instrument where it may be exposed to corrosive or combustible gases. The instrument may be damaged or cause an explosion.

- This instrument should be installed and operated indoors only, between 0 and 40°C and 35 to 80% RH. However, it can be safely operated down to -10°C
- Do not store or use the instrument where it could be exposed to direct sunlight, high temperature or humidity, or condensation. Under such conditions, the instrument may be damaged and insulation may deteriorate so that it no longer meets specifications.
- This instrument is not designed to be entirely water- or dust-proof. Do not use it in an especially dusty environment, nor where it might be
- splashed with liquid. This may cause damage Do not use the instrument near a source of strong electromagnetic
- radiation, or near a highly electrically charged object. These may cause a malfunction To avoid damage to the instrument, protect it from physical shock when
- transporting and handling. Be especially careful to avoid physical shock from dropping.

Functions and Display

- **Auto Power Save Function** . This function automatically switches to the power save state when 30 minutes have elapsed since the last operation.
- The auto power save function is activated automatically when the power is turned on
- To restore from the auto power save state, turn the function switch to the OFF position once.

To Disable Auto Power Save

1. Move the function switch from the OFF position to the $\overline{s_{+}}$ (continuity check) position before all display segments appear.

- 2. While all display segments appear (about one second), move the function switch from \mathfrak{F} to \mathfrak{O} . APS \rightarrow OFF is displayed, and the Auto Power Save function is disabled
- Turning the function switch momentarily OFF and then back on reactivates Auto Power Save.


Auto-range Function

When measuring a DC voltage [---V], AC voltage [\sim V], or resistance [Ω], the measurement range is automatically set to the most appropriate range. Manual range setting is not possible.

Overflow Display

When the input exceeds the measurement range, "OF" is displayed.

Names and Functions of Parts




Measurement Method

- Observe the following precautions to avoid electric shock. • Always verify the appropriate setting of the function selector
- before connecting the test leads.
- Disconnect the test leads from the measurement object before switching the function selector.
- The maximum input voltage is 500V DC/ACrms or 3 x 10⁶ V/Hz. Attempting to measure voltage in excess of the maximum input could destroy the instrument and result in personal injury or death.
- To avoid electrical shock, be careful to avoid shorting live lines with the test leads.
- For safety, test lead connections must always be made at the secondary side of a circuit breaker.
- The maximum rated voltage between input terminals and ground is 500 V DC/ACrms. Attempting to measure voltages exceeding 500 V with respect to ground could damage the instrument and result in personal injury.
- Never apply voltage to the test leads when the Resistance measurement. Continuity test functions are selected. Doing so may damage the instrument and result in personal injury. To avoid electrical accidents, remove power from the circuit before measuring.


Noltage Measurements

3. Read the display.



A Continuity Test

1. Set the function switch to ই . The " 🛼 " indication appears. 2. Connect the test leads to the object to be measured. 3. Conductivity is good when



the buzzer sounds. Maintenance

Replacing Battery

4

 Λ

(H)

Outlet

Ĩ

∬leads

lead

- · Adjustments and repairs should be made only by technically qualified personnel. If the protective functions of the instrument are damaged, either remove it from service or mark it clearly so that others do not use it inadvertently. They may cause discoloration or damage.
- **NOTE:** To avoid corrosion from battery leakage, remove the battery from the instrument if it is to be stored for a long time.
- · To clean the instrument, wipe it gently with a soft cloth moistened with water or mild detergent. Never use solvents such as benzene, alcohol, acetone, ether, ketones, thinners or gasoline, as they can deform and discolor the case
- · If the instrument seems to be malfunctioning, confirm that the battery is not discharged, and that the test leads is not open circuited before contacting your dealer or Hioki representative. Pack the instrument carefully so that it will not be damaged during shipment, and include a detailed written description of the problem. Hioki cannot be responsible for damage that occurs during shipment.

- To avoid electric shock when replacing the battery, first disconnect the test leads from the object to be measured. After replacing the battery, replace the cover and screws before using the instrument.
- Be sure to insert them with the correct polarity. Otherwise, poor performance or damage from battery leakage could result. Replace battery only with the specified type.
- To avoid the possibility of explosion, do not short circuit, disassemble or incinerate battery.
- Keep battery away from children to prevent accidental swallowing. Handle and dispose of battery in accordance with local regulations.
- 1. Remove the test leads from the test item, and power the instrument off. 2. Remove the instrument from the case, and remove the screws on the rear panel.
- Remove the used battery.
- 4. Being careful about the polarity, insert the new battery of the specified type. 5. Replace the rear panel and fasten the screws.

NOTE: When the battery is exhausted, the "E " indication appears in the display Battery is not included in the basic price of this instrument. (For testing purposes, battery is inserted into the instrument, but if it should be exhausted it is not replaced free of charge.)



HIOKI E.E. CORPORATION	DECLARATION OF CONFORMITY		
INSPECTION CERTIFICATE	Manufacturer's Name: HIOKI E.E. CORPORATION		
HIOKI E.E. CORPORATION hereby certifies that the under-mentioned product(s) has been	Manufacturer's Address: 81 Koizumi, Ueda, Nagano 386-1192, Japan		
tested and inspected in accordance with	Product Name: CARD HITESTER		
applicable HIOKI calibration procedures, and	Model Number: 3244		
proven to meet or exceed published			
measurement specifications. We also certify that the measurement standards and	The above mentioned product conforms to the following		
	product specifications:		
instruments used in the calibration procedure are traceable to the national standards	Safety: EN61010-1: 2001 EN61010-031:2002		
organization. Model: <u>3244</u>	EMC: EN61326:1997+A1:1998+A2:2001 +A3:2003 Class B equipment Portable test, measuring and monitoring equipment used in		
S/N:	low-voltage distribution systems		
S/IN:	Supplementary Information:		
	The product herewith complies with the requirements of the Low Voltage Directive 73/23/EEC and the EMC Directive 89/336/EEC.		
INSPECTOR	HIOKI E.E. CORPORATION		
T. Kito	15 September 2006 <u>T. Upshith</u> Tatsuyoshi Yoshiike		
T. Kito	President 3244A999-05		

