## **4L80E-HTRK** Hi-Temp Ring & Endplay Upgrade

**Corrects/Prevents/Reduces** 

No Lockup and 4th hot—Codes 68—39—85 Hard shifts and no 4th—Direct Clutch Slippage Prevents Metal Particles by Separating Shafts Hot Idle Forward Clutch Slip, Aborts LU & 4th. Reverse Delay—Bindup in reverse when hot.

**Shop Owner & Technician :** Most often no lockup and no 4th and codes 68, 39, 85 are caused by rings that have shrunk, or hardened, and not usually caused by bad friction or converter.

**A&B:** This prevents Lube Oil cross-leak from applying Coast clutch by accident, which causes coast & 4th clutch burnup.

**C. Stator Bushing:** Always replace if there is any sign of wear.

**D&E:** Self expanding Hi-temp rings prevents hot forward clutch slip which causes hard shifts, no lockup and 4th. Prevents/Cures hot bindup in reverse.







© TransGo 2011

Hi-temp rings resist shrink and hardening. This will correct reverse delay hot and slips in 3rd hot. No more code 85 and shift aborts. You'll love it.

> **A.** Open rings till they prox fit this picture. Install with Vaseline

or Trans Jel

**B.** Install 2 GOLD washers under original thrust washer.

This keeps shafts from rubbing and making metal particles. Also centers drum on rings. If the drum does not rotate freely remove one gold washer.



LISTEN UP: NEVER make the front end play tighter than rear end play.

29 Aug 2011

Center

**Support** 

© TransGo 2011