
SK® 48RE

2003-2008 Diesel & V10

Increases Torque Capacity Lockup & Shift Firmness Reduces Drainback Perfect for Diesel Trucks


> 48-RE Application 8th vin digit = C 48RE Trans 8th vin digit = 6 47RE Trans





This kit only fits VB's WITH a balance hole here in the main plate. If your original plate does NOT have this balance hole, USE SK®TFOD-Diesel kit.


This product IS NOT compatible with any 46-47RE Swapped / Hybrid valve body or any previously modified 48RE valve body's from any other sources.




2. Install new PLAIN lower 1-2 Accum spring as shown. Some models use upper spring reuse it.

Good News!

New parts were added in an effort to help reduce governor transducer failures common with this transmission.




When Installing multi clutch converter SKIP step one.






Wear in the Boost Valve bore area causes repeated rear band failure & lazy or erratic pressure rise. FIX IT NOW!


Order **P/N TF-Boost** Our redesigned boost valve fixes the issue without any special tools required. An easy "drop-in" solution to a high risk failure.





- **3.** For models WITHOUT a TV cable (Uses a Throttle Motor) AND is equipped with a engine power chip or programmer: Install the gold spacer into the part throttle body. Then install the part throttle (PT) valve. This will reduce the possibility of a **light throttle** 2-3-2-3-2-3 shuttle shift condition. This condition has not been found on TV cable equipped models.
- 4. Use a pick and a small hammer to taper the top of this hole to help start the pin. Install pin furnished into this hole, using needle nose pliers and small hammer. File flush if needed. PT body must sit flush against VB.

1. Insert spring and ball into VB pocket. Use the Mumbly Peg to hold the ball in place. Insert new Manual Valve and reassemble the rooster comb. Remove peg.




Six Check-balls One Cherrybomb

2. Install **CHERRYBOMB** here. Careful to align stem UP through hole in plate when putting VB together.

Detent Ball sloppy in the pocket? Order **P/N TF-Detent** New "drop-in" design keeps manual valve indexed correctly!


3. Grind one notch on slight angle to about the middle of this land. Reuse original spring.



1. Place .156 drill into hole shown and drill all the way through the accumulator housing. With small punch drive Plug into hole just below flush.

2. With small punch drive tapered PLUG just below flush into the hole.

3. Install New Limit Bushing, 3/16 Ball and



Lower Body

Heads Up!

Make sure these small holes are clean or NO
4th and/or NO TCC will be the result.


DO NOT enlarge these holes!

A .020" paper staple fits even in the smaller of the 3 holes & will clean any debris out.

1. Install new **ORANGE** spring here.



Lower Plate (Small Plate)




2. We need to add a hole to the small **Lower VB Plate.** Use channel casting as drill guide. Place plate on bottom of channel using two VB bolts to line it up as shown, then flip it over.


Use this rectangle passage as guide to drill a 0.106" hole through **lower** plate as shown with the drill bit furnished.




Have a great day!



Valve Body Identification






1. Enlarge holes A & B with .106 drill. ReInstall original check balls.


Governor Sensor
(Transducer)

Blow Air into this end.

Pretesting Governor Sensor

There have been numerous reports of transducers failing shortly after overhaul. Do this simple test to weed out any weak ones. If it passes this test, use it. Using shop air (120-130 psi max.) blow air into the end of the transducer. Use a rubber tip blow gun, make a good seal and listen. IT MUST NOT LEAK.





Tech Tip: Using a triple disc converter in a stock daily driver can lead to rough 3-4 and/or rough TCC complaints from your customers.

Plate.

(Optional)