SK® CD4E-Jr Shift Kit® Series 7D Corrects/Prevents/Reduces


Converter Slip and Code 628

Drum Blow-out due to run-away line pressure. Bushing wear due to accidental Lube cut-off.

Kit corrects / prevents the pressure run-away caused by cross leaks, sticking EPC, or electrical malfunction that blows out forward drum, gaskets or breaks pump shaft. Kit corrects low Converter and lube flow that causes Code 628 and fast bushing wear. Don't let all the papers in the kit fake you out. Kit installs quick and easy. The lengthy info is to prevent hard part re-work.

Ford CD4E Mazda LA4A-EL





SERVO PISTON ASSEMBLY

2-4 Servo [Band Adjustment]

Listen: Be careful. Go buy a Stone Age "C" clamp. It makes servo job really easy.

Step 1 Disassembly: Insert the clamp arm just beyond the steel bracket bolt. Do not put the clamp into an oil circuit. Squeeze cover in with clamp and remove snap ring.

Step 2 Assembly: Squeeze cover in with clamp. Then install the Adjustment Washer and snap ring.

Snap

Ring



Mr. Shift


Cover

Page 1

Adjustment

Washer

2-4 Servo Assembly



RETURN SPRIN ASSEMBLY

Main VB

Step 2 Drill .046 to .055

hole thru partition, left to right, under the "X".

Converter

Line

EPC

Step 1

Remove all parts in the PR Valve bore. Measure land "A" on your PR valve. If **Land** "A" measures approx .472, proceed to **Step 2**. If not, the valve body has been bored for an oversized PR Valve. **STOP!** You will need to change the main body with a unmodified, main body and main plate (if plate was drilled).

Step 4

Clean Line Mod Valve & bore and replace original spring with **NEW Orange** spring and reassemble.



Step 3

Drill two .060 to .094 holes through the floor of this passage just enough to enter into the PR valve bore, STOP! Don't drill out the back side of the VB! De-burr holes & clean out chips.


Do not reassemble PR Valve yet.

The bore at "A" erodes over size. Converter and EPC then mix which causes high line pressure and converter slip with blinking OD light-Code 628. No worries! You're *fixing the problem* with this kit!

Heads Up!

High Gear Starts in Man 1 Installing wrong VB can result in High gear start in M1 that may feel like a bind-up. Solenoid firing order in M1 is different for "F6" & "F3" valve bodies & must match the computer strategy.

VB ID by Casting Number



93-96 Casting # starts with "RF-F3" and has a "Pull-in Control Valve".

97up Casting # starts with "**RF-F6**" and does *NOT* use a "Pull-in Control Valve".

Designs match Computers!

Step 1

Clean TCC Control Valve & bore. Replace original spring, bushing & valve with **NEW small Orange** spring, **NEW TCC Bushing** & **Valve** and reassemble.

Step 2

Clean Converter Reg Valve & bore and replace original spring, with **NEW White** spring and reassemble.


Step 3

Retainer Location Retainer 1-2 Accum O-ring must be outboard of retainer!


Accumulator Valve Body

Main Valve Body

Clean PR bore. Lube & install PR Valve fully into the bore. Install **NEW PR Bore Bushing** with small side hole outboard. Install **NEW Red** spring & **New** assembled **EPC Relief Assv**.



Assemble EPC Relief:



EPC Relief Valve Assembly

Install **ball** & **plain spring** into new relief end plug. Using paper clip, compress spring and install the **cotter** pin. Remove paper clip with pliers. When installed the cotter pin end will be outside of the PR bore.

Step 1


Drill Holes: 1, 1a, 2, 3, & 5 with .063 (1/16") drill furnished, OK if already bigger. Don't skip any steps!

You need to know: On a 10 block road test this trans will not act different than without the kit.

However: A **HOT** trip, without the kit, this trans will probably abort lockup and suffer lost lube flow.

Every change has been carefully evaluated and coordinates with other pressure and flow changes. So, please do it just like these instructions and **DON'T** do any other "TECH"—Thank You!

Series 7D



"Thanks for Listening." Gil

Accumulator Plate

01

Notches

 $\supset \cap \cap$

Channel Casting

Step 3. Drill an extra hole at the end of this passage as shown at the white dot, with .070 to .125 drill. Then enlarge hole #4 with same drill.

Page 4

©TransGo 2016 05 August 2022

READ THIS: CD4E Repair Data

This is a great little trans. You are going to see a lot of them. We are confident that the upgrades in the SK® kit will correct the hydraulic malfunctions including runAway line, accidental cutoff to converter apply and lube, blinking light, converter slip, and Code 628/PO741.

However, there's also problems with hard parts that need your attention.

Some shops have been installing a new solenoid pack and a valve body plate upgrade from Ford. We have no reports that these items fix or prevent the complaints. Spend the money for hard parts instead.


Forward Drum

A common failure is forward drum. The end blows off due to runAway line pressure. The driving complaint is a rough 1-2 shift when HOT. A new valve body may correct it for a while. The permanent FIX, for runAway line is the TransGo SK® CD4E-Jr Kit.

ALSO: The welds in this drum often crack with high miles in normal use. It's a good idea to install a new drum. Don't forget to add the lube ring, new drums come without the lube ring.

Broken end Weld Weld Warning: Install ring here.

Bushings: The drum bushings are usually in bad condition from lack of lube or bad connection at the ground strap. This kit will restore lube flow and cooling, but its up to you to file clean the block and the ground strap. Because the bushings are not blue, from overheat, you may be tempted to reuse them—Don't. Loose bushings allow 2-4 band to push the gear train off-center and the rings will then deform and leak.




Page 1 23 Feb 04

Must be smooth and at least 1/16" wide where the rings actually seal.

Repair Information Continued

Listen Up: To prevent lube cut-off problem careful assembly is required. Notches in Reverse Hub must align with Lube holes at forward splines.



This Picture: Notice the bushing is welded to this hub due to misalignment of the splines.

It went out out in one weekend.

Don't make a sad Story: You'd fill most trans's to the COLD mark knowing it will come up HOT. If you do that with this trans you may see it burn down on WHY? COLD mark, on this trans, is the high one, not the low a hot trip. one. **BECAUSE**: This trans has a temp controlled flap valve that causes fluid level to go up in the side pan and down in sump to prevent foaming when re-As much as 2-1/2 qts can be held in the Side pan. ally HOT.

Cold mark

Correct Fluid Level: After your repair, BEFORE the trans gets hot. run it 20 seconds in PARK and bring fluid level to the COLD/top mark. On road test the level will go DOWN slightly as the trans warms, but even very hot it should never be more than 3/8" below COLD mark.

Pressure Ports:

A= Differential lube B= Front Lube

D= Converter Rear.

C= Converter Mid

Hot Trip Complaint: Rough 1-2, no Lockup, blinking light and/or Code 628/PO741. AFTER the SK® Kit is installed this could be lockup slip or a 10-15% ignition miss. Without SK® kit you won't fix it.

Check 628/PO741Code like this: Gauge port "C". Drive till hot. At 200F Port "C" should be at least 70 psi with light throttle in 4th. Restart to clear code. Drive 65 to 75 mph, in lockup, and watch tach while adding throttle. If rpm comes up without an increase in car speed, the converter is slipping.


"Thanks for Listening, let us hear from you."

TransGo Tech Team

Line Pressure port is fitting next to pump: Remove the fitting. Drill it 11/32" and tap it with 1/8" pipe tap. Now your gauge fits it. Operating line pressures when HOT: Forward gears: Min 53-70 Stall 170-200 Park, Rev, "N": Min 68-90 Max 280-300

Both you and your R&R person must read this.


1994 to 97 4cyl Probes and Mazda 626's have a serious ground strap problem that will eat this trans up in a few days—Unless you prevent it. It may look like a lack of lube, but the cause is the engine is starting through the bushing and the gears instead of through the ground strap. The parts shown are out of trans that came back three times.



Melted bushing



Starter



Engine Ground Strap Pad File the pad and both sides of the ground strap.

The car factory put locktite here which can insulate the strap.

Remove the ground strap that goes from battery to the fender. Clean the paint and the strap and reconnect it.

How to check for solid ground: Attach a volt meter from the negative terminal of battery over to the trans. It must read .09V or less, even while starting the engine.

"Thanks for listening"

CD4E & LA4A-EL Electrical Data

If trans slipped or failed PCM may be commanding LIMP or late/hard shifts in a high pressure mode.

Before startup and fluid fill: Cleanse PCM with this routine: Disconnect the positive battery cable. Touch it against the engine and the body, then let it hang. Turn ignition switch on and hit the brake 4 times. Reconnect battery cable.

No 4th/lockup when hot: Above 60,000 miles consider new plugs and wires.

Limp Mode: Or No power to PCM; Or No signals from PCM.

Has high line pressure: "D" is 3rd "2" is 3rd "1" is 2nd No lockup or 4th.

Shift Sol Complaints: Pressure gauge must be attached: While driving at 40mph line pressure must go up and down with throttle and must come down to 53-68 with lift throttle. If lift throttle is above 53-68, don't fuss with shift sols.

-Check /Fix pressure first-

Gear	SS1	SS2	3-2T/CCS
1st	ON	ON	□ NA
2nd	OFF	ON	□ NA
3rd	OFF	OFF	□ NA
4th	ON	OFF	OFF (unlocked)
4th	ON	OFF	ON (lockup)

*Temp Data: Pin 1&2 70F = 35K to 45K 140F = 8K to 5K 200F = 2.6K to 1.7K



Page 4

Connector in the Trans

Ohms	Function	Pin
*Varies	Temp Send	1
*Varies	Temp Return	2
	TCC Power	3
94/95=13.	TCC Grnd	4
96/97=12-20	TCC Grnd	4
12-22	SS2 Grd	5
	Sol Power	6
12-22	SS1 Grd	7
3.7-5.9	3-2T/CCS grd	8
	EPC Power	9
3.7-5.9	EPC Grd	10

Break out shifts: 12V to 6 Ground: 5&7= 1st 5= 2nd None= 3rd 7= 4th





PUMP

6