SK® N4AEL™ Shift Kit®



OD band adjust:


Fits: MAZDA 929 & RX7: 1988-90

Prevents/Reduces:


1-2 Slide --- Spinup 2-3 --- 3-2 Cutloose Mushy 4th --- Soft lockup --- Soft shifts

Shifts--You'll Just love


1. Pump Cover: For firmer lockup enlarge this hole .051 to .055




If trans is in the vehicle skip 1&2.





3. Band Adjustment Tighten band with short wrench. Loosen just enough to rotate the drum by hand. Then loosen 1/4 turn more and tighten the lock nut.













Repair Information

Overdrive Housing



Modulator

1-1/4" diam just above crimp. Tension 5-12oz to 6 -2oz.




Pin: Diam 3mm [1/8"]. Length: 1-3/16" to 1-1/4" Install flat end of capsule into hole.

Vacuum:

Trapped or restricted vacuum can cause loose shifts, band and clutch failure. Before Road Test: With engine idling pull hose off at the modulator. Engine must speed up or idle rough. If engine does not have instant change with hose off, follow hose/tube and drill out any carbon or restriction with .063 to .076 drill. Make sure modulator hose/tube does not connect to same hose/tube as the power brake.

AIR CHECK & PRESSURE LOCATIONS



© TransGo 1994

1/4" Checkball

Page 4