



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #13810722 - 2019 Skyjack SJ6832 RT Dual Fuel 4x4 Scissor Lift



### Item Details:

- Features: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box, 2018 US EPA Label, CARB Compliant, Kubota 3 Cylinder Dual Fuel Engine
- Meter Reading: 1,193 Miles
- Serial # : 37014715
- Inspection Completed: 8/27/25

### Shipping Details:

- Location British Columbia
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

## Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

| Inspection Ratings Key |                                                                                   |
|------------------------|-----------------------------------------------------------------------------------|
| ★★★★                   | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆                  | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆                  | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆                  | Needs immediate repair/replacement. Requires work if it is to perform as expected |

### Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.


| Item                      | Assessment                                                 | Photo                                                                                |
|---------------------------|------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Control Station Upper #9  |                                                            |                                                                                      |
| Control Console           | No visible damage or missing components                    |   |
| Emergency Shut Off Switch | Operational                                                |  |
| Upper Function Controls   | ★★★★☆                                                      |  |
| Limited Function Check    | The main components are in place and operational as noted. |                                                                                      |
| Control Station Upper #1  |                                                            |  |

|                          |  |                                                                                     |
|--------------------------|--|-------------------------------------------------------------------------------------|
| Control Station Upper #2 |  |    |
| Control Station Upper #3 |  |   |
| Control Station Upper #4 |  |   |
| Control Station Upper #5 |  |  |

## General Appearance

| Item                        | Assessment | Photo                                                                                |
|-----------------------------|------------|--------------------------------------------------------------------------------------|
| Picture, Left Front Corner  |            |    |
| Picture, Left Rear Corner   |            |    |
| Picture, Right Rear Corner  |            |   |
| Picture, Right Front Corner |            |  |
| Serial Number / VIN         | 37014715   |  |
| Hour Meter / Odometer       | 1193 mi    |  |


|                         |                                         |                                                                                      |
|-------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Paint                   |                                         |     |
| Body Panels             | No visible damage or missing components |                                                                                      |
| Steps/Ladders           |                                         |    |
| Basket / Safety Railing | No visible damage or missing components |                                                                                      |
| General Appearance #1   |                                         |   |
| General Appearance #2   |                                         |  |
| General Appearance #3   |                                         |  |
| General Appearance #4   |                                         |  |



|                        |  |                                                                                      |
|------------------------|--|--------------------------------------------------------------------------------------|
| General Appearance #5  |  |     |
| General Appearance #6  |  |    |
| General Appearance #7  |  |    |
| General Appearance #8  |  |   |
| General Appearance #9  |  |  |
| General Appearance #10 |  |  |
| General Appearance #11 |  |  |

|                        |  |                                                                                      |
|------------------------|--|--------------------------------------------------------------------------------------|
| General Appearance #12 |  |     |
| General Appearance #13 |  |    |
| General Appearance #14 |  |    |
| General Appearance #15 |  |   |
| General Appearance #16 |  |  |
| General Appearance #17 |  |  |
| General Appearance #18 |  |  |

| Safety                              |             |                                                                                     |
|-------------------------------------|-------------|-------------------------------------------------------------------------------------|
| Item                                | Assessment  | Photo                                                                               |
| Travel Alarm                        | Missing     |                                                                                     |
| Horn                                | Operational |                                                                                     |
| Current Safety Manual               | No          |                                                                                     |
| Current Operator/Maintenance Manual | No          |                                                                                     |
| ANSI Guidelines                     | Yes         |   |
| Safety #1                           |             |   |
| Safety #2                           |             |  |

| Control Station Ground |                                                            |                                                                                    |
|------------------------|------------------------------------------------------------|------------------------------------------------------------------------------------|
| Item                   | Assessment                                                 | Photo                                                                              |
| Gauges                 | Operational                                                |  |
| Function Controls      | ★★★★☆                                                      |  |
| Engine Oil Pressure    | No oil pressure indicator                                  |                                                                                    |
| Limited Function Check | The main components are in place and operational as noted. |                                                                                    |

| Engine                                  |                                         |                                                                                      |
|-----------------------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Item                                    | Assessment                              | Photo                                                                                |
| Emission Label                          |                                         |    |
| Blow-by (subjective visual observation) | No noticeable vapor or pressure         |                                                                                      |
| Starter                                 | Operational                             |                                                                                      |
| Fuel System                             | Operational                             |    |
| Exhaust System                          | No visible damage or missing components |   |
| Radiator                                | ★★★★☆                                   |  |
| Oil Leaks                               | No dripping leaks                       |                                                                                      |
| Fuel Leaks                              | No dripping leaks                       |                                                                                      |
| Cooling System Leaks                    | No dripping leaks                       |                                                                                      |
| Engine - Left Side                      |                                         |  |
| Limited Function Check                  | The engine started and ran.             |                                                                                      |

|           |  |                                                                                      |
|-----------|--|--------------------------------------------------------------------------------------|
| Engine #1 |  |     |
| Engine #2 |  |    |
| Engine #3 |  |    |
| Engine #4 |  |   |
| Engine #5 |  |  |
| Engine #6 |  |  |


| Electrical Operating System    |                                                           |                                                                                     |
|--------------------------------|-----------------------------------------------------------|-------------------------------------------------------------------------------------|
| Item                           | Assessment                                                | Photo                                                                               |
| Battery Condition              | Functioned during the inspection                          |                                                                                     |
| Cables and Connections         | No visible damage or missing components                   |                                                                                     |
| Limited Function Check         | The electrical system was operational in a limited check. |                                                                                     |
| Electrical Operating System #1 |                                                           |   |
| Electrical Operating System #2 |                                                           |   |
| Electrical Operating System #3 |                                                           |  |

## Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

| Item                   | Assessment                      | Photo                                                                                                                                                                                                                                                                         |
|------------------------|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Front Drive Axle       | ★★★★☆                           |  A close-up photograph of the front drive axle assembly, showing the axle, suspension components, and the red-painted wheel hub. The IronPlanet logo is visible in the bottom right corner. |
| Rear Drive Axle        | ★★★★☆                           |  A photograph of the rear drive axle assembly, showing the axle, suspension, and the red-painted wheel hub. The IronPlanet logo is visible in the bottom right corner.                      |
| Final Drives           | ★★★★☆                           |  A close-up photograph of the final drive assembly, showing the housing and the red-painted wheel hub. The IronPlanet logo is visible in the bottom right corner.                          |
| Limited Function Check | The drivetrain was operational. |                                                                                                                                                                                                                                                                               |
| Drivetrain #1          |                                 |  A close-up photograph of the first drivetrain component, showing the housing and the red-painted wheel hub. The IronPlanet logo is visible in the bottom right corner.                   |
| Drivetrain #2          |                                 |  A close-up photograph of the second drivetrain component, showing the housing and the red-painted wheel hub. The IronPlanet logo is visible in the bottom right corner.                  |
| Drivetrain #3          |                                 |  A close-up photograph of the third drivetrain component, showing the housing and the red-painted wheel hub. The IronPlanet logo is visible in the bottom right corner.                   |

|               |  |                                                                                     |
|---------------|--|-------------------------------------------------------------------------------------|
| Drivetrain #4 |  |    |
| Drivetrain #5 |  |   |
| Drivetrain #6 |  |   |
| Drivetrain #7 |  |  |

| Hydraulics             |                                       |                                                                                      |
|------------------------|---------------------------------------|--------------------------------------------------------------------------------------|
| Item                   | Assessment                            | Photo                                                                                |
| Pumps (Hydraulics)     | ★★★★☆                                 |    |
| Valves                 | ★★★★☆                                 |    |
| Hydraulic Tank         | ★★★★☆                                 |   |
| Lift Cylinders         | ★★★★☆                                 |  |
| Steering Cylinder      | ★★★★☆                                 |  |
| Outrigger Cylinders    | ★★★★☆                                 |  |
| Limited Function Check | The hydraulic system was operational. |                                                                                      |

|               |  |                                                                                      |
|---------------|--|--------------------------------------------------------------------------------------|
| Hydraulics #1 |  |     |
| Hydraulics #2 |  |    |
| Hydraulics #3 |  |    |
| Hydraulics #4 |  |   |
| Hydraulics #5 |  |  |
| Hydraulics #6 |  |  |
| Hydraulics #7 |  |  |


|               |  |                                                                                    |
|---------------|--|------------------------------------------------------------------------------------|
| Hydraulics #8 |  |   |
| Hydraulics #9 |  |  |


## Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item               | Assessment | Photo                                                                                |
|--------------------|------------|--------------------------------------------------------------------------------------|
| Steering Linkage   | ★★★★☆      |    |
| Frame Condition    | ★★★★☆      |    |
| Scissor Linkage    | ★★★★☆      |   |
| Platform Condition | ★★★★☆      |  |
| Platform Extension | ★★★★☆      |  |
| Left Front Tire    | Screws     |  |

|                                       |                                                            |                                                                                      |
|---------------------------------------|------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Left Rear Tire                        | Screws                                                     |     |
| Right Rear Tire                       | Screws                                                     |    |
| Right Front Tire                      | Screws                                                     |    |
| Wheel Condition                       | No visible damage or missing components                    |                                                                                      |
| Wheel Studs                           | ★★★★☆                                                      |                                                                                      |
| Outriggers / Stabilizers              | ★★★★☆                                                      |   |
| Limited Function Check (Scissor-lift) | The main components appear to be in place and operational. |                                                                                      |
| Chassis #1                            |                                                            |  |
| Chassis #2                            |                                                            |  |

|            |  |                                                                                      |
|------------|--|--------------------------------------------------------------------------------------|
| Chassis #3 |  |     |
| Chassis #4 |  |    |
| Chassis #5 |  |    |
| Chassis #6 |  |   |
| Chassis #7 |  |  |
| Chassis #8 |  |  |
| Chassis #9 |  |  |

|             |  |                                                                                      |
|-------------|--|--------------------------------------------------------------------------------------|
| Chassis #10 |  |     |
| Chassis #11 |  |    |
| Chassis #12 |  |    |
| Chassis #13 |  |   |
| Chassis #14 |  |  |
| Chassis #15 |  |  |
| Chassis #16 |  |  |

|             |  |                                                                                    |
|-------------|--|------------------------------------------------------------------------------------|
| Chassis #17 |  |   |
| Chassis #18 |  |  |

**Buy this item and view more at [www.ironplanet.com](https://www.ironplanet.com) or call 800-211-3983**

IronPlanet, Inc. © 2012 All Rights Reserved