



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13445339 - 2024 Skyjack SJ3219 Electric Scissor Lift



Item Details:

- Features: 18 ft 6 in Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Solid Non-Marking Tires, Upper Control Box
- Meter Reading: 82 Miles
- Serial # : A100047839
- Inspection Completed: 5/15/25

Shipping Details:







- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report



Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.




Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

<p>Serial Number / VIN</p>	<p>A100047839</p>	
<p>CE Mark</p>	<p>No CE mark found</p>	
<p>Hour Meter / Odometer</p>	<p>82 mi</p>	
<p>Paint</p>	<p>No visible damage</p>	
<p>Body Panels</p>	<p>No visible damage or missing components</p>	
<p>Steps/Ladders</p>		
<p>Basket / Safety Railing</p>	<p>No visible damage or missing components</p>	
<p>General Appearance #1</p>		






General Appearance #2		 A photograph showing the rear of a red Skyjack scissor lift. The model number "SJ3219 E" is printed in white on the red frame. A yellow and black logo is visible on the side. The lift is parked on a gravel surface.
General Appearance #3		 A photograph of a grey Skyjack scissor lift. The number "101740" is printed in yellow on the side. The "skyjack" logo is visible. The lift is parked on a gravel surface.
General Appearance #4		 A close-up photograph of the operator's control panel and safety features. It shows a red handrail, a control lever, and various warning labels and indicators.
General Appearance #5		 A close-up photograph of the scissor mechanism and the platform of the lift. The platform is red and has a perforated metal surface. The scissor arms are also visible.
General Appearance #6		 A photograph showing the front view of the scissor lift. The red platform and the mast are visible. The lift is parked in an outdoor lot.
General Appearance #7		 Another photograph showing the front view of the scissor lift, similar to the previous one but from a slightly different perspective. The red platform and mast are clearly visible.




Safety		
Item	Assessment	Photo
Travel Alarm	Inoperable	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	
Safety #1		



Control Station Ground		
Item	Assessment	Photo
Function Controls	★ ★ ★ ☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground #1		
Control Station Ground #2		







Control Station Upper



Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.







Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		
Control Station Upper #2		







Electrical Operating System		
Item	Assessment	Photo
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Appears normal - Not operationally checked	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		








Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Drive Motors	★★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		
Hydraulics #2		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Brake System	★★★★☆	
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Scissor Linkage	★★★★☆	
Platform Condition	★★★★☆	
Platform Extension	★★★★☆	
Left Front Tire	Cracks, Chunks missing	

Left Rear Tire	Cracks, Chunks missing	
Right Rear Tire	Cracks, Chunks missing	
Right Front Tire	Cracks, Chunks missing	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Pothole Protection Bars	★★★★☆ Functional	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		

Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		

Chassis #9		
Chassis #10		
Chassis #11		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved