



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14097075 - 2017 JLG 660SJ 4WD Diesel Telescopic Boom Lift



Item Details:

- Features: 65 ft Max Platform Height, 520 lb Max Weight Capacity, Jib, Power to Platform, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 50 hp Diesel Engine, 355/55D625 Foam-Filled Tires
- Meter Reading: 2,858 Hours
- Serial # : 0300236821
- Inspection Completed: 12/2/25

Shipping Details:

- Location Ontario
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0300236821	
Hour Meter / Odometer	2858 hrs	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

Safety		
Item	Assessment	Photo
Travel Alarm	Inoperable	
Horn	Inoperable	
Swing Brake	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	
Safety #1		
Safety #2		

Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Oil Pressure	No oil pressure indicator	
Limited Function Check	The main components are in place and operational as noted.	

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.


Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	★★★★☆	
Function Controls	★★★★☆	
Engine Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	


Engine		
Item	Assessment	Photo
Engine #1		
Emission Label		
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	

Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	After jump starting, the engine ran.	

Drivetrain


Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Final Drive	★★★★☆	 A close-up photograph of the left front final drive assembly, showing a black circular cover with a central bolt and surrounding mounting hardware.
Left Rear Final Drive	★★★★☆	 A close-up photograph of the left rear final drive assembly, showing a black circular cover with a central bolt and surrounding mounting hardware.
Left Rear Drive Motor	★★★★☆	 A photograph showing the left rear drive motor, which is a red, cylindrical component with a central shaft and surrounding mechanical parts.
Right Rear Final Drive	★★★★☆	 A close-up photograph of the right rear final drive assembly, showing a black circular cover with a central bolt and surrounding mounting hardware.
Right Rear Drive Motor	★★★★☆	 A photograph showing the right rear drive motor, which is a red, cylindrical component with a central shaft and surrounding mechanical parts.
Right Front Final Drive	★★★★☆	 A close-up photograph of the right front final drive assembly, showing a black circular cover with a central bolt and surrounding mounting hardware.
Limited Function Check	The drivetrain was operational.	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★☆☆	
Valves	★★★☆☆	
Hydraulic Tank	★★★☆☆	
Hoses (Hydraulic)	★★★☆☆	
Steering Cylinders	★★★☆☆	
Boom Lift Cylinder	★★★☆☆	
Boom Extension Cylinder	★★★☆☆	

Jib Cylinder	☆☆☆☆	
Basket Tilt Cylinder	☆☆☆☆	
Basket Rotator Motor	☆☆☆☆	
Frame Leveling Cylinders	☆☆☆☆	
Limited Function Check	The hydraulic system was operational.	

Chassis		
Item	Assessment	Photo
Chassis #1		
Chassis #2		
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Left Front Tire	No visible defects	
Left Rear Tire	No visible defects	

Right Rear Tire	Tears	
Right Front Tire	No visible defects	
Wheel Condition	No visible damage or missing components	
Bottom Covers		
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	

Left Side of Boom		 A close-up photograph of the left side of the orange telescopic boom, showing the hydraulic cylinders and structural components. The boom is positioned in a snowy outdoor environment.
Right Side of Boom		 A photograph showing the right side of the boom, highlighting the hydraulic system and the articulation points. The background shows a snowy field and a fence.
Boom Wear Guides	☆☆☆☆	 A close-up view of the boom's wear guides, which are metal components designed to reduce friction and wear during movement. The boom is orange and yellow.
Jib Condition	☆☆☆☆	 A photograph of the jib (the lower section of the boom) in its retracted position. It shows the hydraulic cylinders and the base of the boom. The ground is covered in snow.
Cable Tray Ladder		 A close-up of the cable tray ladder, which is a metal structure used to organize and protect the cables running along the boom. It is painted orange and yellow.
Work Basket		 A photograph of the work basket, which is the platform where the operator stands. It has orange safety railings and a black control panel. The basket is on a snowy surface.

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved