



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14349303 - 2016 JLG 1055 Telehandler



Item Details:

- Features: Open Operator Station, {values=[55], unitId=14} Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing
- Meter Reading: 5,030 Hours
- Serial # : 0160077320
- Inspection Completed: 11/21/25

Shipping Details:

- Location Maryland (Cecil County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0160077320	
CE Mark	No CE mark found	
Paint	No visible damage	
Body Panels	No visible damage or missing components Fuel tank cover not bolted properly screw missing	
Fenders	Left rear missing, Right front missing, Right rear missing	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	

General Appearance #1		
General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		

General Appearance #8		
General Appearance #9		
General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		
General Appearance #14		


General Appearance #15		
General Appearance #16		



Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
Safety #1		
Safety #2		

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Seat/Armrests	Operator arm rest torn	

Glass	No visible damage or missing components	
Mirrors		
Steering Control	★★☆☆ Steering wheel switches missing	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Transmission Disconnect Control	★★★★☆	
Load Charts	Chart book in cab	

Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter / Odometer	5030 hrs	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	US EPA Label not legible Requires Diesel Exhaust Fluid, Data tag damaged	
v2 Engine # 1		
v2 Engine # 2		
v2 Engine # 3		
v2 Engine # 4		
v2 Engine # 5		
v2 Engine # 6		

v2 Engine # 7		
v2 Engine # 8		
v2 Engine # 9		
v2 Engine # 10		
v2 Engine # 11		
v2 Engine # 12		
v2 Engine # 13		

Emission Label	Data tag damaged	
Blow-by (subjective visual observation)	Significant	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	

Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain


Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.





Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	

Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		
Drivetrain #4		
Drivetrain #5		
Drivetrain #6		

Drivetrain #7		
Drivetrain #8		
Drivetrain #9		
Drivetrain #10		
Drivetrain #11		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Has oil accumulation oil dripping	
Boom Lift Cylinder(s)	★★★★☆	

Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Outrigger Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		

Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		
Hydraulics #9		

Hydraulics #10		
Hydraulics #11		
Hydraulics #12		
Hydraulics #13		
Hydraulics #14		
Hydraulics #15		
Hydraulics #16		
Hydraulics #17		


Hydraulics #18		
Hydraulics #19		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		
Chassis #13		

Chassis #14		
Chassis #15		
Chassis #16		
Chassis #17		
Chassis #18		
Chassis #19		
Chassis #20		

Chassis #21		
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	★★★★☆	
Rollers and Guides	★★★★☆	
Boom Wear Guides	★★★★☆	

Outriggers	☆☆☆☆ Street pads	
-------------------	-----------------------------	---

Telehandler*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆ Not visible	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆ Not operationally checked	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 400/75-28 Brand: Camso Model: TLH753 Tread Depth: 31/32	
Left Rear Tire	Size: 400/75-28 Brand: Camso Model: TLH753 Tread Depth: 30/32	

Right Rear Tire	Size: 400/75-28 Brand: Camso Model: TLH753 Tread Depth: 30/32	
Right Front Tire	Size: 400/75-28 Brand: Camso Model: TLH753 Tread Depth: 31/32	
Wheel Condition	No visible damage or missing components	
Telehandler* #1		
Telehandler* #2		
Telehandler* #3		
Telehandler* #4		

Telehandler* #5		
Telehandler* #6		
Telehandler* #7		
Telehandler* #8		
Telehandler* #9		
Telehandler* #10		
Loader Quick Coupler	★★★★☆ Not operationally checked	

Load Back Rest	☆☆☆☆ Unknown material sticks	
Forks	☆☆☆☆	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved