



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #13869120 - 2017 Genie GTH-1056 Telehandler



### Item Details:

- Features: Open Operator Station, 10000 lb Max Lift Capacity, 72 in Forks, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing
- Meter Reading: 2,917 Hours
- Serial # : GTH10E-11911
- Inspection Completed: 8/22/25

### Shipping Details:

- Location California (Riverside County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

## Inspection Ratings Key

|       |                                                                                   |
|-------|-----------------------------------------------------------------------------------|
| ★★★★  | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆ | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆ | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆ | Needs immediate repair/replacement. Requires work if it is to perform as expected |

## Hydraulics

| Item               | Assessment   | Photo                                                                                |
|--------------------|--------------|--------------------------------------------------------------------------------------|
| Hydraulics #19     |              |                                                                                      |
| Pumps (Hydraulics) | ★★★★         |   |
| Valves             | ★★★★<br>Seep |  |
| Hydraulic Tank     | ★★★★         |  |
| Hoses (Hydraulics) | Seep         |  |


|                                              |            |                                                                                      |
|----------------------------------------------|------------|--------------------------------------------------------------------------------------|
| Auxiliary Hydraulic Plumbing                 | Capped off |     |
| Boom Lift Cylinder(s)                        | ★★★★☆      |    |
| Telescopic Boom Cylinders                    | ★★★★☆      |    |
| Carriage Tilt Cylinder                       | ★★★★☆      |   |
| Fork Positioning Cylinder (on fork carriage) | ★★★★☆      |  |
| Frame Leveling Cylinders                     | ★★★★☆      |  |
| Outrigger Cylinders                          | ★★★★☆      |  |

|                        |                                       |                                                                                      |
|------------------------|---------------------------------------|--------------------------------------------------------------------------------------|
| Steering Cylinders     | ☆☆☆☆                                  |     |
| Limited Function Check | The hydraulic system was operational. |                                                                                      |
| Hydraulics #1          |                                       |    |
| Hydraulics #2          |                                       |    |
| Hydraulics #3          |                                       |   |
| Hydraulics #4          |                                       |  |
| Hydraulics #5          |                                       |  |
| Hydraulics #6          |                                       |  |



| General Appearance          |              |                                                                                      |
|-----------------------------|--------------|--------------------------------------------------------------------------------------|
| Item                        | Assessment   | Photo                                                                                |
| Picture, Left Front Corner  |              |    |
| Picture, Left Rear Corner   |              |    |
| Picture, Right Rear Corner  |              |   |
| Picture, Right Front Corner |              |  |
| Serial Number / VIN         | GTH10E-11911 |  |
| Paint                       | Damage       |  |

|                       |                                                                                |                                                                                      |
|-----------------------|--------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Body Panels           | Rust damage                                                                    |     |
| Fenders               | Left front damaged, Left rear damaged, Right front damaged, Right rear damaged |    |
| Steps                 | No visible damage or missing components                                        |    |
| Hand Rails            | No visible damage or missing components                                        |   |
| Exterior Lights       | No lights equips                                                               |  |
| General Appearance #1 |                                                                                |  |
| General Appearance #2 |                                                                                |  |

|                       |  |                                                                                      |
|-----------------------|--|--------------------------------------------------------------------------------------|
| General Appearance #3 |  |     |
| General Appearance #4 |  |    |
| General Appearance #5 |  |    |
| General Appearance #6 |  |   |
| General Appearance #7 |  |  |
| General Appearance #8 |  |  |
| General Appearance #9 |  |  |

|                        |  |                                                                                      |
|------------------------|--|--------------------------------------------------------------------------------------|
| General Appearance #10 |  |     |
| General Appearance #11 |  |    |
| General Appearance #12 |  |    |
| General Appearance #13 |  |   |
| General Appearance #14 |  |  |

| Safety                              |             |                                                                                     |
|-------------------------------------|-------------|-------------------------------------------------------------------------------------|
| Item                                | Assessment  | Photo                                                                               |
| Travel Alarm                        | Operational |                                                                                     |
| Horn                                | Operational |                                                                                     |
| Seat Belts                          | Operational |                                                                                     |
| Current Safety Manual               | Yes         |                                                                                     |
| Current Operator/Maintenance Manual | Yes         |                                                                                     |
| Safety #1                           |             |   |
| Safety #2                           |             |  |

| Control Station                 |                                    |                                                                                      |
|---------------------------------|------------------------------------|--------------------------------------------------------------------------------------|
| Item                            | Assessment                         | Photo                                                                                |
| Seat/Armrests                   | Operator seat cover torn           |    |
| Mirrors                         |                                    |    |
| Steering Control                | ★★★★☆<br>Heavy steering wheel play |   |
| Hydraulic Controls              | ★★★★☆                              |  |
| Drivetrain Controls             | ★★★★☆                              |  |
| Transmission Disconnect Control | ★★★★☆                              |  |


|                        |                                                            |                                                                                      |
|------------------------|------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Load Charts            | Chart book in cab                                          |     |
| Engine Oil Pressure    | The gauge registers in the operating range.                |    |
| Warning Lights         | Operational                                                |    |
| Gauges                 | Operational                                                |   |
| Hour Meter / Odometer  | 2917 hrs                                                   |  |
| Limited Function Check | The main components are in place and operational as noted. |                                                                                      |
| Control Station #1     |                                                            |  |

| Engine                                  |                                         |                                                                                      |
|-----------------------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Item                                    | Assessment                              | Photo                                                                                |
| Blow-by (subjective visual observation) | Spits oil out of dipstick               |                                                                                      |
| Starter                                 | Operational                             |                                                                                      |
| Exhaust System                          | No visible damage or missing components |    |
| Radiator                                | ★★★★☆                                   |    |
| Oil Leaks                               | Filter seep                             |   |
| Engine - Left Side                      |                                         |  |
| Engine - Right Side                     |                                         |  |
| DEF / AdBlue Tank                       |                                         |  |
| Limited Function Check                  | The engine started and ran.             |                                                                                      |

## Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

| Item                       | Assessment          | Photo                                                                                |
|----------------------------|---------------------|--------------------------------------------------------------------------------------|
| Transmission               | ★★☆☆<br>Operational |    |
| Transfer Case / Drop Box   | ★★☆☆<br>Operational |    |
| Front Drive Axle           | ★★☆☆                |   |
| Front Axle Oscillating Pin | ★★☆☆                |  |
| Rear Drive Axle            | ★★☆☆                |  |
| Rear Axle Oscillating Pin  | ★★☆☆                |  |

|                        |                                 |                                                                                      |
|------------------------|---------------------------------|--------------------------------------------------------------------------------------|
| Final Drives           | ★★★★☆                           |     |
| Limited Function Check | The drivetrain was operational. |                                                                                      |
| Drivetrain #1          |                                 |    |
| Drivetrain #2          |                                 |    |
| Drivetrain #3          |                                 |   |
| Drivetrain #4          |                                 |  |
| Drivetrain #5          |                                 |  |
| Drivetrain #6          |                                 |  |



## Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item               | Assessment | Photo                                                                                |
|--------------------|------------|--------------------------------------------------------------------------------------|
| Boom Condition     | ★★★★☆      |    |
| Left Side of Boom  |            |    |
| Right Side of Boom |            |   |
| Chain / Tensioners | ★★★★☆      |  |
| Rollers and Guides | ★★★★☆      |  |
| Boom Wear Guides   | ★★★★☆      |  |

|            |      |                                                                                    |
|------------|------|------------------------------------------------------------------------------------|
| Outriggers | ☆☆☆☆ |   |
| Chassis #1 |      |  |
| Chassis #2 |      |  |

**Telehandler\***

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item                            | Assessment                                                                  | Photo                                                                                |
|---------------------------------|-----------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Steering Linkage                | ★★★★☆                                                                       |    |
| Frame Condition                 | ★★★★☆                                                                       |    |
| Limited Function Check          | The main chassis components functioned during a limited check.              |                                                                                      |
| Master Cylinder                 | ★★★★☆                                                                       |   |
| Brake Control                   | ★★★★☆                                                                       |  |
| Brake Lines/Hoses               | ★★★★☆                                                                       |                                                                                      |
| Park Brake                      | ★★★★☆                                                                       |                                                                                      |
| Limited Function Check - Brakes | The service brakes are operational, The park brake is operational.          |                                                                                      |
| Left Front Tire                 | Size: 14.00-28(360/85-28) Brand: Genie Model: ENDURO A/T Tread Depth: 22/32 |  |

|                  |                                         |                                                                                      |
|------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Left Rear Tire   | Tread Depth: 20/32                      |     |
| Right Rear Tire  | Tread Depth: 21/32                      |    |
| Right Front Tire | Tread Depth: 20/32                      |    |
| Wheel Condition  | No visible damage or missing components |   |
| Load Back Rest   | ★★★★☆                                   |  |
| Forks            | ★★★★☆                                   |  |
| Telehandler* #1  |                                         |  |

|                 |  |                                                                                    |
|-----------------|--|------------------------------------------------------------------------------------|
| Telehandler* #2 |  |   |
| Telehandler* #3 |  |  |
| Telehandler* #4 |  |  |

**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet, Inc. © 2012 All Rights Reserved