



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14095008 - 2018 Genie GTH-844 Telehandler



Item Details:

- Features: Enclosed Cab, Air Conditioner, 44 ft Max Lift Height, 8000 lb Max Lift Capacity, 2015 US EPA Label, 60 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing
- Meter Reading: 3,957 Hours
- Serial # : GTH08E-11990
- Inspection Completed: 10/9/25

Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

<p>Serial Number / VIN</p>	<p>GTH08E-11990</p>	 <p>The image shows a white identification plate with black text. At the top, it says 'Genie'. Below that, it lists: 'MODEL: GTH844', 'SERIAL NUMBER: GTH08E-11990', 'STATIONARY: 48" x 48" x 48"', 'YEAR OF MANUFACTURE: 2018', 'TOTAL PRODUCTION: 8918 (81-1999) of', 'MAX. LIFT CAPACITY: 4500 lbs', 'MAX. EXTENDED: 4500 lbs', 'AT MAX. LIFT CAPACITY', 'COUNTRY OF MANUFACTURE: United States', 'MADE IN: United States', 'Genie USA, LLC', '10000 W. 10th Street', 'Genie Tower', 'Scottsdale, AZ 85258', 'TEL: 480-346-7000', 'WWW.GENIE.COM', '© 2018 Genie'. There is an 'IRON PLANET' logo in the bottom right corner of the photo.</p>
<p>Paint</p>	<p>No visible damage</p>	 <p>The image shows the side of the blue telehandler. It has 'HercRentals' written in white on the top and 'Genie' in yellow on the side. There is an 'IRON PLANET' logo in the bottom right corner.</p>
<p>Body Panels</p>	<p>No visible damage or missing components</p>	 <p>The image shows the rear of the blue telehandler. It has 'HercRentals' and 'Genie' branding. There is an 'IRON PLANET' logo in the bottom right corner.</p>
<p>Fenders</p>	<p>Left rear damaged, Right rear damaged</p>	 <p>The image is a close-up of the rear wheel and fender area. The fender is cracked and damaged. There is a yellow 'Herc' sticker and a white label with the number '10-23-0316'. There is an 'IRON PLANET' logo in the bottom right corner.</p>
<p>Steps</p>	<p>No visible damage or missing components</p>	 <p>The image shows a close-up of the operator's step area. The step is black and appears to be in good condition. There is an 'IRON PLANET' logo in the bottom right corner.</p>
<p>Hand Rails</p>	<p>No visible damage or missing components</p>	 <p>The image shows the operator's perspective from inside the cab. Hand rails are visible on the sides of the cab. There is an 'IRON PLANET' logo in the bottom right corner.</p>
<p>Exterior Lights</p>	<p>All lights operational</p>	 <p>The image shows the front view of the blue telehandler. The headlights and other exterior lights are visible. There is an 'IRON PLANET' logo in the bottom right corner.</p>

General Appearance #1		
General Appearance #2		
General Appearance #3		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Inoperable	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station		
Item	Assessment	Photo
Seat/Armrests	Operator seat armrest damaged	
Glass	No visible damage or missing components	
Mirrors		
Cab Door	No visible damage or missing components	
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Load Charts	Posted on cab wall	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter / Odometer	3957 hrs	
Air Conditioner	Inoperable	
Heater	Not operationally checked	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		

Control Station #2		
Control Station #3		

Engine		
Item	Assessment	Photo
Engine	2015 US EPA Label	
Emission Label		
A/C Compressor	Compressor will not engage	
Blow-by (subjective visual observation)	Recirculating system	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		

Engine - Right Side		
Limited Function Check	The engine started and ran.	

Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	

Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Front	
Boom Lift Cylinder(s)	★★★★☆	
Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	

Frame Leveling Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Boom Condition	★★★☆☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	★★★☆☆	
Rollers and Guides	★★★☆☆	
Boom Wear Guides	★★☆☆☆ Heavy wear	

Telehandler*		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 13.00-24 Brand: Solidbos Tread Depth: 48/32	
Left Rear Tire	Size: 13.00-24 Brand: Solidbos Tread Depth: 37/32	

<p>Right Rear Tire</p>	<p>Size: 13.00-24 Brand: Solidbos Tread Depth: 42/32</p>	
<p>Right Front Tire</p>	<p>Size: 13.00-24 Brand: Solidboss Tread Depth: 42/32</p>	
<p>Wheel Condition</p>	<p>No visible damage or missing components</p>	
<p>Loader Quick Coupler</p>	<p>Not operationally checked</p>	
<p>Load Back Rest</p>	<p>★★★★☆</p>	
<p>Forks</p>	<p>★★★★☆</p>	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved