



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #14340554 - 2016 Skyjack SJ4632 Electric Scissor Lift



### Item Details:

- Features: 32 ft Max Platform Height, 700 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box
- Meter Reading: 304 Hours
- Serial #: 70028458
- Inspection Completed: 11/17/25

### Shipping Details:

- Location Missouri (Kansas City, MO-KS area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Buyer MUST Call 48 Hours in Advance of Pickup, Buyer MUST Self Load

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

## **Inspection Ratings Key**

|       |                                                                                   |
|-------|-----------------------------------------------------------------------------------|
| ★★★★  | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆ | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆ | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆ | Needs immediate repair/replacement. Requires work if it is to perform as expected |

## **General Appearance**

| Item                        | Assessment | Photo                                                                                |
|-----------------------------|------------|--------------------------------------------------------------------------------------|
| Picture, Left Front Corner  |            |   |
| Picture, Left Rear Corner   |            |  |
| Picture, Right Rear Corner  |            |  |
| Picture, Right Front Corner |            |  |

|                         |                                         |                                                                                      |
|-------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Serial Number / VIN     | 70028458                                |     |
| CE Mark                 | No CE mark found                        |                                                                                      |
| Hour Meter / Odometer   | 304 hrs                                 |    |
| Paint                   | No visible damage                       |    |
| Body Panels             | No visible damage or missing components |                                                                                      |
| Steps/Ladders           |                                         |   |
| Basket / Safety Railing | No visible damage or missing components |                                                                                      |
| General Appearance #1   |                                         |  |

| Safety                              |             |                                                                                    |
|-------------------------------------|-------------|------------------------------------------------------------------------------------|
| Item                                | Assessment  | Photo                                                                              |
| Travel Alarm                        | Operational |                                                                                    |
| Horn                                | Operational |                                                                                    |
| Current Safety Manual               | No          |                                                                                    |
| Current Operator/Maintenance Manual | Yes         |                                                                                    |
| ANSI Guidelines                     | Yes         |  |
| Safety #1                           |             |  |

| Control Station Ground |                                                            |                                                                                    |
|------------------------|------------------------------------------------------------|------------------------------------------------------------------------------------|
| Item                   | Assessment                                                 | Photo                                                                              |
| Function Controls      | ☆☆☆☆                                                       |  |
| Limited Function Check | The main components are in place and operational as noted. |                                                                                    |

## Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item                            | Assessment                                                 | Photo                                                                                |
|---------------------------------|------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Control Console                 | No visible damage or missing components                    |    |
| Emergency Shut Off Switch       | Operational                                                |    |
| Safety Control Hand/Foot Switch | ★★★★☆<br>Operational                                       |   |
| Upper Function Controls         | ★★★★☆                                                      |  |
| Limited Function Check          | The main components are in place and operational as noted. |                                                                                      |
| Control Station Upper #1        |                                                            |  |

| Electrical Operating System |                                                                                 |                                                                                    |
|-----------------------------|---------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
| Item                        | Assessment                                                                      | Photo                                                                              |
| Operating Voltage           | 24 Volts                                                                        |                                                                                    |
| Battery Condition           | Functioned during the inspection                                                |                                                                                    |
| Cables and Connections      | No visible damage or missing components                                         |  |
| Battery Charger             | Included Appears normal - Not operationally checked, 100-240 Volt, Single Phase |  |
| Limited Function Check      | The electrical system was operational in a limited check.                       |                                                                                    |

**Drivetrain**

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

| Item                   | Assessment                      | Photo                                                                              |
|------------------------|---------------------------------|------------------------------------------------------------------------------------|
| Drive Motors           | ☆☆☆☆                            |  |
| Limited Function Check | The drivetrain was operational. |                                                                                    |

| Hydraulics             |                                       |                                                                                                                                                                                                                                                      |
|------------------------|---------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Item                   | Assessment                            | Photo                                                                                                                                                                                                                                                |
| Pumps (Hydraulics)     | ★★★★☆                                 |  A close-up photograph of the hydraulic pump assembly, showing the pump motor, control valve, and associated hoses. The unit is mounted on a metal frame.          |
| Valves                 | ★★★★☆                                 |  A close-up photograph of the hydraulic valve assembly, showing the control valve and associated hoses. The unit is mounted on a metal frame.                      |
| Hydraulic Tank         | ★★★★☆                                 |  A close-up photograph of the hydraulic tank, showing the tank body, filler cap, and associated hoses. The unit is mounted on a metal frame.                      |
| Hoses                  |                                       |  A close-up photograph of the hydraulic hoses, showing the hoses connected to the pump and valve assembly. The hoses are black and have yellow and red markings. |
| Lift Cylinders         | ★★★★☆                                 |  A close-up photograph of the lift cylinders, showing the cylinders mounted on the lift arms. The cylinders are black and have yellow and red markings.          |
| Steering Cylinder      | ★★★★☆                                 |  A close-up photograph of the steering cylinder, showing the cylinder mounted on the steering arm. The cylinder is black and has yellow and red markings.        |
| Limited Function Check | The hydraulic system was operational. |                                                                                                                                                                                                                                                      |

|               |  |                                                                                   |
|---------------|--|-----------------------------------------------------------------------------------|
| Hydraulics #1 |  |  |
|---------------|--|-----------------------------------------------------------------------------------|

## Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item               | Assessment                                                             | Photo                                                                                |
|--------------------|------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Brake System       | ★★☆☆<br>The brake system functioned, stopping and holding the machine. |    |
| Steering Linkage   | ★★☆☆                                                                   |    |
| Frame Condition    | ★★☆☆                                                                   |   |
| Scissor Linkage    | ★★☆☆                                                                   |  |
| Platform Condition | ★★☆☆                                                                   |  |
| Platform Extension | ★★☆☆                                                                   |  |

|                                       |                                                            |                                                                                      |
|---------------------------------------|------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Left Front Tire                       | No visible defects                                         |     |
| Left Rear Tire                        | No visible defects                                         |    |
| Right Rear Tire                       | No visible defects                                         |    |
| Right Front Tire                      | No visible defects                                         |   |
| Wheel Condition                       | No visible damage or missing components                    |                                                                                      |
| Wheel Studs                           | ★★★★☆                                                      |                                                                                      |
| Pothole Protection Bars               | ★★★★☆<br>Functional                                        |  |
| Limited Function Check (Scissor-lift) | The main components appear to be in place and operational. |                                                                                      |
| Chassis #1                            |                                                            |  |

Chassis #2



**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet , Inc. © 2012 All Rights Reserved