



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810957 - 2016 JLG 4069LE Electric Scissor Lift



Item Details:

- Features: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Non-Marking Tires, Upper Control Box
- Meter Reading: 681 Miles
- Serial # : 0200253525
- Inspection Completed: 8/11/25

Shipping Details:


- Location Texas (Tarrant County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Hydraulics		
Item	Assessment	Photo
Hydraulics #9		
Pumps (Hydraulics)	★★★★	 A close-up photograph of a hydraulic pump assembly mounted on a yellow machine. The pump is a small, cylindrical unit with various hoses and electrical connections. The background shows the yellow body of the machine with the text 'www.jlg.com' visible.
Valves	★★★★	 A photograph showing a complex arrangement of hydraulic valves and hoses. The components are mounted on a yellow metal frame. The background is a yellow surface with the text 'IRON PLANET' visible.
Hydraulic Tank	★★★★	 A photograph of a hydraulic tank, which is a large, rectangular container with a yellow top. It has various hoses and a pump unit attached to it. The background shows the yellow body of the machine with the text 'www.jlg.com' visible.
Hoses	Blown hose.	 A photograph showing a close-up of a hydraulic hose that has been blown out, with the internal structure exposed. The hose is yellow and the background shows the yellow body of the machine.

Lift Cylinders	★★☆☆ Hydraulic leak visible platform raises and then comes down.	
Steering Cylinder	★★★☆☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	0200253525	
CE Mark	No CE mark found	
Hour Meter / Odometer	681 mi, Not operationally checked.	

Paint	No visible damage	
Body Panels	Hydraulic compartment door damaged, Compartment doors on all sides damaged.	
Steps/Ladders	Bent	
Basket / Safety Railing	Left railing bent, Right railing bent	
General Appearance #1		
General Appearance #2		
General Appearance #3		
General Appearance #4		

General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	No	

Control Station Ground		
Item	Assessment	Photo
Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	

Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	48 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Appears normal - Not operationally checked, 115 Volt, Single Phase Plug cover broken.	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		
Electrical Operating System #2		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drive Motors	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine.	
Steering Linkage	★★☆☆	
Frame Condition	★★☆☆	
Scissor Linkage	★★☆☆	
Platform Condition	★★☆☆	
Platform Extension	★★☆☆	

Left Front Tire	Cracks, Chunks missing	
Left Rear Tire	Cracks, Chunks missing	
Right Rear Tire	Cracks, Chunks missing	
Right Front Tire	Cracks, Chunks missing	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Limited Function Check (Scissor-lift)	The main components functioned with minor wear throughout.	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved