



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810821 - 2016 Genie GS3232 Electric Scissor Lift



Item Details:

- Features: 32 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box
- Meter Reading: 47 Hours
- Serial # : GS3216P-147090
- Inspection Completed: 8/4/25

Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drivetrain #2		
Drive Motors	★★★★	
Limited Function Check	The drivetrain was operational.	

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	GS3216P-147090	
Hour Meter / Odometer	47 hrs	

Paint	Concrete residue And has rust on it	
Body Panels	Right door is bent. Bent panel on the back left	
Steps/Ladders	Bent	
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		
General Appearance #2		
General Appearance #3		

General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		
General Appearance #10		

General Appearance #11



Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	No	


Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Engine Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	


Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	Screen is hard to see	
Emergency Shut Off Switch	Operational	
Upper Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	24 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included 24 Volt, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	


Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		
Hydraulics #2		


Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Brake System	★★★★☆	
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Scissor Linkage	★★★★☆	
Platform Condition	★★★☆☆ Has some bent metal	
Platform Extension	★★★★☆	
Left Front Tire	Tears	

Left Rear Tire	Tears	
Right Rear Tire	Tears	
Right Front Tire	Tears	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Pothole Protection Bars	★★★★☆ Functional	
Outriggers / Stabilizers	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	

Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		

Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		
Chassis #13		
Chassis #14		

Chassis #15		
Chassis #16		
Chassis #17		
Chassis #18		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved