



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13811434 - 2016 JLG 4069LE Scissor Lift



Item Details:

- Features: 46 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Power Inverter, Upper Control Box
- Meter Reading: 571 Hours
- Serial # : 0200258325
- Inspection Completed: 8/7/25

Shipping Details:

- Location California (Riverside County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0200258325	
Hour Meter / Odometer	571 hrs	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	
Safety #1		
Safety #2		
Safety #3		

Control Station Ground		
Item	Assessment	Photo
Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground #1		


Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	48 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included Appears normal - Not operationally checked, 120 Volt, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	

Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Drive Motors	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		


Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	 A close-up photograph of a hydraulic pump assembly mounted on a yellow metal frame. The pump is a white, rectangular unit with various hoses and electrical connections. An "IRON PLANET" watermark is visible in the bottom right corner.
Valves	★★★★☆	 A close-up photograph of hydraulic hoses and valves. The hoses are braided and connected to various components. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulic Tank	★★★★☆	 A photograph showing a hydraulic tank and pump assembly. The tank is a large, dark, rectangular unit, and the pump is a white unit mounted on top. An "IRON PLANET" watermark is visible in the bottom right corner.
Hoses		 A photograph showing hydraulic hoses and a tank. The hoses are connected to a white tank. An "IRON PLANET" watermark is visible in the bottom right corner.
Lift Cylinders	★★★★☆	 A photograph showing the lift cylinders of the scissor lift. The cylinders are yellow and extend upwards. An "IRON PLANET" watermark is visible in the bottom right corner.
Steering Cylinder	★★★★☆	 A close-up photograph of a steering cylinder. The cylinder is a dark, cylindrical unit with a metal rod extending from the top. An "IRON PLANET" watermark is visible in the bottom right corner.
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1




Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Scissor Linkage	★★★★☆	
Platform Condition	★★★★☆	
Platform Extension	★★★★☆	
Left Front Tire	No visible defects	

Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	
Right Front Tire	No visible defects	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		
Chassis #2		

Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved