



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14340467 - 2015 Skyjack SJ7135RT Diesel 4x4 Scissor Lift



Item Details:

- Features: 35 ft Max Platform Height, 900 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Upper Control Box, Tier 4, 2015 US EPA Label, Kubota D1105-EF02 3 Cylinder 18.5 kW 1.1 L Diesel Engine
- Meter Reading: 2,791 Hours
- Serial # : 34003166
- Inspection Completed: 11/8/25

Shipping Details:

- Location Illinois (Grundy County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	34003166	
Hour Meter / Odometer	2791 hrs	
Paint	Other unknown material	
Body Panels	Engine compartment door damaged, Hydraulic compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	Left railing bent, Right railing bent, Front railing bent, Rear railing bent	
General Appearance #1		

General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	

Control Station Ground		
Item	Assessment	Photo
Function Controls	☆☆☆☆	
Engine Oil Pressure	No oil pressure indicator	
Limited Function Check	The main components are in place and operational as noted.	

Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		



Engine		
Item	Assessment	Photo
Emission Label		
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	



Engine #1		
Engine #2		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Front Drive Axle	★★★★☆	 A close-up photograph of the front drive axle assembly of a green scissor lift. The axle is a heavy-duty metal shaft with a differential housing in the center. The surrounding components are painted green, matching the lift's body. The ground is a light-colored gravel or dirt surface.
Rear Drive Axle	★★★★☆	 A photograph of the rear drive axle assembly. This view shows the axle from a slightly different angle, highlighting the rear differential and the connection to the lift's frame. A yellow and orange vehicle is visible in the background, parked on the same gravel surface.
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		 A detailed close-up of the drivetrain components, showing the axle, differential, and various suspension parts. The components are metallic and show some signs of wear and grease. The green paint of the lift's frame is visible at the edges of the frame.


Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	

Outrigger Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		

Hydraulics #7		
Hydraulics #8		
Hydraulics #9		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Scissor Linkage	★★★★☆	
Platform Condition	★★★★☆	
Platform Extension	★★★★☆	
Left Front Tire	Cracks, Chunks missing, Tears	

Left Rear Tire	Cracks, Chunks missing, Tears	
Right Rear Tire	Cracks, Chunks missing, Tears	
Right Front Tire	Cracks, Chunks missing, Tears	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Outriggers / Stabilizers	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		
Chassis #2		

Chassis #3



Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved