



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13811482 - 2016 JLG 4069LE Electric Scissor Lift



Item Details:

- Features: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Non-Marking Tires, Upper Control Box
- Meter Reading: 610 Hours
- Serial # : 200253037
- Inspection Completed: 9/16/25

Shipping Details:

- Location Arizona (Phoenix-Mesa area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	200253037	
Hour Meter / Odometer	610 hrs	
Paint	No visible damage	
Body Panels	Hydraulic compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	

Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	48 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included 110 Volt, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drive Motors	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	 A close-up photograph of a hydraulic pump assembly mounted on a yellow metal frame. The pump is a black and silver unit with various hoses and electrical connections. An "IRON PLANET" watermark is visible in the bottom right corner.
Valves	★★★★☆	 A photograph showing a hydraulic valve assembly with multiple colored hoses (red, blue, yellow) connected to a metal block. The assembly is mounted on a yellow frame. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulic Tank	★★★★☆	 A photograph of a hydraulic tank and pump assembly. The tank is a white plastic container with a black pump motor on top. It is mounted on a yellow frame. An "IRON PLANET" watermark is visible in the bottom right corner.
Hoses		 A photograph showing a complex arrangement of hydraulic hoses and a valve assembly. The hoses are various colors and are connected to a metal valve block. The background is a yellow metal frame. An "IRON PLANET" watermark is visible in the bottom right corner.
Lift Cylinders	★★★★☆	 A photograph showing the internal structure of a scissor lift, specifically the lift cylinders. The cylinders are yellow and are arranged in a parallel fashion. An "IRON PLANET" watermark is visible in the bottom right corner.
Steering Cylinder	★★★★☆	 A photograph of a steering cylinder, which is a black metal component with a hydraulic hose attached. It is mounted on a yellow metal frame. An "IRON PLANET" watermark is visible in the bottom right corner.
Limited Function Check	The hydraulic system was operational.	

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Scissor Linkage	★★★★☆	
Platform Condition	★★★★☆	
Platform Extension	★★★★☆	
Left Front Tire	Cracks	

Left Rear Tire	Cracks	
Right Rear Tire	Cracks	
Right Front Tire	Chunks missing	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		
Chassis #2		

Chassis #3



Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved