



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14339927 - 2019 Skyjack SJ 3226 Electric Scissor Lift



Item Details:

- Features: 26 ft Max Platform Height, 500 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires
- Meter Reading: 292 Hours
- Serial # : 27042860
- Inspection Completed: 11/18/25

Shipping Details:

- Location Florida (Lakeland-Winter Haven area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	27042860	
Hour Meter / Odometer	292 hrs	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

General Appearance #2



Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	No	

Control Station Ground		
Item	Assessment	Photo
Function Controls	☆☆☆☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground #1		

Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		
Control Station Upper #2		

Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	24V DC Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included Appears normal - Not operationally checked, 110V AC Volt, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.


Item	Assessment	Photo
Drive Motors	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		 A close-up photograph of a hydraulic cylinder, likely part of a scissor lift. The cylinder is silver and black, with a red stripe. The IronPlanet logo is visible in the bottom right corner of the image.
---------------	--	--

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine.	
Steering Linkage	★★☆☆	
Frame Condition	★★☆☆	
Scissor Linkage	★★☆☆	
Platform Condition	★★☆☆	
Platform Extension	★★☆☆	

Left Front Tire	Cracks	
Left Rear Tire	Cracks	
Right Rear Tire	Cracks	
Right Front Tire	Cracks	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Pothole Protection Bars	★★★★☆ Functional	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	

Chassis #1



Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved