



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810956 - 2016 JLG 4069LE Electric Scissor Lift



Item Details:

- Features: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Power to Platform
- Meter Reading: 555 Hours
- Serial # : 0200253063
- Inspection Completed: 8/26/25

Shipping Details:

- Location Texas (Tarrant County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report


Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0200253063	
Hour Meter / Odometer	555 hrs	
Paint	No visible damage	
Body Panels	Battery compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

General Appearance #2		
General Appearance #3		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	
Safety #1		

Control Station Ground		
Item	Assessment	Photo
Function Controls	★ ★ ★ ☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground #1		

Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	

Electrical Operating System

Item	Assessment	Photo
Operating Voltage	24 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included 24 Volt	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		
Electrical Operating System #2		
Electrical Operating System #3		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drive Motors	★★★★☆	
Front Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	 A close-up photograph of a hydraulic pump assembly mounted on a yellow metal frame. The pump is a compact, cylindrical unit with various hoses and electrical connections. An "IRON PLANET" watermark is visible in the bottom right corner.
Valves	★★★★☆	 A photograph showing a hydraulic valve assembly with multiple ports and hoses, mounted on a yellow metal structure. The assembly is complex, with various wires and hydraulic lines connected. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulic Tank	★★★★☆	 A photograph of a hydraulic tank and pump assembly. The tank is a large, rectangular metal container with a pump mounted on top. Various hoses and electrical connections are visible. An "IRON PLANET" watermark is visible in the bottom right corner.
Hoses		 A photograph showing a bundle of hydraulic hoses and wires, neatly organized and secured with straps. The hoses are connected to various components of the lift. An "IRON PLANET" watermark is visible in the bottom right corner.
Lift Cylinders	★★★★☆	 A photograph looking up at a large hydraulic cylinder, which is part of the lift mechanism. The cylinder is a thick, black metal rod extending upwards. The background shows a construction site with various equipment. An "IRON PLANET" watermark is visible in the bottom right corner.
Steering Cylinder	★★★★☆	 A close-up photograph of a steering cylinder, showing the hydraulic rod and the mounting bracket. The cylinder is a thick, black metal rod. An "IRON PLANET" watermark is visible in the bottom right corner.
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Scissor Linkage	★★★★☆	
Platform Condition	★★★★☆	
Platform Extension	★★★★☆	
Left Front Tire	No visible defects	

Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	
Right Front Tire	No visible defects	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		
Chassis #2		

Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved