



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #14095007 - 2016 Genie GS-4390 Diesel 4x4 Scissor Lift



### Item Details:

- Features: 1500 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Foam Filled Tires, Upper Control Box, 2015 US EPA Label, Deutz D2.9 L4 4 Cylinder 49 hp Diesel Engine
- Meter Reading: 2,759 Hours
- Serial #: GS9016F-51456
- Inspection Completed: 10/9/25

### Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

## **Inspection Ratings Key**

|       |                                                                                   |
|-------|-----------------------------------------------------------------------------------|
| ★★★★  | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆ | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆ | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆ | Needs immediate repair/replacement. Requires work if it is to perform as expected |

## **General Appearance**

| Item                        | Assessment | Photo                                                                                |
|-----------------------------|------------|--------------------------------------------------------------------------------------|
| Picture, Left Front Corner  |            |   |
| Picture, Left Rear Corner   |            |  |
| Picture, Right Rear Corner  |            |  |
| Picture, Right Front Corner |            |  |

|                         |                                         |                                                                                      |
|-------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Serial Number / VIN     | GS9016F-51456                           |     |
| Hour Meter / Odometer   | 2759 hrs                                |    |
| Paint                   | No visible damage                       |    |
| Body Panels             | Engine compartment door damaged         |   |
| Steps/Ladders           |                                         |  |
| Basket / Safety Railing | No visible damage or missing components |                                                                                      |
| General Appearance #1   |                                         |  |

General Appearance #2



| Safety                              |             |       |
|-------------------------------------|-------------|-------|
| Item                                | Assessment  | Photo |
| Travel Alarm                        | Operational |       |
| Horn                                | Operational |       |
| Current Safety Manual               | No          |       |
| Current Operator/Maintenance Manual | No          |       |
| ANSI Guidelines                     | No          |       |

| Control Station Ground |                                                            |                                                                                     |
|------------------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Item                   | Assessment                                                 | Photo                                                                               |
| Gauges                 | Operational                                                |   |
| Function Controls      | ★★★★☆                                                      |   |
| Engine Oil Pressure    | The gauge registers in the operating range.                |  |
| Limited Function Check | The main components are in place and operational as noted. |                                                                                     |

## Control Station Upper

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item                      | Assessment                                                 | Photo                                                                               |
|---------------------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Control Console           | No visible damage or missing components                    |   |
| Emergency Shut Off Switch | Operational                                                |   |
| Upper Function Controls   | ★★★★☆                                                      |  |
| Limited Function Check    | The main components are in place and operational as noted. |                                                                                     |



| Engine                                  |                                         |                                                                                      |
|-----------------------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Item                                    | Assessment                              | Photo                                                                                |
| Emission Label                          |                                         |    |
| Blow-by (subjective visual observation) | Recirculating system                    |                                                                                      |
| Starter                                 | Operational                             |                                                                                      |
| Fuel System                             | Operational                             |    |
| Exhaust System                          | No visible damage or missing components |   |
| Radiator                                | ★★★☆☆                                   |  |
| Oil Leaks                               | No dripping leaks                       |                                                                                      |
| Fuel Leaks                              | No dripping leaks                       |                                                                                      |
| Cooling System Leaks                    | No dripping leaks                       |                                                                                      |
| Onboard Generator                       | Not operationally checked               |  |



|                        |                             |                                                                                    |
|------------------------|-----------------------------|------------------------------------------------------------------------------------|
| Engine - Left Side     |                             |   |
| Engine - Right Side    |                             |  |
| Limited Function Check | The engine started and ran. |                                                                                    |

## Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

| Item                   | Assessment                      | Photo                                                                              |
|------------------------|---------------------------------|------------------------------------------------------------------------------------|
| Drive Motors           | ☆☆☆☆<br>Can not get rear motors |  |
| Final Drives           | ☆☆☆☆                            |  |
| Limited Function Check | The drivetrain was operational. |                                                                                    |

| Hydraulics             |                                       |                                                                                      |
|------------------------|---------------------------------------|--------------------------------------------------------------------------------------|
| Item                   | Assessment                            | Photo                                                                                |
| Pumps (Hydraulics)     | ★★★★☆                                 |    |
| Valves                 | ★★★★☆                                 |    |
| Hydraulic Tank         | ★★★★☆                                 |   |
| Hoses                  |                                       |  |
| Lift Cylinders         | ★★★☆☆<br>Seepage                      |  |
| Steering Cylinder      | ★★★★☆                                 |  |
| Limited Function Check | The hydraulic system was operational. |                                                                                      |

## Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item               | Assessment            | Photo                                                                                |
|--------------------|-----------------------|--------------------------------------------------------------------------------------|
| Steering Linkage   | ★★★★☆                 |    |
| Frame Condition    | ★★★★☆                 |    |
| Scissor Linkage    | ★★★☆☆<br>Cracked weld |   |
| Platform Condition | ★★★★☆                 |  |
| Platform Extension | ★★★★☆                 |  |
| Left Front Tire    | Chunks missing        |  |

|                                       |                                                            |                                                                                     |
|---------------------------------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Left Rear Tire                        | Chunks missing                                             |    |
| Right Rear Tire                       | Chunks missing                                             |   |
| Right Front Tire                      | Chunks missing                                             |   |
| Wheel Condition                       | No visible damage or missing components                    |  |
| Wheel Studs                           | ★★★★☆                                                      |                                                                                     |
| Limited Function Check (Scissor-lift) | The main components appear to be in place and operational. |                                                                                     |

Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved