



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13810858 - 2016 JLG 600S 4WD Diesel Telescopic Boom Lift



Item Details:

- Features: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Deutz 4 Cylinder Diesel Engine, Foam-Filled Tires
- Meter Reading: 2,995 Hours
- Serial # : 0300216402
- Inspection Completed: 8/4/25

Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0300216402	
Hour Meter / Odometer	2995 hrs	
Paint	Has a lot of rust on it	
Body Panels	Has a lot of rust on it	
Basket / Safety Railing	Top rail is bent metal riding is bent has rust on it and has a piece screw to the front of it	
General Appearance #1		
General Appearance #2		

General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		

General Appearance #10		
General Appearance #11		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Foot Switch	☆☆☆☆	
Function Controls	☆☆☆☆	
Engine Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Blow-by (subjective visual observation)	Can not get video	
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Onboard Generator	Not operationally checked	
Engine - Left Side		
Limited Function Check	The engine started and ran.	

Engine #1		
Engine #2		
Engine #3		
Engine #4		
Engine #5		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Final Drive	★★★★☆	
Left Front Drive Motor	★★★★☆	
Left Rear Final Drive	★★★★☆	
Left Rear Drive Motor	★★★★☆	
Right Rear Final Drive	★★★★☆	
Right Rear Drive Motor	★★★★☆	


Right Front Final Drive	★ ★ ★ ☆	
Right Front Drive Motor	★ ★ ★ ☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★☆☆ Has residue on it	
Valves	★★★☆	
Hydraulic Tank	★★★☆	
Hoses (Hydraulic)	★★☆☆ Some of the hoses are dry rotted	
Steering Cylinders	★★★☆	
Boom Lift Cylinder	★★☆☆ Dripping leak	

Secondary Boom Cylinder	★★★★☆	
Boom Extension Cylinder	★★★★☆	
Basket Tilt Cylinder	Dripping leak	
Basket Rotator Motor	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		

Hydraulics #4		
Hydraulics #5		

Chassis		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Brake System	★★★★☆	
Left Front Tire	Cracks, Chunks missing, Tears	
Left Rear Tire	Cracks, Chunks missing, Tears	
Right Rear Tire	Cracks, Chunks missing, Tears	
Right Front Tire	Cracks, Chunks missing, Tears	

Wheel Condition	No visible damage or missing components	
Turntable Bearing	★★★★☆	
Bottom Covers		
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	
Left Side of Boom	Has a lot of rust	

Right Side of Boom	Has a lot of rust	
Boom Wear Guides	★★★★☆	
Cable Tray Ladder		
Work Basket		
Chassis #1		
Chassis #2		
Chassis #3		

Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		

Chassis #11		
Chassis #12		
Chassis #13		
Chassis #14		
Chassis #15		
Chassis #16		
Chassis #17		

Chassis #18		
Chassis #19		
Chassis #20		
Chassis #21		
Chassis #22		
Chassis #23		
Chassis #24		

Chassis #25		
Chassis #26		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved