



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13811008 - 2016 JLG 800S 4WD Diesel Telescopic Boom Lift



Item Details:

- Features: 80 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, Tier 4, 2015 US EPA Label, Deutz TD2.9L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 16-625NHS Foam-Filled Tires
- Meter Reading: 5,601 Hours
- Serial # : 0300202457
- Inspection Completed: 9/18/25

Shipping Details:

- Location Tennessee (Nashville area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0300202457	
Hour Meter / Odometer	5601 hrs	
Paint	Other unknown material	
Body Panels	Hydraulic compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		

General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		


Safety		
Item	Assessment	Photo
Travel Alarm	Inoperable	
Horn	Inoperable	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	


Control Station Ground		
Item	Assessment	Photo
Function Controls	★★★★☆	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	★★★★☆ Operational	
Function Controls	★★★★☆	
Engine Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted. The item was not operational. The main components could not be operationally checked.	

Engine		
Item	Assessment	Photo
Engine #1		
Emission Label		
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	


Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Onboard Generator	Operational	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	After jump starting, the engine ran.	

Drivetrain


Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Final Drive	★★★★☆	 A close-up photograph of the left front final drive assembly, showing a large, treaded tire mounted on a white rim. The assembly is part of an orange machine.
Left Front Drive Motor	★★★★☆	 A close-up photograph of the left front drive motor, showing a hydraulic cylinder and associated components. A warning label is visible on the orange body.
Left Rear Final Drive	★★★★☆	 A close-up photograph of the left rear final drive assembly, showing a large, treaded tire mounted on a white rim. The assembly is part of an orange machine.
Left Rear Drive Motor	★★★★☆	 A close-up photograph of the left rear drive motor, showing a hydraulic cylinder and associated components. The orange body of the machine is visible.
Right Rear Final Drive	★★★★☆	 A close-up photograph of the right rear final drive assembly, showing a large, treaded tire mounted on a white rim. The assembly is part of an orange machine.
Right Rear Drive Motor	★★★★☆	 A close-up photograph of the right rear drive motor, showing a hydraulic cylinder and associated components. The orange body of the machine is visible.

Right Front Final Drive	☆☆☆☆	
Right Front Drive Motor	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★☆☆☆ Dripping leak	
Valves	★★☆☆☆ Dripping leak	
Hydraulic Tank	★★★☆☆	
Hoses (Hydraulic)	★★★☆☆	
Steering Cylinders	★★★☆☆	
Boom Lift Cylinder	★★★☆☆	
Boom Extension Cylinder	★★★☆☆	

Basket Tilt Cylinder	★ ★ ★ ☆	
Basket Rotator Motor	★ ★ ★ ☆	
Frame Leveling Cylinders	★ ★ ★ ☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		

Chassis		
Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Brake System	★★★★☆ The brake system functioned, stopping and holding the machine.	

Left Front Tire	Cracks, Flat spots	
Left Rear Tire	Cracks, Tears	
Right Rear Tire	Cracks, Tears	
Right Front Tire	Cracks, Tears	
Wheel Condition	No visible damage or missing components	
Turntable Bearing	★★★★☆	
Swing Motor	★★★★☆	

Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Boom Wear Guides	★★★★☆	
Cable Tray Ladder		
Work Basket		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved