



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14095013 - 2018 Skyjack SJ 66T 4WD Diesel Articulating Boom Lift



Item Details:

- Features: 66 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Onboard Generator, 2017 US EPA Label, Deutz TD2.9L4 4 Cylinder 74 hp Diesel Engine, 385/65D19.5 Foam-Filled Tires
- Meter Reading: 3,475 Hours
- Serial # : 97002982
- Inspection Completed: 10/15/25

Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	97002982	
Hour Meter / Odometer	3475 hrs	
Paint	No visible damage	
Body Panels	Engine compartment door damaged	
Basket / Safety Railing	Front railing bent	
General Appearance #1		
General Appearance #2		
General Appearance #3		

General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	No	


Control Station Ground

Item	Assessment	Photo
Function Controls	☆☆☆☆	
Oil Pressure	Warning light inoperable	
Warning Lights	Inoperable	
Limited Function Check	The main components are in place and operational as noted.	

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	Control area (top) damaged Material buildup	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	★★★★☆ Operational	
Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Emission Label		
Blow-by (subjective visual observation)	Recirculating system	
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Onboard Generator	Not operationally checked	


Engine - Left Side		 A photograph showing the left side of a diesel engine. Various components like the alternator, belts, and hoses are visible. The word "IRON" is partially visible on a component in the lower right.
Engine - Right Side		 A photograph showing the right side of the engine. A large, light-colored air filter or housing is prominent. The word "IRON" is visible on a component in the lower right.
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Final Drive	★★★★☆	
Left Rear Final Drive	★★★★☆	
Right Rear Final Drive	★★★★☆	
Right Front Final Drive	★★★★☆	
Front Center Drive Motor	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		


Drivetrain #2		
Drivetrain #3		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulic)	★★★★☆	
Steering Cylinders	★★★★☆	
Boom Lift Cylinder	★★★★☆	
Boom Extension Cylinder	★★★☆☆ Grinding noise when extending boom	

Jib Cylinder	☆☆☆☆	
Basket Tilt Cylinder	☆☆☆☆	
Basket Rotator Motor	☆☆☆☆	
Limited Function Check	The hydraulic system was operational. Grinding noise when extending boom	

Chassis		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Left Front Tire	Chunks missing	
Left Rear Tire	Chunks missing	
Right Rear Tire	Chunks missing	
Right Front Tire	Chunks missing	

Wheel Condition	No visible damage or missing components	
Turntable Bearing	★★★★☆	
Bottom Covers		
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★☆☆ Grinding noise when extending boom	
Left Side of Boom		

Right Side of Boom		
Boom Wear Guides	★★☆☆ Heavy wear	
Jib Condition	★★★☆☆	
Cable Tray Ladder		
Work Basket	Bent kick rail	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved