



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #13971070 - 2015 JLG 600S 4WD Diesel Telescopic Boom Lift



### Item Details:

- Features: 60 ft Max Platform Height, 1000 lb Max Weight Capacity, Power to Platform, Onboard Generator, 2015 US EPA Label, Deutz TD 2.9 L4 4 Cylinder 67 hp 2.9 L Diesel Engine, 39X15-22.5 Tires
- Meter Reading: 4,846 Hours
- Serial # : 0300207971
- Inspection Completed: 9/3/25

### Shipping Details:

- Location Illinois (Grundy County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

## Inspection Ratings Key

|       |                                                                                   |
|-------|-----------------------------------------------------------------------------------|
| ★★★★  | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆ | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆ | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆ | Needs immediate repair/replacement. Requires work if it is to perform as expected |

## General Appearance

| Item                        | Assessment | Photo                                                                                |
|-----------------------------|------------|--------------------------------------------------------------------------------------|
| Picture, Left Front Corner  |            |   |
| Picture, Left Rear Corner   |            |  |
| Picture, Right Rear Corner  |            |  |
| Picture, Right Front Corner |            |  |

|                         |                                         |                                                                                      |
|-------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Serial Number / VIN     | 0300207971                              |     |
| Hour Meter / Odometer   | 4846 hrs                                |    |
| Paint                   | No visible damage                       |    |
| Body Panels             | No visible damage or missing components |   |
| Steps/Ladders           |                                         |  |
| Basket / Safety Railing | No visible damage or missing components |                                                                                      |
| General Appearance #1   |                                         |  |

| Safety                              |             |                                                                                    |
|-------------------------------------|-------------|------------------------------------------------------------------------------------|
| Item                                | Assessment  | Photo                                                                              |
| Travel Alarm                        | Operational |                                                                                    |
| Horn                                | Operational |                                                                                    |
| Swing Brake                         | Operational |                                                                                    |
| Current Safety Manual               | Yes         |                                                                                    |
| Current Operator/Maintenance Manual | Yes         |                                                                                    |
| ANSI Guidelines                     | Yes         |  |

| Control Station Ground |                                                                    |                                                                                     |
|------------------------|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Item                   | Assessment                                                         | Photo                                                                               |
| Function Controls      | ★★★★☆                                                              |   |
| Oil Pressure           | The fault indicator shuts off after the engine oil pressure rises. |   |
| Warning Lights         | Operational                                                        |  |
| Limited Function Check | The main components are in place and operational as noted.         |                                                                                     |


## Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item                       | Assessment                                                 | Photo                                                                                |
|----------------------------|------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Control Console            | No visible damage or missing components                    |    |
| Emergency Shut Off Switch  | Operational                                                |    |
| Safety Control Foot Switch | ★★★★☆<br>Operational                                       |   |
| Function Controls          | ★★★★☆                                                      |  |
| Engine Warning Lights      | Operational                                                |                                                                                      |
| Limited Function Check     | The main components are in place and operational as noted. |                                                                                      |



| Engine         |                                         |                                                                                      |
|----------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Item           | Assessment                              | Photo                                                                                |
| Emission Label |                                         |    |
| Starter        | Operational                             |                                                                                      |
| Fuel System    | Operational                             |    |
| Exhaust System | No visible damage or missing components |   |
| Radiator       | ★★★★☆                                   |  |
| Oil Leaks      | No dripping leaks                       |  |
| Fuel Leaks     | No dripping leaks                       |  |

|                        |                             |                                                                                      |
|------------------------|-----------------------------|--------------------------------------------------------------------------------------|
| Cooling System Leaks   | No dripping leaks           |     |
| Onboard Generator      | Operational                 |    |
| Engine - Left Side     |                             |    |
| Engine - Right Side    |                             |   |
| Limited Function Check | The engine started and ran. |                                                                                      |
| Engine #1              |                             |  |





## Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

| Item                   | Assessment | Photo                                                                                |
|------------------------|------------|--------------------------------------------------------------------------------------|
| Left Front Final Drive | ★★★★☆      |    |
| Left Front Drive Motor | ★★★★☆      |    |
| Left Rear Final Drive  | ★★★★☆      |   |
| Left Rear Drive Motor  | ★★★★☆      |  |
| Right Rear Final Drive | ★★★★☆      |  |
| Right Rear Drive Motor | ★★★★☆      |  |

|                         |                                 |                                                                                    |
|-------------------------|---------------------------------|------------------------------------------------------------------------------------|
| Right Front Final Drive | ☆☆☆☆                            |   |
| Right Front Drive Motor | ☆☆☆☆                            |  |
| Limited Function Check  | The drivetrain was operational. |                                                                                    |

| Hydraulics               |                              |                                                                                      |
|--------------------------|------------------------------|--------------------------------------------------------------------------------------|
| See photos for condition |                              |                                                                                      |
| Item                     | Assessment                   | Photo                                                                                |
| Pumps (Hydraulics)       | ★★★★☆                        |    |
| Valves                   | ★★★★☆                        |    |
| Hydraulic Tank           | ★★★★☆                        |   |
| Hoses (Hydraulic)        | ★★★★☆                        |  |
| Steering Cylinders       | ★★★★☆                        |  |
| Boom Lift Cylinder       | ★★★☆☆<br>Accumulation fluid. |  |


|                          |                                       |                                                                                      |
|--------------------------|---------------------------------------|--------------------------------------------------------------------------------------|
| Secondary Boom Cylinder  | ★★★★☆                                 |     |
| Boom Extension Cylinder  | ★★★★☆                                 |                                                                                      |
| Basket Tilt Cylinder     | ★★★★☆                                 |    |
| Basket Rotator Motor     | ★★★★☆                                 |    |
| Frame Leveling Cylinders | ★★★★☆                                 |   |
| Limited Function Check   | The hydraulic system was operational. |                                                                                      |
| Hydraulics #1            |                                       |  |
| Hydraulics #2            |                                       |  |



| Chassis          |                                                                         |                                                                                      |
|------------------|-------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Item             | Assessment                                                              | Photo                                                                                |
| Steering Linkage | ★★★★☆                                                                   |    |
| Frame Condition  | ★★★★☆                                                                   |    |
| Brake System     | ★★★★☆<br>The brake system functioned, stopping and holding the machine. |   |
| Left Front Tire  | No visible defects                                                      |  |
| Left Rear Tire   | No visible defects                                                      |  |
| Right Rear Tire  | No visible defects                                                      |  |



|                         |                                         |                                                                                      |
|-------------------------|-----------------------------------------|--------------------------------------------------------------------------------------|
| Right Front Tire        | No visible defects                      |     |
| Wheel Condition         | No visible damage or missing components |    |
| Turntable Bearing       | ★★★★☆                                   |    |
| Bottom Covers           |                                         |   |
| Swing Motor             | ★★★★☆                                   |  |
| Hydraulic Center Swivel | ★★★★☆                                   |  |
| Boom Condition          | ★★★★☆                                   |  |

|                    |       |                                                                                                                                                                                                                                                                                   |
|--------------------|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Left Side of Boom  |       |  A photograph showing the left side of the telescopic boom, which is yellow and orange. The boom is extended upwards and to the right. The background shows a gravel lot with other equipment.   |
| Right Side of Boom |       |  A photograph showing the right side of the telescopic boom, which is yellow and orange. The boom is extended upwards and to the right. The background shows a gravel lot with other equipment. |
| Boom Wear Guides   | ★★★★☆ |  A close-up photograph of the boom wear guides, which are yellow and orange. The guides are mounted on the boom and are used to guide the cables.                                               |
| Cable Tray Ladder  |       |  A photograph showing the cable tray ladder, which is yellow and orange. The ladder is mounted on the boom and is used to hold the cables.                                                     |
| Work Basket        |       |  A photograph showing the work basket, which is orange. The basket is mounted on the boom and is used for lifting workers.                                                                    |
| Chassis #1         |       |  A close-up photograph of the chassis, which is orange. The chassis is the base of the lift and is used to support the boom and basket.                                                       |
| Chassis #2         |       |  A photograph showing the chassis, which is orange. The chassis is the base of the lift and is used to support the boom and basket.                                                           |

**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet , Inc. © 2012 All Rights Reserved