



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14251149 - 2007 Genie S-65 4WD Diesel Telescopic Boom Lift



Item Details:

- Features: 65 ft Max Platform Height, 500 lb Max Weight Capacity, Jib, Power to Platform, Onboard Generator, 2007 US EPA Label, Deutz D2011L03I 3 Cylinder 36.3 kW 2.33 L Diesel Engine, 355/55D625 Foam-Filled Tires
- Meter Reading: 9,260 Hours
- Serial # : S6007-15738
- Inspection Completed: 12/9/25

Shipping Details:

- Location Illinois (Grundy County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	S6007-15738	
Hour Meter / Odometer	9260 hrs	
Paint	Other unknown material	
Body Panels	Engine compartment door damaged, Hydraulic compartment door heavy rust / corrosion	
Basket / Safety Railing	Front railing damaged	
General Appearance #1		
General Appearance #2		
General Appearance #3		

General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		
General Appearance #10		

General Appearance #11




Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Swing Brake	Operational	
ANSI Guidelines	Froze shut	
Safety #1		

Control Station Ground		
Item	Assessment	Photo
Function Controls	☆☆☆☆	
Oil Pressure	Warning light inoperable	
Warning Lights	Inoperable	
Limited Function Check	The main components are in place and operational as noted.	

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Control Console	Material buildup	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	☆☆☆☆ Operational	
Function Controls	☆☆☆☆	
Engine Warning Lights	Inop lights	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Emission Label		
Blow-by (subjective visual observation)	Too small	
Starter	Operational	
Fuel System	Operational	
Exhaust System	No visible damage or missing components	
Oil Leaks	Rear of engine	
Onboard Generator	Not operationally checked	
Engine - Left Side		

Engine - Right Side		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		

Drivetrain


Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Front Drive Motor	★★★★☆	
Left Rear Drive Motor	★★★★☆	
Right Rear Drive Motor	★★★★☆	
Right Front Drive Motor	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulic)	★★★★☆	
Steering Cylinders	★★★★☆	
Boom Lift Cylinder	★★★★☆	

Secondary Boom Cylinder	★★★★☆	
Boom Extension Cylinder	★★★★☆	
Jib Cylinder	★★★★☆	
Basket Tilt Cylinder	★★★★☆	
Basket Rotator Motor	★★★☆☆ Dripping leak	
Frame Leveling Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Chassis		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Left Front Tire	Cracks, Chunks missing, Tears	
Left Rear Tire	Cracks, Chunks missing, Tears	
Right Rear Tire	Cracks, Chunks missing, Tears	
Right Front Tire	Cracks, Chunks missing, Tears	
Wheel Condition	No visible damage or missing components	

Turntable Bearing	★★★★☆	
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Boom Wear Guides	★★★★☆	

Jib Condition	★★★★☆	
Cable Tray Ladder		
Work Basket		
Chassis #1		
Chassis #2		
Chassis #3		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved