



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14005021 - 2016 JLG 1255 Telehandler



Item Details:

- Features: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 12000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 96 in Forks, Manual Coupler, Outriggers, Frame Leveling, Auxiliary Hydraulic Plumbing
- Meter Reading: 5,785 Hours
- Serial #: 0160073668
- Inspection Completed: 9/16/25

Shipping Details:

- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report


Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance


Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0160073668	 A close-up photograph of a JLG serial number plate. The plate is white with black text and features the JLG logo. It includes fields for Model, Serial Number, and Year of Manufacture. The serial number U920370 is clearly visible. The plate is mounted on a dark surface, and an 'IRON PLANET' logo is visible in the bottom right corner.
CE Mark	No CE mark found	
Paint	Damage	 A close-up photograph showing significant paint damage on the side of the telehandler. The paint is chipped and peeling, revealing the underlying metal. The 'IRON PLANET' logo is visible on the side panel.
Body Panels	No visible damage or missing components	
Fenders	No visible damage or missing components.	 A close-up photograph of the front fender and tire of the telehandler. The fender is black and shows some wear. The tire is large and appears to be in good condition. The 'IRON PLANET' logo is visible on the fender.
Exterior Lights	All lights operational	 A close-up photograph of the front exterior lights of the telehandler. The lights are orange and appear to be in good condition. The 'IRON PLANET' logo is visible on the side panel.
General Appearance #1		 A close-up photograph of the rear of the telehandler. The rear panel is black and shows some wear. The JLG logo is visible on the side. The 'IRON PLANET' logo is visible on the side panel.
General Appearance #2		 A close-up photograph of the rear of the telehandler. The rear panel is black and shows some wear. The JLG logo is visible on the side. The 'IRON PLANET' logo is visible on the side panel.

General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		

General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		


Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		

Cab Door	No visible damage or missing components	
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Load Charts	Chart book in cab	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	

Hour Meter / Odometer	5785 hrs	
Air Conditioner	Operational	
Heater	Not operationally checked	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	No US EPA Label Present Requires Diesel Exhaust Fluid	
v2 Engine # 1		
A/C Compressor	Operational	
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	

Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	

Final Drives	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked	
Boom Lift Cylinder(s)	★★★★☆	

Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Outrigger Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		

Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.


Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Chassis #8		
Boom Condition	★★★★☆	
Chain / Tensioners	★★★★☆	
Rollers and Guides	★★★★☆	
Boom Wear Guides	★★★★☆	
Outriggers	★★★★☆	

Telehandler*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 400/75-28 Brand: Lightning Tread Depth: 23/32	

Left Rear Tire	Size: 400/75-28 Brand: Firestone Model: Duraforce Tread Depth: 26/32	
Right Rear Tire	Size: 400/75-28 Brand: Firestone Model: Duraforce Tread Depth: 26/32	
Right Front Tire	Size: 400/75-28 Brand: Lightning Tread Depth: 23/32	
Wheel Condition	No visible damage or missing components	
Telehandler* #1		
Telehandler* #2		
Telehandler* #3		

Telehandler* #4		
Telehandler* #5		
Telehandler* #6		
Telehandler* #7		
Telehandler* #8		
Telehandler* #9		
Loader Quick Coupler	★★★★☆ Not operationally checked	

Load Back Rest	☆☆☆☆	
Forks	☆☆☆☆	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved