



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13811325 - 2016 JLG 1055 Telehandler



Item Details:

- Features: Enclosed Cab, Air Conditioner, 55 ft Max Lift Height, 10000 lb Max Lift Capacity, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling
- Meter Reading: 7,520 Hours
- Serial # : 0160075715
- Inspection Completed: 9/5/25

Shipping Details:

- Location Quebec
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance


Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0160075715	
Paint	Damage	
Body Panels	No visible damage or missing components	
Fenders	No visible damage or missing components.	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
General Appearance #1		


General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		

General Appearance #9



Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
Safety #1		 A photograph of the front cover of a JLG Operation & Safety Manual. The cover is white with black text. It features the JLG logo at the top left and bottom right. The title 'Operation & Safety Manual' is centered. Below the title, it lists 'Models 642, 742, 943, 1043, 1055, 1255'. At the bottom left, it says 'ANSI'. At the bottom right, there is a small 'IRON PLANET' logo.
Safety #2		 A photograph of a page from the JLG Operation & Safety Manual, showing two 'WARNING' sections. Each section has a black triangle icon with an exclamation mark followed by the word 'WARNING' in bold. The text below each warning is in a smaller font. The page is white with black text. The JLG logo is visible at the bottom right, and a small 'IRON PLANET' logo is at the bottom right corner of the photo.

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		

Control Station #7		
Control Station #8		
Seat/Armrests	Operator seat cushion damaged	
Glass	No visible damage or missing components	
Mirrors		
Cab Door	Door seal damaged	
Steering Control	★★☆☆ Signs of use and minor damages	

Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Load Charts	Chart book in cab	
Engine Oil Pressure	The gauge registers in the operating range.	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter / Odometer	7520 hrs	
Air Conditioner	Operational	

Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	No US EPA Label Present	
v2 Engine # 1		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		


DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★☆☆ Operational, Dripping leak, Leaking from the sensor seal	
Front Drive Axle	★★★☆	
Front Axle Oscillating Pin	★★★☆	
Rear Drive Axle	★★★☆	
Rear Axle Oscillating Pin	★★★☆	
Final Drives	★★★☆	
Limited Function Check	The drivetrain was operational.	

Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★☆☆ Some are dry and cracked	
Boom Lift Cylinder(s)	★★★★☆	
Telescopic Boom Cylinders	★★★★☆	

Carriage Tilt Cylinder	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Outrigger Cylinders	★★★★☆	
Steering Cylinders	★★★☆☆ Dripping leak on the left cylinder, Front left cylinder seems to be leaking	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		

Hydraulics #4		
Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		
Hydraulics #9		
Hydraulics #10		

Hydraulics #11		
Hydraulics #12		
Hydraulics #13		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	★★★★☆	
Rollers and Guides	★★★★☆	
Boom Wear Guides	★★★★☆	

Outriggers	☆☆☆☆	
------------	------	---

Telehandler*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Brake Control	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 400/75-28 Brand: Firestone Model: DuraForce MH Tread Depth: 5/32	
Left Rear Tire	Size: 400/75-28 Brand: Firestone Model: DuraForce MH Tread Depth: 12/32	

Right Rear Tire	Size: 400/75-28 Brand: Firestone Model: DuraForce MH Tread Depth: 14/32	
Right Front Tire	Size: 400/75-28 Brand: Firestone Model: DuraForce MH Tread Depth: 6/32	
Wheel Condition	No visible damage or missing components	
Telehandler* #1		
Telehandler* #2		
Telehandler* #3		
Telehandler* #4		

Telehandler* #5		
Telehandler* #6		
Telehandler* #7		
Load Back Rest	☆☆☆☆	
Forks	☆☆☆☆	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved