



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13869134 - 2017 Genie GTH-844 Telehandler



Item Details:

- Features: Open Operator Station, 43 ft 10 in Max Lift Height, 8000 lb Max Lift Capacity, 2016 US EPA Label, 60 in Forks, Tilt Carriage
- Meter Reading: 2,222 Hours
- Serial # : GTH08E-10766
- Inspection Completed: 8/27/25

Shipping Details:

- Location California (Riverside County)
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report


Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	GTH08E-10766	
Paint	Damage	
Body Panels	No visible damage or missing components	
Fenders	No visible damage or missing components.	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
General Appearance #1		

General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		

Control Station #7		
Control Station #8		
Seat/Armrests	No visible damage or missing components	
Mirrors		
Steering Control	★★★★☆ Heavy steering wheel play	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	

Load Charts	Posted on cab wall	
Engine Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter / Odometer	2222 hrs, Meter inoperable, Hour meter did not change/Hard to Read	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	2016 US EPA Label	
Emission Label		
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Drive Motors	★★☆☆	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	
Final Drives	★★☆☆	
Limited Function Check	The drivetrain was operational.	

Drivetrain #1		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.
Drivetrain #2		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.
Drivetrain #3		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.
Drivetrain #4		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.
Drivetrain #5		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.
Drivetrain #6		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.
Drivetrain #7		 A close-up photograph of a tire and wheel assembly. The tire is black with a tread pattern. The wheel is silver. An "IRON PLANET" watermark is visible in the bottom right corner.

Drivetrain #8



Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked	
Boom Lift Cylinder(s)	★★★★☆	

Telescopic Boom Cylinders	★★★★☆	
Side Shift Cylinder	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	
Fork Positioning Cylinder (on fork carriage)	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		

Hydraulics #2



Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Chassis #1		
Boom Condition	☆☆☆☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	☆☆☆☆	
Rollers and Guides	☆☆☆☆	

Boom Wear Guides



Telehandler*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 330/85-28 Brand: Extremelift Model: EXL-T1 Tread Depth: 31/32	

Left Rear Tire	Size: 330/85-28 Brand: Extremelift Model: ETH-1 Tread Depth: 31/32	
Right Rear Tire	Size: 330/85-28 Brand: Extremelift Model: EXL-T1 Tread Depth: 31/32	
Right Front Tire	Size: 330/85-28 Brand: Extreme lift Model: EXL-T1 Tread Depth: 31/32	
Wheel Condition	No visible damage or missing components	
Telehandler* #1		
Telehandler* #2		
Load Back Rest	★★★★☆	

Forks	☆☆☆☆	
-------	------	---

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved