



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13869098 - 2019 Skyjack SJ1256THS Telehandler



Item Details:

- Features: Enclosed Cab, Air Conditioner, 56 ft Max Lift Height, 12000 lb Max Lift Capacity, 2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Positive Air Shutoff, 60 in Forks, Manual Coupler, Outriggers, Frame Leveling
- Meter Reading: 7,522 Hours
- Serial # : 87410396
- Inspection Completed: 9/23/25

Shipping Details:

- Location Alberta
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Buyer MUST Call 48 Hours in Advance of Pickup, Buyer MUST Self Load

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	87410396, The serial number is not legible. This unit may be difficult to export. Tag damaged	
Paint	Damage	
Body Panels	Engine cover damaged, Grille damaged	
Fenders	Right rear damaged, Right rear fender bent	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
General Appearance #1		

General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		

General Appearance #9		
General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		
General Appearance #14		
General Appearance #15		

General Appearance #16		
General Appearance #17		
General Appearance #18		
General Appearance #19		
General Appearance #20		
General Appearance #21		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	

Control Station		
Item	Assessment	Photo
Seat/Armrests	Operator seat cushion damaged	
Glass	No visible damage or missing components	
Mirrors		
Cab Door	Door frame damaged Door seal damaged	
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	☆☆☆☆	
Load Charts	Chart book in cab	
Engine Oil Pressure	The gauge registers in the operating range.	
Gauges	Operational	
Hour Meter / Odometer	7522 hrs	
Air Conditioner	Inoperable	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		

Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		
Control Station #7		
Control Station #8		

Control Station #9		
Control Station #10		
Control Station #11		
Control Station #12		

Engine		
Item	Assessment	Photo
Engine	2019 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid	
Emission Label		
A/C Compressor	Compressor missing	
Blow-by (subjective visual observation)	Visible	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	

Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		
Engine #3		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	

Final Drives	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Telescopic Boom Cylinders	★★★★☆	

Carriage Tilt Cylinder	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Outrigger Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		

Hydraulics #4		 A close-up photograph of the hydraulic pump assembly on a telehandler. It shows a red pump housing, various hoses, and electrical connections. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #5		 A photograph showing a hydraulic cylinder and associated valve components. The cylinder is dark and shows some wear. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #6		 A photograph of a hydraulic cylinder with a hose attached. The cylinder is dark and shows signs of use. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #7		 A photograph showing a hydraulic cylinder and hose assembly. The cylinder is dark and shows some wear. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #8		 A photograph of a hydraulic cylinder and hose assembly. The cylinder is dark and shows signs of use. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #9		 A photograph showing a hydraulic cylinder and hose assembly. The cylinder is dark and shows some wear. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #10		 A photograph of a hydraulic cylinder and hose assembly. The cylinder is dark and shows signs of use. An "IRON PLANET" watermark is visible in the bottom right corner.

Hydraulics #11		
Hydraulics #12		
Hydraulics #13		
Hydraulics #14		
Hydraulics #15		
Hydraulics #16		
Hydraulics #17		

Hydraulics #18		 A close-up photograph of a hydraulic cylinder and its mounting arm on a telehandler. The cylinder is dark grey and shows signs of wear. The background is a sandy, outdoor environment. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #19		 A close-up photograph of a hydraulic cylinder and its mounting arm, similar to the previous image. The cylinder is dark grey and shows signs of wear. The background is a sandy, outdoor environment. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #20		 A close-up photograph of a hydraulic cylinder and its mounting arm, similar to the previous images. The cylinder is dark grey and shows signs of wear. The background is a sandy, outdoor environment. An "IRON PLANET" watermark is visible in the bottom right corner.
Hydraulics #21		 A close-up photograph of a hydraulic cylinder and its mounting arm, similar to the previous images. The cylinder is dark grey and shows signs of wear. The background is a sandy, outdoor environment. An "IRON PLANET" watermark is visible in the bottom right corner.

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Boom Condition	★★★★☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	★★★★☆	
Rollers and Guides	★★★★☆	
Boom Wear Guides	★★★★☆	

Outriggers	★★★☆☆ Dirt pads	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		

Telehandler*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 14.00-24 Brand: SolidBoss Tread Depth: 23/32	
Left Rear Tire	Size: " Brand: " Tread Depth: 20/32	

Right Rear Tire	Size: " Brand: " Tread Depth: 17/32	
Right Front Tire	Size: " Brand: " Tread Depth: 19/32	
Wheel Condition	No visible damage or missing components	
Load Back Rest	★★★★☆ Top bars bent	
Forks	★★★★☆	
Telehandler* #1		
Telehandler* #2		

Telehandler* #3		
Telehandler* #4		
Telehandler* #5		
Telehandler* #6		
Telehandler* #7		
Telehandler* #8		
Telehandler* #9		

Telehandler* #10		
Telehandler* #11		
Telehandler* #12		
Telehandler* #13		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved