



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #14577210 - 2015 Skyjack SJ6832 RT Dual Fuel 4x4 Scissor Lift



### Item Details:

- Features: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Foam Filled Tires, Upper Control Box, 2015 US EPA Label, Kubota WH972-GL-ET 3 Cylinder Gasoline Engine
- Meter Reading: 2,221 Hours
- Serial # : 37007013
- Inspection Completed: 1/12/26

### Shipping Details:





- Location Missouri (Kansas City, MO-KS area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Buyer MUST Call 48 Hours in Advance of Pickup, Buyer MUST Self Load



 Protected by IronClad Assurance



# Inspection Report


**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.






| Inspection Ratings Key |   |
|------------------------|---|
| ★★★★                   | Limited use or recently replaced. Free of visible wear or defects.                |
| ★★★☆☆                  | Performs within the tolerances expected for age and type of item                  |
| ★★☆☆☆                  | Although performing, shows indication of needing repair or replacement            |
| ★☆☆☆☆                  | Needs immediate repair/replacement. Requires work if it is to perform as expected |






| General Appearance          |            |  |
|-----------------------------|------------|--|
| Item                        | Assessment | Photo  |
| Picture, Left Front Corner  |            |   |
| Picture, Left Rear Corner   |            |  |
| Picture, Right Rear Corner  |            |  |
| Picture, Right Front Corner |            |  |


|                         |   |   |
|-------------------------|---|---|
| Serial Number / VIN     | 37007013                                |    |
| CE Mark                 | No CE mark found                        |   |
| Hour Meter / Odometer   | 2221 hrs                                |   |
| Paint                   | No visible damage                       |   |
| Body Panels             | Engine compartment door damaged         |   |
| Steps/Ladders           |   |  |
| Basket / Safety Railing | No visible damage or missing components |   |





| <b>Safety</b>                       |                   |  |
|-------------------------------------|-------------------|--|
| <b>Item</b>                         | <b>Assessment</b> | <b>Photo</b>   |
| Travel Alarm                        | Inoperable        |  |
| Horn                                | Operational       |  |
| Current Safety Manual               | Yes               |  |
| Current Operator/Maintenance Manual | Yes               |  |
| ANSI Guidelines                     | Yes               |  |
| Safety #1                           |                   |  |

| <b>Control Station Ground</b> |  |  |
|-------------------------------|--|--|
| <b>Item</b>                   | <b>Assessment</b>  | <b>Photo</b>   |
| Function Controls             | ★ ★ ★ ☆  |  |
| Limited Function Check        | The main components are in place and operational as noted. |  |




| <b>Control Station Upper</b>  |  |  |
|---|--|--|
| Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed. |  |  |
| <b>Item</b>   | <b>Assessment</b>  | <b>Photo</b>   |
| Control Console   | No visible damage or missing components                    |    |
| Emergency Shut Off Switch   | Operational  |    |
| Safety Control Hand/Foot Switch   | ★★★★☆<br>Operational                                       |   |
| Upper Function Controls   | ★★★★☆  |  |
| Limited Function Check  | The main components are in place and operational as noted. |  |
| Control Station Upper #1  |  |  |







| <b>Engine</b>        |   |  |
|----------------------|---|--|
| <b>Item</b>          | <b>Assessment</b>                       | <b>Photo</b>   |
| Emissions Status     | 2015 US EPA Label                       |  |
| Emission Label       |   |    |
| Starter              | Operational                             |  |
| Fuel System          | Operational                             |    |
| Exhaust System       | No visible damage or missing components |   |
| Radiator             | ★★★★☆                                   |  |
| Oil Leaks            | No dripping leaks                       |  |
| Fuel Leaks           | No dripping leaks                       |  |
| Cooling System Leaks | No dripping leaks                       |  |
| Engine - Left Side   |   |  |







|                        |   |   |
|------------------------|---|---|
| Engine - Right Side    |   |  |
| Limited Function Check | After jump starting, the engine ran. The engine would not re-start after shutting down without jump starting. |   |

| <b>Drivetrain</b>  |                                 |  |
|--|---------------------------------|--|
| Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage. |                                 |  |
| <b>Item</b>  | <b>Assessment</b>               | <b>Photo</b>   |
| Drive Motors   | ★★★☆☆                           |    |
| Limited Function Check   | The drivetrain was operational. |  |
| Drivetrain #1  |                                 |    |
| Drivetrain #2  |                                 |   |
| Drivetrain #3  |                                 |  |


| Hydraulics         |            |  |
|--------------------|------------|--|
| Item               | Assessment | Photo  |
| Pumps (Hydraulics) | ★★★★☆      |    |
| Valves             | ★★★★☆      |    |
| Hydraulic Tank     | ★★★★☆      |   |
| Hoses              |            |  |
| Lift Cylinders     | ★★★★☆      |  |
| Steering Cylinder  | ★★★★☆      |  |

|                        |                                       |  |
|------------------------|---------------------------------------|--|
| Outrigger Cylinders    | ☆☆☆☆                                  |   |
| Limited Function Check | The hydraulic system was operational. |  |
| Hydraulics #1          |                                       |  |
| Hydraulics #2          |                                       |  |

| Chassis  |  |  |
|--|--|--|
| IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed. |  |  |
| Item   | Assessment   | Photo  |
| Brake System   | ★★☆☆<br>The brake system functioned, stopping and holding the machine. |    |
| Steering Linkage   | ★★☆☆   |    |
| Frame Condition  | ★★☆☆   |   |
| Scissor Linkage  | ★★☆☆   |  |
| Platform Condition   | ★★☆☆   |  |
| Platform Extension   | ★★☆☆<br>Metal damage.  |  |

|                                       |  |  |
|---------------------------------------|--|--|
| Left Front Tire                       | Cracks, Chunks missing                                     |     |
| Left Rear Tire                        | Cracks, Chunks missing                                     |    |
| Right Rear Tire                       | Cracks, Chunks missing                                     |    |
| Right Front Tire                      | Cracks, Chunks missing                                     |   |
| Wheel Condition                       | No visible damage or missing components                    |  |
| Wheel Studs                           | ★★★★☆  |  |
| Outriggers / Stabilizers              | ★★★★☆  |  |
| Limited Function Check (Scissor-lift) | The main components appear to be in place and operational. |  |
| Chassis #1                            |  |  |

Chassis #2



**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet, Inc. © 2012 All Rights Reserved