



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14577193 - 2016 Skyjack SJ6832 RTE Electric 4x4 Scissor Lift



Item Details:

- Features: 32 ft Max Platform Height, 1000 lb Max Weight Capacity, Platform Extension, Power to Platform, Stabilizers, Foam Filled Tires, Upper Control Box
- Meter Reading: 221 Hours
- Serial # : 37300125
- Inspection Completed: 1/16/26

Shipping Details:





- Location Connecticut (New London-Norwich, CT-RI area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup







 Protected by IronClad Assurance


Inspection Report


Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.




Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	37300125	
CE Mark	No CE mark found	
Hour Meter / Odometer	221 hrs	
Paint	Concrete residue	
Body Panels	Battery compartment door damaged, Hydraulic compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	No visible damage or missing components	
General Appearance #1		


General Appearance #2		
General Appearance #3		
General Appearance #4		





Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	





Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Ground #1		







Control Station Upper






Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.







Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	★★☆☆ Operational	
Upper Function Controls	★★☆☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		







Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	48 Volts	
Battery Condition	Functioned during the inspection, Weak or under-charged, Unit was charged at one point to finish inspection	
Cables and Connections	No visible damage or missing components	 A photograph showing a battery bank consisting of several large black battery units mounted on a metal frame. The batteries are connected with various cables and terminals. An "IRON PLANET" watermark is visible in the bottom right corner.
Battery Charger	Included 120 Volt, Single Phase	 A photograph of a white battery charger unit mounted on a metal structure. It has various cables connected to it and a control panel with a red emergency stop button. An "IRON PLANET" watermark is visible in the bottom right corner.
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		 A photograph showing a complex arrangement of electrical wires, some bundled together, and components within an electrical compartment. There are red and blue wires, and some components are partially obscured. An "IRON PLANET" watermark is visible in the bottom right corner.
Electrical Operating System #2		 A close-up photograph of a charging port on a metal surface. The port is a circular opening with a protective cap. Next to it is a label that reads "CHARGER PLUG" and another label below it that says "ALWAYS PLUG IN CHARGER" and "SIEMPRE". An "IRON PLANET" watermark is visible in the bottom right corner.

Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Drive Motors	★★★☆☆	
Front Drive Axle	★★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	

Outrigger Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine.	
Steering Linkage	★★☆☆	
Frame Condition	★★☆☆	
Scissor Linkage	★★☆☆	
Platform Condition	★★☆☆	
Platform Extension	★☆☆☆☆ Would not slide	
Left Front Tire	Chunks missing, Tears	

Left Rear Tire	Chunks missing, Tears	
Right Rear Tire	Chunks missing, Tears	
Right Front Tire	Chunks missing, Tears	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Outriggers / Stabilizers	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		
Chassis #2		

Chassis #3		 A photograph showing the exterior of the scissor lift chassis. The chassis is primarily grey with orange safety components. It features a steering wheel, a seat, and various control levers. The lift is parked on a paved surface. An "IRON PLANET" logo is visible in the bottom right corner of the image.
Chassis #4		 A photograph showing the interior of the scissor lift chassis. The floor is covered with a brown, textured mat. The chassis is painted orange. A black hose is visible on the left side. A green and yellow logo is partially visible in the bottom right corner.

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved