



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #14786806 - 2017 JLG 8042 Telehandler



### Item Details:

- Features: Open Operator Station, 29 ft 6 in Max Lift Height, 8000 lb Max Lift Capacity, 48 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing
- Meter Reading: 1,938 Hours
- Serial # : 160082853
- Inspection Completed: 2/23/26

### Shipping Details:





- Location California (Yolo County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup








 Protected by IronClad Assurance





# Inspection Report





**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.







Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected






General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		







Serial Number / VIN	160082853	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
General Appearance #1		



General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		

<b>Safety</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
Safety #1		
Safety #2		
Safety #3		

Control Station		
Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Mirrors		
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Transmission Disconnect Control	★★★★☆	







Load Charts	Chart book in cab	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter / Odometer	1938 hrs	
Air Conditioner	Operational	
Limited Function Check	The main components are in place and operational as noted.	






<b>Engine</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Engine	No US EPA Label Present	
v2 Engine # 1		
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	







Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	






## Drivetrain




Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.







Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	




Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		
Drivetrain #4		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Front	
Boom Lift Cylinder(s)	★★★★☆	
Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	

Frame Leveling Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		





Hydraulics #6		
Hydraulics #7		
Hydraulics #8		

<b>Chassis</b>		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Chassis #1		
Chassis #2		
Chassis #3		
Boom Condition	☆☆☆☆	
Left Side of Boom		
Right Side of Boom		

Chain / Tensioners	☆☆☆☆	
Rollers and Guides		
Boom Wear Guides	☆☆☆☆	

<b>Telehandler*</b>		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 370/75-28 Brand: Firestone Model: DualForce Tread Depth: 21/32	

Left Rear Tire	Size: 370/75-28 Brand: Firestone Model: Dual Force Tread Depth: 19/32	
Right Rear Tire	Size: 370/75-28 Brand: Firestone Model: Dual Force Tread Depth: 13/32	
Right Front Tire	Size: 370/75-28 Brand: Firestone Model: Dual Force Tread Depth: 21/32	
Wheel Condition	No visible damage or missing components	
Telehandler* #1		
Telehandler* #2		
Telehandler* #3		

Telehandler* #4		
Telehandler* #5		
Telehandler* #6		
Telehandler* #7		
Telehandler* #8		
Loader Quick Coupler	★★★★☆ Operational	
Load Back Rest	★★★★☆	

Forks



**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet, Inc. © 2012 All Rights Reserved