



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14786807 - 2017 SkyTrak 8042 Telehandler



Item Details:

- Features: Open Operator Station, 42 ft 4 in Max Lift Height, 8000 lb Max Lift Capacity, 2017 US EPA Label, 72 in Forks, Tilt Carriage, Manual Coupler, Frame Leveling, Auxiliary Hydraulic Plumbing
- Meter Reading: 2,324 Hours
- Serial # : 160082426
- Inspection Completed: 2/26/26

Shipping Details:





- Location California (Yolo County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup








 Protected by IronClad Assurance

Inspection Report



Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.







Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		






<p>Serial Number / VIN</p>	<p>160082426</p>	
<p>Paint</p>	<p>No visible damage</p>	
<p>Body Panels</p>	<p>No visible damage or missing components</p>	
<p>Steps</p>	<p>No visible damage or missing components</p>	
<p>Hand Rails</p>	<p>No visible damage or missing components</p>	
<p>Exterior Lights</p>	<p>All lights operational</p>	
<p>General Appearance #1</p>		







General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		





Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	
Safety #1		







Control Station		
Item	Assessment	Photo
Control Station #1		
Seat/Armrests	No visible damage or missing components	
Mirrors		
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	

<p>Transmission Disconnect Control</p>	<p>★★★★☆</p>	
<p>Load Charts</p>	<p>Posted on cab wall</p>	
<p>Engine Oil Pressure</p>	<p>The fault indicator shuts off after the engine oil pressure rises.</p>	
<p>Warning Lights</p>	<p>Operational</p>	
<p>Gauges</p>	<p>Operational</p>	
<p>Hour Meter / Odometer</p>	<p>2324 hrs</p>	
<p>Limited Function Check</p>	<p>The main components are in place and operational as noted.</p>	







Engine		
Item	Assessment	Photo
Engine	2017 Unable to locate label US EPA Label	
Emission Label		
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	

<h2>Drivetrain</h2>		
<p>Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.</p>		
Item	Assessment	Photo
Transmission	<p>★★★★☆ Operational</p>	
Transfer Case / Drop Box	<p>★★★★☆ Operational</p>	
Drive Motors	<p>★★★★☆</p>	
Front Drive Axle	<p>★★★★☆</p>	
Front Axle Oscillating Pin	<p>★★★★☆</p>	
Rear Drive Axle	<p>★★★★☆</p>	
Rear Axle Oscillating Pin	<p>★★★★☆</p>	

Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		






Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Front	
Boom Lift Cylinder(s)	★★★★☆	
Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	








Frame Leveling Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		







Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Chassis #1		
Boom Condition	☆☆☆☆	
Left Side of Boom		
Right Side of Boom		
Chain / Tensioners	☆☆☆☆	
Rollers and Guides	☆☆☆☆	

Boom Wear Guides



Telehandler*		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 370/75-28 Brand: Firestone Tread Depth: 25/32	

<p>Left Rear Tire</p>	<p>Size: 370/75-28 Brand: Firestone Tread Depth: 25/32</p>	
<p>Right Rear Tire</p>	<p>Size: 370/75-28 Brand: Firestone Tread Depth: 25/32</p>	
<p>Right Front Tire</p>	<p>Size: 370/75-28 Brand: Firestone Tread Depth: 25/32</p>	
<p>Wheel Condition</p>	<p>No visible damage or missing components</p>	
<p>Telehandler* #1</p>		
<p>Telehandler* #2</p>		
<p>Telehandler* #3</p>		

Telehandler* #4		
Telehandler* #5		
Telehandler* #6		
Loader Quick Coupler	★★★★☆ Operational	
Load Back Rest	★★★★☆	
Forks	★★★★☆	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved