



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #14786824 - 2019 JLG 4045R Electric Scissor Lift



### Item Details:

- Features: 29 ft Max Platform Height, 550 lb Max Weight Capacity, Platform Extension, Power to Platform, Solid Non-Marking Tires, Upper Control Box
- Meter Reading: 329 Hours
- Serial # : 0200269368
- Inspection Completed: 2/24/26

### Shipping Details:





- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.






 Protected by IronClad Assurance

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	0200269368	
CE Mark	No CE mark found	
Hour Meter / Odometer	329 hrs	
Paint	Other unknown material	
Body Panels	Battery compartment door damaged, Hydraulic compartment door damaged	
Steps/Ladders		
Basket / Safety Railing	Right railing bent	
General Appearance #1		





General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		



<b>Safety</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	No	





<b>Control Station Ground</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Function Controls	★ ★ ★ ☆	
Limited Function Check	The main components are in place and operational as noted.	







### Control Station Upper



Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.






Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		







<b>Electrical Operating System</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Operating Voltage	24 Volts	
Battery Condition	Functioned during the inspection	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included Appears normal - Not operationally checked, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	








<b>Drivetrain</b>		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Drive Motors	★ ★ ★ ☆	
Final Drives	★ ★ ★ ☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		

<b>Chassis</b>		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine., Could not get pictures of braking system	
Steering Linkage	★★☆☆	
Frame Condition	★★☆☆	
Scissor Linkage	★★☆☆	
Platform Condition	★★☆☆	
Platform Extension	★★☆☆	

Left Front Tire	Cracks, Chunks missing	
Left Rear Tire	Cracks, Chunks missing	
Right Rear Tire	Cracks, Chunks missing	
Right Front Tire	Cracks, Chunks missing	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Pothole Protection Bars	★★★★☆ Functional	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	

Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		

**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet, Inc. © 2012 All Rights Reserved