



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #14786825 - 2019 JLG 4069LE Electric Scissor Lift



### Item Details:

- Features: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box
- Meter Reading: 219 Hours
- Serial # : M200033717
- Inspection Completed: 3/24/26

### Shipping Details:




- Location Texas (Harris County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

 Protected by IronClad Assurance





# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected





General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		




<p>Serial Number / VIN</p>	<p>M200033717</p>	 <p>A close-up photograph of the machine's identification plate. The plate is black with white text and fields. It includes the following information: MODEL (partially obscured), SERIAL NO. M200033717, NOM. BATT. VOLTAGE 48V, MODEL YEAR 2019, MACHINE WEIGHT 1500 LB, and PLATFORM HEIGHT 6'6". Below the plate is a green 'IMPORTANT' sticker with the code ICES-001. The JLG logo is visible in the bottom right corner.</p>
<p>Hour Meter / Odometer</p>	<p>219 hrs</p>	 <p>A close-up photograph of the hour meter display. The display is a small rectangular window with a black background and white text, showing the number '219'. The display is mounted on a metal panel with various warning symbols and the JLG logo.</p>
<p>Paint</p>	<p>No visible damage</p>	 <p>A photograph showing the exterior of the scissor lift. The machine is primarily orange and yellow. The platform is raised, and the scissor mechanism is visible. The JLG logo is prominently displayed on the side of the platform.</p>
<p>Body Panels</p>	<p>Battery compartment door damaged, Hydraulic compartment door damaged</p>	 <p>A close-up photograph of the battery compartment door, which is orange. The door shows signs of damage, including a missing section and a jagged edge. The JLG logo is visible on the door.</p>
<p>Steps/Ladders</p>		 <p>A close-up photograph of the scissor lift's steps and ladders. The steps are yellow with orange handrails. The ladders are also yellow with orange handrails. The JLG logo is visible on the side of the steps.</p>
<p>Basket / Safety Railing</p>	<p>No visible damage or missing components</p>	
<p>General Appearance #1</p>		 <p>A close-up photograph of the machine's interior panel. The panel is yellow and features a black warning sticker with white text. The sticker includes the text 'CANADA ICES-001' and 'IMPORTANT'. The JLG logo is visible in the bottom right corner.</p>

General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		

<b>Safety</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	
ANSI Guidelines	No	



<b>Control Station Ground</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Function Controls	★ ★ ★ ☆	
Limited Function Check	The main components are in place and operational as noted.	







<b>Control Station Upper</b>		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	★★★★☆ Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	







<b>Electrical Operating System</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Operating Voltage	48 Volts	
Battery Condition	Weak or under-charged	
Cables and Connections	No visible damage or missing components	
Battery Charger	Appears normal - Not operationally checked	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		





## Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drive Motors	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		

<b>Chassis</b>		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Steering Linkage	☆☆☆☆	
Frame Condition	☆☆☆☆	
Scissor Linkage	☆☆☆☆	
Platform Condition	☆☆☆☆	
Platform Extension	☆☆☆☆	
Left Front Tire	No visible defects	

Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	
Right Front Tire	No visible defects	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	

**Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983**

IronPlanet , Inc. © 2012 All Rights Reserved