



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14787252 - 2017 JLG 4069LE Electric Scissor Lift



Item Details:

- Features: 40 ft Max Platform Height, 800 lb Max Weight Capacity, Platform Extension, Power to Platform, Foam Filled Tires, Upper Control Box
- Meter Reading: 188 Hours
- Serial # : 200261873
- Inspection Completed: 3/30/26

Shipping Details:





- Location California (Riverside County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup







 Protected by IronClad Assurance







Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected


General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		



<p>Serial Number / VIN</p>	<p>200261873</p>	
<p>CE Mark</p>	<p>No CE mark found</p>	
<p>Hour Meter / Odometer</p>	<p>188 hrs</p>	
<p>Paint</p>	<p>No visible damage</p>	
<p>Body Panels</p>	<p>No visible damage or missing components</p>	
<p>Steps/Ladders</p>		
<p>Basket / Safety Railing</p>	<p>No visible damage or missing components</p>	
<p>General Appearance #1</p>		

General Appearance #2		 <p>A close-up photograph of the equipment's identification label. The label is black with white text and includes fields for 'MODEL', 'SERIAL NO.', 'MAXIMUM WEIGHT', 'LIFT', 'LIFT CAPACITY', 'LIFT HEIGHT', 'LIFT SPEED', 'LIFT TIME', 'LIFT TYPE', 'LIFT CLASS', 'LIFT CODE', 'LIFT CATEGORY', 'LIFT GROUP', 'LIFT SUBGROUP', 'LIFT PARTS', 'LIFT ACCESSORIES', 'LIFT OPTIONS', 'LIFT CONFIGURATION', 'LIFT SERIALS', 'LIFT PARTS', 'LIFT ACCESSORIES', 'LIFT OPTIONS', 'LIFT CONFIGURATION'. A white sticker with 'rjglobal.com' and 'U0986652' is attached to the top right. Below the label is a green 'IMPORTANT' notice with safety instructions.</p>
General Appearance #3		 <p>A photograph showing the side profile of the JLG scissor lift. The lift is yellow with orange safety railings. The 'JLG' logo is visible on the side of the platform. The lift is parked on a paved surface.</p>
General Appearance #4		 <p>A photograph showing the side profile of the JLG scissor lift from a slightly different angle than the previous image. The lift is yellow with orange safety railings. The 'JLG' logo is visible on the side of the platform. The lift is parked on a paved surface.</p>
General Appearance #5		 <p>A close-up photograph of the orange battery compartment on the side of the JLG scissor lift. The compartment is rectangular and has the 'JLG' logo on it. The lift is parked on a paved surface.</p>
General Appearance #6		 <p>A photograph showing the side profile of the JLG scissor lift. The lift is yellow with orange safety railings. The 'JLG' logo is visible on the side of the platform. The lift is parked on a paved surface.</p>
General Appearance #7		 <p>A close-up photograph of the orange battery compartment on the side of the JLG scissor lift. The compartment is rectangular and has the 'JLG' logo and the model number '43110BLA' on it. The lift is parked on a paved surface.</p>
General Appearance #8		 <p>A close-up photograph of the orange battery compartment on the side of the JLG scissor lift. The compartment is rectangular and has the 'JLG' logo on it. The lift is parked on a paved surface.</p>

General Appearance #9












Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	


Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Engine Oil Pressure	No oil pressure indicator	
Limited Function Check	The main components are in place and operational as noted.	







Control Station Upper




Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.







Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station Upper #1		







Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	48 Volts	
Battery Condition	Weak or under-charged	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included 110 Volt, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	
Electrical Operating System #1		
Electrical Operating System #2		
Electrical Operating System #3		






Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Drive Motors	★ ★ ★ ☆	
Rear Drive Axle	★ ★ ★ ☆	
Final Drives	★ ★ ★ ☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine.	
Steering Linkage	★★★☆☆	
Frame Condition	★★★☆☆	
Scissor Linkage	★★★☆☆	
Platform Condition	★★★☆☆	
Platform Extension	★★★☆☆	
Left Front Tire	Chunks missing	

Left Rear Tire	Chunks missing	
Right Rear Tire	Chunks missing	
Right Front Tire	Chunks missing	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Outriggers / Stabilizers	★★★★☆	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		

Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved