



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14825732 - 2015 Genie GS3232 Electric Scissor Lift



Item Details:

- Features: Platform Extension, Power to Platform, Stabilizers, Solid Non-Marking Tires, Upper Control Box
- Meter Reading: 305 Hours
- Serial # : GS3215A-141552
- Inspection Completed: 3/24/26

Shipping Details:





- Location Ohio (Dayton-Springfield area)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

 Protected by IronClad Assurance

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected




General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		





Serial Number / VIN	GS3215A-141552	
Hour Meter / Odometer	305 hrs	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Steps/Ladders		
Basket / Safety Railing	Right railing bent	
General Appearance #1		
General Appearance #2		



General Appearance #3



Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
ANSI Guidelines	Yes	



Control Station Ground		
Item	Assessment	Photo
Gauges	Operational	
Function Controls	★★★★☆	
Warning Lights	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Control Station Upper		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Control Console	No visible damage or missing components	
Emergency Shut Off Switch	Operational	
Safety Control Hand/Foot Switch	★★★★☆ Operational	
Upper Function Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	








Electrical Operating System		
Item	Assessment	Photo
Operating Voltage	24 Volts	
Battery Condition	Functioned during the inspection, Weak or under-charged	
Cables and Connections	No visible damage or missing components	
Battery Charger	Included Appears normal - Not operationally checked, 120 Volt, Single Phase	
Limited Function Check	The electrical system was operational in a limited check.	







Drivetrain







Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drive Motors	★★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Lift Cylinders	★★★★☆	
Steering Cylinder	★★★★☆	

Outrigger Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Brake System	★★☆☆ The brake system functioned, stopping and holding the machine.	
Steering Linkage	★★☆☆	
Frame Condition	★★☆☆	
Scissor Linkage	★★☆☆	
Platform Condition	★★☆☆	
Platform Extension	★★☆☆	
Left Front Tire	Chunks missing, Tears	

Left Rear Tire	Chunks missing, Tears	
Right Rear Tire	Chunks missing, Tears	
Right Front Tire	Chunks missing, Tears	
Wheel Condition	No visible damage or missing components	
Wheel Studs	★★★★☆	
Pothole Protection Bars	★★★★☆ Functional	
Limited Function Check (Scissor-lift)	The main components appear to be in place and operational.	
Chassis #1		

Chassis #2		
Chassis #3		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved