



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

### Item #15110212 - 2018 JLG 1043 Telehandler



#### Item Details:

- Features: Open Operator Station, 43 ft Max Lift Height, 10000 lb Max Lift Capacity, Requires Diesel Exhaust Fluid, 60 in Forks, Outriggers, Auxiliary Hydraulic Plumbing
- Meter Reading: 6,809 Hours
- Serial # : 0160089840
- Inspection Completed: 5/8/26

#### Shipping Details:





- Location Texas (Tarrant County)
- Loading Dock Available: No
- Pickup Hours: null-null
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

 Protected by IronClad Assurance

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected


General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		







<p>Serial Number / VIN</p>	<p>0160089840</p>	
<p>CE Mark</p>	<p>No CE mark found</p>	
<p>Paint</p>	<p>Damaged</p>	
<p>Body Panels</p>	<p>Engine cover damaged</p>	
<p>Fenders</p>	<p>No visible damage or missing components.</p>	
<p>Hand Rails</p>	<p>No visible damage or missing components</p>	
<p>Exterior Lights</p>	<p>1 Inoperable / damaged / missing</p>	
<p>General Appearance #1</p>		






General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		







General Appearance #9













<b>Safety</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
Safety #1		








Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Steering Control	★★★★☆	

<p>Hydraulic Controls</p>	<p>★★☆☆☆ Will not return to center, Outrigger controls stick.</p>	
<p>Drivetrain Controls</p>	<p>★★★★☆</p>	
<p>Load Charts</p>	<p>None found</p>	
<p>Engine Oil Pressure</p>	<p>The fault indicator shuts off after the engine oil pressure rises.</p>	
<p>Warning Lights</p>	<p>Operational</p>	
<p>Gauges</p>	<p>Operational</p>	
<p>Hour Meter / Odometer</p>	<p>6809 hrs</p>	
<p>Limited Function Check</p>	<p>The main components are in place and operational as noted.</p>	

<b>Engine</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Engine	No US EPA Label Present Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
Blow-by (subjective visual observation)	Minor	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	







Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	








<b>Drivetrain</b>		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Front Axle Oscillating Pin	★★☆☆	
Rear Drive Axle	★★☆☆	
Rear Axle Oscillating Pin	★★☆☆	




Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		
Drivetrain #4		
Drivetrain #5		
Drivetrain #6		







Drivetrain #7











Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Front	
Boom Lift Cylinder(s)	★★★★☆	








Telescopic Boom Cylinders	★★★★☆	
Carriage Tilt Cylinder	★★★★☆	
Frame Leveling Cylinders	★★★★☆	
Outrigger Cylinders	★★★★☆ Control sticks	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		







Hydraulics #3		
Hydraulics #4		
Hydraulics #5		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Boom Condition	☆☆☆☆	
Left Side of Boom		
Right Side of Boom		

Chain / Tensioners	★★★★☆	
Boom Wear Guides	★★★★☆	
Outriggers	★★★★☆ Street pads	

<b>Telehandler*</b>		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder	★★★★☆	
Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The service brakes are operational, The park brake is operational.	
Left Front Tire	Size: 400/75-28 Brand: OTR Model: LiftBoss Tread Depth: 29 /32	

Left Rear Tire	Size: 400/75-28 Brand: OTR Model: LiftBoss Tread Depth: 36/32	
Right Rear Tire	Size: 400-75-28 Brand: OTR Model: LiftBoss Tread Depth: 33 /32	
Right Front Tire	Size: 400-75-28 Brand: OTR Model: LiftBoss Tread Depth: 31 /32	
Wheel Condition	No visible damage or missing components	
Telehandler* #1		
Telehandler* #2		
Telehandler* #3		

Telehandler* #4		
Telehandler* #5		
Telehandler* #6		
Telehandler* #7		
Load Back Rest	<p>★★☆☆</p> <p>Crossbar bent</p>	
Forks	<p>★★★★</p>	

Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved