	LACSE
Location:	

_______ Truck and Equipment Consulting, LLC - BULL DOZER INSPECTION CHECKLIST

Los Angeles , CA

Date (Y/M/D	10/27/2021
Inspector	R.F.

(Basic Info	ormation)				
(Manufacturer)	Caterpillar				
(Model Number)	D9T				
(Serial Number)	CAT00D9TJRJS01720				
(Year of Manufacturing)	2011				
(Hour Meter Reading)	19,603.8 Hrs				
(Engine Model) sn TXH01700 Tier IV	CAT C18 ACERT 18.1L 436 Hp I6 TurboD				
(Transmission)	Powershift 3 FWRD + 3 REV				
(Country of Origin)	USA				

Specification and Dimensions						
Serial Plate / Arrangement Number		RJS01720 / ARR# 2058600				
Cabin Canopy (Circle)		Cabin				
EPA Certificate / Permits Posted		ROPS / FOPS				
Track Gauge / Shoe Size		Track Gauge =88.6 in / Shoes =24 in				
Number Shoes / Rollers Hydraulic /Engine Oil/Coolant Capacities		43 per side / 8 Track Rollers per side				
		Hyd Tank=23.5 gal/Eng Oil=9.7 gal/Coolant= 25.9 g				
Hydraulic Relief		Lift =3800 psi / Steering =5875 psi				
Blade		SU 17.7 yd3 / 169 in / 15,130 lbs				
Ripper		No				
Operating Weight		106,618 lbs				

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

	(Check List)	Α	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Х				Good appearance No damage Some surface panel cosmetics only
APPEARANCE	(General Appearance-Rear)		Χ	Χ			Good appearance No damage Standing water in rear backside compartment
	(General Appearance-Right)		Χ				Good appearance Good panels+panel gaps, Good rails No damage
	(General Appearance-Left)		Χ				Good appearance Good panels+panel gaps, Good rails 1 Step Bent
	(General Appearance-Upper)		Χ				Good Cab,Roof+upper panels Stacks have caked dried material No damage
	(Major / Minor Surface Rust)		Χ				No Rust Seen
	(Body Panel Rust Damage / Cancer)		Χ				No panel or body damage seen, No rust cancer
	(Visible Weld Repairs / Stress Cracks)		Χ				No patches or weld repairs seen
	(Glass Condition)		Χ				Good glass No damage
	(Chassis / Undercarriage Damage)			Х			Wetness seen on underisde panels Good panel gaps No damage
	(Operator Cabin)		Χ	Χ			Overall Good appearance Headliner has large oil stains cosmetics
OPERATOR'S	(Operator Controls and Switches)		Χ				Complete Good Appearane Good Function
COCKPIT	(Hour Meter Activity)		Χ				Working
	(Other Gauge Activity)		Χ				Displays Good Working Order No Service Codes
	(Door / Canopy Latches)		Χ				Good latch function
	(Safety - Horn / Wipers)		Χ				Working
	(Cabin Ventilation / A/C / Heat)		Χ				A/C working
	(Operator Seat Condition)		Χ				Seat Good Condition
	(Seat Belts / Fire Extinguisher)		Χ				Yes
ENGINE	(Oil Color / Fluid Appearance / Particulates or Granuales)		Χ				Oil Good Appearance No signs or smells of cross contamination when hot
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Χ				No unusual noises at start up or shut down Good Idle
	(Engine Exhaust Color - White / Blue / Black / Clear)		Χ				Normal Small puffs of black under throttle Clear at operating temps
	(Oil Leaks)		Χ				No active leaks seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Χ				No smoke issues
	(Coolant Color / Fluid Appearance)		Χ				Coolant Good appearance No signs of contamination No mud or foul odor
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Χ				No coolant leaks seen Hoses dry No pump noises
	(Coolant Leaks from Radiator)		Χ				None seen
	(Overall Engine Appearance Clean / Wet / Dry)		Χ				Engine Dry appearance No seepage stains Weatherstripping is loose
	(Overall appearance of Hydraulic lines/fittings - worn/cracked)		Χ				Good appearance hydraulic lines + fittings No seepages or damage seen
HYDRAULICS	(Hydraulic Pump Sounds / Noises)		Χ				No unusual pump noises or vibrations under load
OVERALL	Wet or Damp hydraulic lines and fittings / fluid leaks)		Χ				No hydraulic leaks seen
	(External Controls / Levers Condition)		Χ				Good appearance
	(Hydraulics Service Records / Maintenance History)		~				1 Filter Marked 7/13/2021 @ 19.496 , with additional history

	(Lighting Sy	stem Condition)			Χ				Working		
	(Reverse Alarm / Backup Signal)				Χ				Working		
ELECTRICAL	ECTRICAL (Battery Condition)		Χ	Χ			Average Appea				
	(Other Elect	ric Device Condit	ion)		Х				Good function both Driver Information di	splay and Diagnostics monitor	
	(Foot Brake)				Χ				Good brake function		
BRAKES	A K E S (Inching Brake Functional & Working Condition) X			Working							
	(Parking Brake)				Χ				Good function	on	
	(Other Remarks)				Χ				Brakes good perfo	rmance	
	(Clutch Nois	e / Function)			Χ				No unusual noises or	vibrations	
RANSMISSION	(Transmissio	n Noise / Function	on)		Χ				Good Forward and Rever	se performance	
	(Shift Lever	Condition & Func	tion)		Χ				Good shifter fun	nifter function	
	(Other Remarks)			Χ							
	(Lift)	(Oil Leak from Cylinder)			Χ				No leaks from lift cyl	inder seen	
	(LIIL)	(Mounting Pin Co	ondition)		Χ				Good pin appear	rance	
HYDRAULICS	(Tilt)	(Oil Leak from Cylinder)			Χ				No leaks from Tilt cylinder		
CYLINDERS	(TIIL)	(Mounting Pin Condition)			Χ				Good appeara	Good appearance	
	(Angle)	(Oil Leak from Cylinder)			Χ				No leaks from Angle cy	ylinder seen	
	(Aligie)	(Mounting Pin Co	ondition)		Χ				Good appeara	nce	
	Ripper	(Other Remarks)							N/A	N/A	
	Undercarriag	ge Appearance			Χ	Χ			B- Some surface wear +rust idler and ro	ller and roller surfaces Above Average	
	Right Side D		Χ				B / B- = Right Sprocket Teeth+Cute	eeth+Cutouts Minimal surface wear			
		ive Sprocket/Link			Χ					Cutouts Above Avg Minimal surface wear	
CHASSIS	Right Side F	ront Idler/Upper a	and Lower Roller		Χ	Χ			B- / C+ = Right side Idler + rollers some surface rust +wear		
UNDER		ont Idler/Upper a	nd Lower Roller		Χ	Χ		B- / C+ = Left side Idler + roller some surface rust +wear			
CARRIAGE	Track Condition	tion			Χ	Χ		B = Tracks Good Appearance no cracked or broken shoes Gro		l or broken shoes Grouser B-	
	OPERATIO Forward Steering/Brakes/Clutch X In N Reverse Steering/Brakes/Clutch X Steering/Brakes/Clutch X Lift/Tilt/Angle X				Good Function in Forward						
		PERATIO							Good Use (A)9	use (A)90% to (E) 20%	
		N Reverse							Good Function in Reverse		
			Lift/Tilt/Angle						Good		
	Other Comments			Χ				Quiet travel No undercarriage	ū		
LADE/	(Blade Edge				Χ				Good appearance of blade egde No	dents No damage seen	
RIPPER	(Blade Overa				Χ				Good	N/A	
		all Condition)							1411		
	(Other Remarks)				X				Good lift, drop, tilt, and angle function		

OVERALL EXTERIOR RATING: <u>B</u> QUALITY: <u>B/B-</u>
OVERALL INTERIOR RATING: <u>B</u> SAFETY: <u>B</u>
OVERALL PERFORMANCE: B FUNCTIONALITY: B
OVERALL CONDITION GRADE: B
FLUID SAMPLE REQUEST (Y/N) _n_ OIL _n_ COOLANT _n_

DIMENSIONS: (Transport Reff only)

LENGTH: 193.3 in / 274.3 in (w/blade)

WIDTH: 113.4 in HEIGHT: 157.5 in WEIGHT: 80,062 lbs *A:Remaining Ratio *B:Remaining Ratio

90% or more

io 70% or more

*C:Remaining Ratio 50% or more *D:Remaining Ratio 20% or more

*E:Remaining Ratio 20% or less