Calex

TRUCK AND EQUIPMENT CONSULTING LLC -ENCLOSED CAB CRAWLER VERTICAL

Santa Clari ta, CA

DRILL CHECKLIST (STANDARD)

Operator Position

Extension Rods

Depth

Head

Serial Plate/Frame Inscription

EPA Certificate / Permits Posted

7/12/2022

B160US0100

Enclosed Cab w/A/C + Heat (working)

EROPS / EFOPS

50 Meter Stroke (w/rotary head)

4 Section Round Locking Kelly Bars H16 Rotary Head

L.W.

Inspector

Initials

Date (Y/M/D

Specification and Dimensions

(Basic Information)						
(Manufacturer)		Casagrande				
(Model Number)		B160XP Hydraulic Piling Rig				
(Serial Number)		B160US0100				
(Year of Manufacturing)		2016				
(Engine Hours Meter Readir	ng)	1060 Hrs				
(Drill Type)		Rotary + CFA (continuous flight) piling				
(Engine Model)	TIER IV	Cummins QSB6.7 6.7L 225Hp I6 TurboD				
(Hydraulic System Relief)		5076 psi				
(Hydraulic Tank Capacity)		Hydraulic =87 gal / Fuel =74 gal				
(Emissions Urea Tank)		15 gal capacity				
	Α	(Near to Brand New or Excellent Condition)				

4	To gui oupdoicy									
A	(Near to Brand New or Excellent Condition)		Origin				Italy			
В	(A little Wear and Good Condition)									
C	(Fair Workable Condition for Hour Meter Rea	ding)								
D	(Workable but minor repair is required)									
E	(Workable but major repair is required)									
	(Check List)	Α	В	С	D	Е	(Remarks)			
eral Appearance-Front)			Х				Good appearance front panels, some surface rust cosmetics No da			
ieral Appearance-Rear)			Х	Х			Some scrapes and surface rust lower counterweight, panel cosm			
eral Appearance-Front) eral Appearance-Rear) eral Appearance-Right) eral Appearance-Left) eral Appearance-Upper) or / Minor Surface Rust) y Panels / Covers - Rust Damage / Cancer) ble Weld Repairs / Stress Cracks) ss Condition)			Х				Good side panels+gap fitment			
ieral Appearance-Left)			Х				Good side panels+gap fitment			
eral Appearance-Upper)							Cab roof, upper surfaces and upper panels Good appearance No o			
or / Minor Surface Rust)			Х	Х			Areas of surface rust cosmetics on unpainted unplated metals No			
ly Panels / Covers - Rust I	Damage / Cancer)		Х				No rust damage no cancer			
ble Weld Repairs / Stress (Cracks)		Х				No weld repairs seen No cracks or damage to structure or crossme			
ss Condition)			Х				Good Glass			
ssis / Undercarriage Dama	ge)		Х				Good underside panels + gaps No damage			
erator Cabin)			Х				Good cabin appearance Solid floors Good panels No wear issues			
erator Controls and Switche	es)		Х				Complete Good appearance and function switchgear and control			
r Meter Activity)			Х				Working			
er Gauge Activity)			Х				Good Driver Info display function No Service Codes			
r / Canopy Latches)			Х				Good function all latches and doors			
ety – Horn / First Aid Kit)			Х				Working			
erator Seat Condition)			Х				Good appearance No damage			
ety – Seat Belts / Fire Exti	nguisher)		Х				Yes			
Color / Fluid Appearance /	Particulates or Granuales)		Х				Good appearance No signs of cross contamination No Oil Blow			

6 TurboD	Max Drill Speed	Drill =32 RPM / Max Discharge Speed =130 RPM
	Micropiling Depth	Max Depth =52 Ft / Main Winch = 35,969 lbs
74 gal	Track Length/Width	Track Length =177 in / 24 in Width Triple Grouser
	Opeating Weight	90,389 lbs (Std Micropiling Config w/Kelly bars)
Condition)	Origin	Italy
n)		
Meter Readi	ing)	
uired)		
uired)		

	(Check List)	А	В	С	D	E	(Remarks)
GENERAL	(General Appearance-Front)		Х				Good appearance front panels, some surface rust cosmetics No damage
APPEARANCE	(General Appearance-Rear)		Х	Х			Some scrapes and surface rust lower counterweight, panel cosmetics
	(General Appearance-Right)		Х				Good side panels+gap fitment
	(General Appearance-Left)		Х				Good side panels+gap fitment
	(General Appearance-Upper)		Х				Cab roof, upper surfaces and upper panels Good appearance No damage
	(Major / Minor Surface Rust)		Х	Х			Areas of surface rust cosmetics on unpainted unplated metals No damage
	(Body Panels / Covers - Rust Damage / Cancer)		Х				No rust damage no cancer
	(Visible Weld Repairs / Stress Cracks)		Х				No weld repairs seen No cracks or damage to structure or crossmembers
	(Glass Condition)		Х				Good Glass
	(Chassis / Undercarriage Damage)		Х				Good underside panels + gaps No damage
	(Operator Cabin)		Х				Good cabin appearance Solid floors Good panels No wear issues seen
OPERATOR'S	(Operator Controls and Switches)		Х				Complete Good appearance and function switchgear and controls
COCKPIT	(Hour Meter Activity)		Х				Working
	(Other Gauge Activity)		Х				Good Driver Info display function No Service Codes
	(Door / Canopy Latches)		Х				Good function all latches and doors
	(Safety – Horn / First Aid Kit)		Х				Working
	(Operator Seat Condition)		Х				Good appearance No damage
	(Safety – Seat Belts / Fire Extinguisher)		Х				Yes
ENGINE	(Oil Color / Fluid Appearance / Particulates or Granuales)		Х				Good appearance No signs of cross contamination No Oil Blow By
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Х				Easy and quick start up Smooth Idle
	(Engine Exhaust Color – White / Blue / Black / Clear)		Х				Clear Stays Clear at Operating Temps
	(Oil Leaks)		Х				No active Engine oil leaks seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Х				No smoke issues Smooth idle No unusual noises
	(Coolant Color / Fluid Appearance)		Х				Good appearance of coolant No signs of cross contamination
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Х				No cooling system noises or leaks
	(Coolant Leaks from Radiator)		Х				No leaks or dried seepages seen
	(Overall Engine Appearance Clean / Wet / Dry)		Х				Clean and dry engine appearance
	(Overall appearance of Hydraulic lines/fittings - worn/cracked)		Х				No frayed or damaged hoses or fitting seen
HYDRAULICS	(Hydraulic Pump Sounds / Noises)		Х				No unusual pump noises during operations
OVERALL	Wet or Damp hydraulic lines and fittings / fluid leaks)		Х				No dried seepages No dampness or discoloration on hydraulics
	External Controls / Levers Condition)		Х				Good appearance and function
	(Hvdraulics Service Records / Maintenance History)						not marked or provided

Location:

	(Lighting Sy	stem Condition)				1			N/A		
	(Reverse Alarm / Backup Signal)								N/A		
ELECTRICAL	(Battery Condition)				Х			Good	d appearance		
	(Other Electric Device Condition)				Х			Electrics Good function Displ	ay sharp and clear No Service Codes		
	Swivel Bearing Condition				Х			Smooth and Quiet Rotation both directions			
SWING TABLE	Swivel Motor Condition				Х			Quiet Good performance			
	Swivel Joint Condition				Х			Good appearance			
	(Other Rema	arks)			Х			Swing table bolts	s quiet Good appearance		
		Clutch Noise / Function)			Х			No noises or vibrations during travel			
TRANSMISSION	(Transmission Noise / Function)				Х			Good forward and reverse	e No hesitiation or unusual noises		
	(Shift Lever Condition & Function)				Х			Goo	od response		
	(Other Rem	(Other Remarks)			Х				travel function		
	воом	(Oil Leak from Cy			Х			Pistons good appearar	nce No pitting No discoloration		
	Beelw	(Mounting Pin Condition)			Х				ce No wear issues seen		
HYDRAULICS	DRILL	(Oil Leak from Cylinder)			Х			÷	nce No pitting No discoloration		
CYLINDERS	0.000	(Mounting Pin Condition)			Х				ce No wear issues seen		
	OTHER	(Oil Leak from Cylinder)			Х			<u> </u>	nce No pitting No discoloration		
		(Mounting Pin Condition)			Х				ce No wear issues seen		
	/ /	(Other Remarks)			Х			Good Function of Hydraulic System			
	-	(Transom / Boom / Arm Function / Noise)			Х				vibrations Smooth and quiet		
		is / Loose Pins / S			Х				ose play No travel noises		
			Sprocket / Shoe Condition		X X	X X			wear seen on sprockets No curling seen		
CRAWLER &		RIGHT SIDE Link Bush / Drive Sprocket / Shoe Condition			X X	X			wear seen on sprockets No curling seen		
WHEEL ASSEMBLIES		LEFT SIDE Upper & Lower Roller / Front Idler Condition RIGHT SIDE Upper & Lower Roller / Front Idler Condition			X X	X			surface wear seen on idler edges		
ASSEMBLIES	RIGHT SIDE	Opper & Lower Ro	Right Front *(A)to(E)		X	X		Rollers =C Surface rust+wear			
	(Roller	(Front) (Rear)	Left Front *(A)to(E)		x	X		Rollers =C Surface rust+wear	ł		
	Condition)		Right Rear		Ŷ	X		Rollers =C Surface rust+wear	use (A)90% to (E) 20%		
	o on anaion,		Left Rear		X	X		Rollers =C Surface rust+wear			
	(Track Condition)				~	X			me wear+tear seen on undercarriage		
	(Drill Head)				х	~			appearance		
DRILL	(Drill Mast)				X			Good appearance No damage Boom side panels Good appearance			
COMPONENTS	(Rotation)	(X				od rotation		
•	(Drill Elevati	on)			х				Working		
	(Lift and Drop)				Х				+ Drop Function		
I	(Chains)	1.			X				aood appearance		
BRAKES	(Foot Brake)			X	1		Good brake function			
I	(Inching Bra				Х			Good			
	(Parking Brake)				Х	1		Go	od function		
FRAME	Front				Х			Good chassis +frame appearance Good crossmembers No rust or damage			
APPEARANCE	Rear				X			Good chassis +frame appearance	e Good crossmembers No rust or damage		
	Center				X			Good chassis +frame appearance Good crossmembers No rust or damage			
		Spring Condition			X	1	l		appearance		
OPERATION	1 0	ORWARD & REVERSE			Х	1			/el response from engine + transmission		
I	SWING TABLE ROTATION				X	1		Smooth and quiet G	ood rotation both directions		
	BOOM LIFT / ANGLE / TILT				Х			Good Lift / Til	t / Angle performance		
	OVERALL FUNCTIONALITY				Х			Good Function	ality and Performance		
RATINGS	OVERALL V	ISUAL INSPECTIO	DN	İ	Х	1		Good appearance of hydraulics, o	chassis, hydraulic components Clean+dry		
	COMMENTS				Х	Х		Some surface wear to under	carriage componens with travel noise		
	OVERALL PERFORMANCE INSPECTION				Х			Good hydraulic performance, go	od engine, steering, brakes, and controls		
	COMMENTS	COMMENTS						No site drillin	g tested or performed		

 OVERALL EXTERIOR RATING:

 QUALITY:

 OPERATORS STATION RATING:

 SAFETY:

 OVERALL PERFORMANCE:

 FUNCTIONALITY:

 OVERALL GRADE EVALUATION:
 B / B FUNCTIONALITY:

 FLUID SAMPLE REQUEST (Y/N)

 Eng Oil

 Hyd Oil

Dimensions: (transport reff only)

Length: 49 Ft Width: 8 Ft 3 in Height: 11 Ft Weight: 90,389 lbs
 *A:Remaining Ratio
 90% or more

 *B:Remaining Ratio
 70% or more

 *C:Remaining Ratio
 50% or more

 *D:Remaining Ratio
 20% or more

 *E:Remaining Ratio
 20% or less