Location:	SunState	Equipment	
	Oakland	CA	

TRUCK AND EQUIPMENT CONSULTING LLC - DUMP TRUCK

Date (Y/M/D	8/2/2022
Inspector Initials	C.T.

(Basic Information)					
(Make)	Ford				
(Model)	F550 S Duty XL Reg Cab 4x2 Dualie Rear				
(Serial Number)	1FDUF5GT8CEB96785				
(Year of Manufacturing/Origin)	2012				
(Color)	White / Gray				
(Mileage)	79,496.2 Miles				
(Engine)	PowerStroke 6.7L 390Hp V8 Turbo Diesel				
(Transmission)	Automatic 6 Spd				
(Dump Capacity)	3 yd3				

A	(Near to	Brand	New or	Excellent	Condition)

- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions					
GVWR	19,500 lbs				
Body	Valew Dump Body				
DOT	CALIF Perm				
Brake	Hydraulic				
Front / Rear Axle	Front =6500 lbs / Rear =14,706 lbs				
Tires	Bridgestone/Continental 225/70R 19.5G				
PTO	Floor Mount				
Rear	4.88				
Wheelbase	141 inch				
Origin	Louisville, Kentucky USA				
Other	Tarp System / Fed Annual Inspection Cert 11/2021				

	(Check List)	Α	В	С	D	Е	(Remarks)
GENERAL	(General Appearance-Front)		Х				Good appearance of grille, bumpers, front fenders good panels No damage
APPEARANCE	(General Appearance-Rear)		Х	Х			Rear dump heavy wear+paint loss, areas of surface rust, upper edge dented
	(General Appearance-Right)		Χ				Right side body panels Good appearance No damage Dump panels straight
	(General Appearance-Left)		Х				Left side body panels Good appearance No damage Dump panels straight
	(General Appearance-Upper)		Χ				Good appearance upper body+panel gaps, roof,hood Dump panels straight
	(Major / Minor Surface Rust)		Χ	Х			Areas of surface rust rear dump body, some front suspension+inner hubs
	(Body Panels / Covers - Rust Damage / Cancer)		Х	Χ			No rust cancer Dump panels surface rust + precancer No damage
	(Visible Weld Repairs / Stress Cracks)		Χ				None seen 1 poss epoxy repair seen on exhaust
	(Glass Condition)		Х				Good Glass
	(Chassis / Undercarriage Damage)		Х				Good appearance Frame rails, underside components Dry appearance
	(Operator Cabin)		Χ				Solid floors dash+steering wheel Good appearance No damage
OPERATOR'S	(Operator Controls and Switches)		Χ				Complete No broken switches or controls
COCKPIT	(Odometer Activity)		Χ				Working
	(Other Gauge Activity)		Χ				Gauges+display Working No Check Engine or Service Indicators lit
	(Door / Canopy Latches)		Χ				Good Hood + Door latch function
	(Safety - Horn / First Aid Kit)		Χ				Horn Working
	(Operator Seat Condition)		Χ				Seats Good condition
	(Other)		Χ				A/C working
ENGINE	(Oil Color / Fluid Appearance)		Χ				Normal Appearance No Blow-By at operating temp
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		Χ				Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color - White / Blue / Black / Clear)		Χ				Clear / Clear at Temperature
	(Oil Leaks)		Χ	Χ			1 drip seen on ground see photos
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		Χ				No smoke issues
	(Coolant Color / Fluid Appearance)		Χ				Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		Χ				No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)		Χ				None seen Some dented radiator fins
	(Overall Engine Appearance Clean / Wet / Dry)		Х				Dusty dirty but overall dry No damage seen No active seepages seen

	I/o le o le o le o	 			T W I
	(Lighting System Condition)	 Х			Working
	(Reverse Alarm / Backup Signal)	Χ			Working
ELECTRICAL	(Battery Condition)	Χ	Χ		Some dried corrosion on battery terminals
	(Other Electric Device Condition)	Χ			Good PTO + Dump control function
	FRONT TRACTOR TIRES	Χ			Tires =B Good appearance No side wall damage Hubs =B- some inner rust
TIRES	TRAILER TIRES X4	Χ			Tires =B Good appearance No side wall damage Hubs =B- some inner rust
	OTHER	Χ			Inner hubs some surface rust Dry No damages seen
	(Clutch Noise / Function)	Χ			No unusual transmission noises or vibrations
TRANSMISSION	(Transmission Noise / Function)	Χ			Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	Χ			Good Shifter function
	(Other Remarks)	Χ			Pedals Good appearance No excess wear or tear
DIFFERENTIAL	(Rear Diff - Noises ?)	Χ			No Rear Diff Noises heard
BRAKES	(Foot Brake)	Χ			Good Brake Function
	(AIR BRAKE)				N/A
	(Parking Brake)	Χ			Good function
DUMP and	LIFT + DUMP	Χ			Good Lift + Drop function
HYDRAULICS	HYDRAULICS	Χ			Working
	TARP	Χ	Χ		Tarp + frame some wear
	PUMP PERFORMANCE	Χ			Working No clicking noises
OPERATION	FORWARD & REVERSE	Χ			Good Forward and Reverse
	STEERING + BRAKES	Χ			Good Steering and Brakes
	ENGINE	Χ			Engine Good Response
	CONTROLS	Χ			Controls Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	Χ			Good body panels,panel gaps, Hydraulics clean+dry No pitting or seepages
	COMMENTS	Х	Χ		Wear+tear to dump body surfaces, areas of discolortion underside areas
	OVERALL PERFORMANCE INSPECTION	Х			Good travel performance Good steering+brakes Good engine response
	COMMENTS	Χ			Good dump lift and drop function + performance

OVERALL EXTERIOR RATING: <u>B/C+</u> QUALITY: <u>B-/C+</u>
OVERALL INTERIOR RATING: <u>B-</u> SAFETY: <u>B</u>
OVERALL PERFORMANCE: B FUNCTIONALITY: B
OVERALL CONDITION GRADE: B-
FLUID SAMPLE REQUEST (Y/N) n OIL n COOLANT n

TIRES

*A:Remaining Ratio 90% or more
*B:Remaining Ratio 70% or more
*C:Remaining Ratio 50% or more
*D:Remaining Ratio 20% or more
*E:Remaining Ratio 20% or less