

Inspection Report (On-Highway Truck Basic Template)

General Info

| | |
|--|---|
| Year | 2011 |
| Make | Peterbilt |
| Model | 386 |
| Serial Number | 1XPHDP9X7BD118394 |
| Truck Odometer Reading | 405,212 |
| Current Inspection / State Cert / DOT | Annual Inspection Completed 12/2021 In accordance with 49CFR 396.17 to 396.23 |
| Previous Application (e.g., earth moving, mining, demolition, etc) | aerial lift transport |

Dimensions

| | |
|---------------------------|--|
| Dimensions | Please enter in or verify (if pre-populated) the following dimensions. |
| Length (ft and inches) | 25' 6" |
| Width (ft and inches) | 8' 4" |
| Height (ft and inches) | 11' 3" |
| Wheelbase (ft and inches) | |
| GVWR (lbs) | 50,350 |



Features and Configuration

| | |
|-------------------------------------|--|
| Features | Enter in and/or verify the following information regarding the features of this equipment. |
| Heat | Yes |
| A/C | Yes |
| Radio | Yes |
| Backup Camera | No |
| Cruise Control | Yes |
| PTO | Yes |
| PTO Details | Chelsea 489GLAHX - V3XK/ Parker P16 |
| Engine Break | Yes |
| Differential Lock | Yes |
| OMM (Operator & Maintenance Manual) | Yes |
| Telematics | No |
| Auxiliary Engine | No |
| Liftgate | No |

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Truck Basic Template)

| | |
|-----------------------------------|---|
| Instructions | <p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background |
| Exterior Walkaround Photos |  |
| |  |

Inspection Report (On-Highway Truck Basic Template)




Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)



General Appearance Inspection Points

General Appearance



| | |
|-----------------|--|
| Front | 3 - Normal Wear & Tear |
| Front Condition | Visible chipped paint or dents, Other (see comments) |
| Comments | visible clear coat peeling |

Inspection Report (On-Highway Truck Basic Template)



Front Photos





Inspection Report (On-Highway Truck Basic Template)

| | | |
|----------------|--|--|
| |  | |
| Rear | 4 - Like New, Recently Replaced | |
| Rear Condition | No visible damage | |
| Rear Photos |  | |
| Left | 3 - Normal Wear & Tear | |

Inspection Report (On-Highway Truck Basic Template)

| | |
|----------------|--|
| Left Condition | Visible chipped paint or dents, Other (see comments) |
| Comments | small crack on left side battery cover/step and small dent on left side mud guard |
| Left Photos |  |
| |  |
| Right | 4 - Like New, Recently Replaced |



Inspection Report (On-Highway Truck Basic Template)

| | |
|-----------------|--|
| Right Condition | Visible chipped paint or dents, Other (see comments) |
| Comments | small dent on R/S mud guard the rest looks great |
| Right Photos |  |
| |  |

Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)

| | |
|--------------------------------|--|
| |  |
| Upper | 4 - Like New, Recently Replaced |
| Upper Condition | No visible damage, Other (see comments) |
| Comments | minor clear coat peeling |
| Upper Photos |  |
| Body Panels (Any Rust Damage?) | 4 - Like New, Recently Replaced |
| Body Panel Condition | Visible chipped paint or dents, Other (see comments) |
| Comments | minor scuff marks on front hood/fenders the cab looks great |

Inspection Report (On-Highway Truck Basic Template)



Body Panels Photos





Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)

| | | |
|---|---|--|
| |  | |
| |  | |
| Doors / Canopy Latches | 4 - Like New, Recently Replaced | |
| Doors / Canopy Latches Condition | No visible damage | |

Inspection Report (On-Highway Truck Basic Template)




| | |
|--------------------------------------|--|
| <p>Doors / Canopy Latches Photos</p> |  |
| |  |
| <p>Glass Condition</p> | <p>4 - Like New, Recently Replaced</p> |
| <p>Glass Condition Notes</p> | <p>Glass intact, no visible damage</p> |

Inspection Report (On-Highway Truck Basic Template)

Glass Condition Photos




Inspection Report (On-Highway Truck Basic Template)

| | |
|----------------------------------|---|
| |  |
| Mirrors | 4 - Like New, Recently Replaced |
| Mirror Condition Notes | Mirrors present and intact, no visible damage, Other (see comments) |
| Comments | small bend on right side mirror |
| Mirrors Photos |  |
| Lighting System | 4 - Like New, Recently Replaced |
| Lighting System Condition | One or more exterior lights are non-operational, Other (see comments) |
| Comments | factory lights all functional, right side beacon light not working, 2 overhead interior dome lamps not working, all other lights inside and out work properly |
| Lighting System Photos |  |

Inspection Report (On-Highway Truck Basic Template)




Inspection Report (On-Highway Truck Basic Template)






Cab Inspection Points

On Highway - Cab

| | |
|----------------------------------|--|
| Instructions | <p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required</p> <p>Take close-up photos of and leave comments.</p> |
| Serial Number Plate Photo |  |

Inspection Report (On-Highway Truck Basic Template)

| | |
|-----------------------|--|
| Operator Cabin | 3 - Normal Wear & Tear |
| Comments | interior in really nice condition |
| Operator Cabin Photos |  |
| |  |
| |  |

Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)




Inspection Report (On-Highway Truck Basic Template)




Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)

| | | |
|--|--|--|
| |  | |
| <p>Operator's Seat & Arm Rests</p> | <p>4 - Like New, Recently Replaced</p> | |
| <p>Operator's Seat & Arm Rests Photos</p> |  | |
| |  | |
| <p>Seat Belt</p> | <p>3 - Normal Wear & Tear</p> | |




Inspection Report (On-Highway Truck Basic Template)

| | |
|-------------------------|--|
| <p>Seat Belt Photos</p> |  |
| |  |
| |  |




Inspection Report (On-Highway Truck Basic Template)

| | |
|--------------------------------|--|
| |  |
| Cabin Lights | 3 - Normal Wear & Tear |
| Comments | some overhead dome lights inoperable |
| Cabin Lights Photos |  |
| |  |
| Controls & Switches | 4 - Like New, Recently Replaced |
| Comments | all switches seem to be functioning |

Inspection Report (On-Highway Truck Basic Template)

| | |
|---------------------------------------|--|
| <p>Controls & Switches Photos</p> |  |
| |  |
| |  |
| <p>Odometer Activity</p> | <p>4 - Like New, Recently Replaced</p> |

Inspection Report (On-Highway Truck Basic Template)

| | |
|--|---|
| <p>Odometer Activity Photos</p> |  |
| <p>Other Gauge Activity</p> | <p>4 - Like New, Recently Replaced</p> |
| <p>Other Gauge Activity Photos</p> |  |
|  | |
| <p>Heater & A/C</p> | <p>4 - Like New, Recently Replaced</p> |
| <p>Comments</p> | <p>A/C EXCEEDED 30° TEMP DROP HEATER WORKING WELL</p> |

Inspection Report (On-Highway Truck Basic Template)



Heater & A/C Photos




Fans / Vents

4 - Like New, Recently Replaced

Inspection Report (On-Highway Truck Basic Template)


| | |
|-------------------------------|---|
| Fans / Vents Photos |  |
| |  |
| Horn | 3 - Normal Wear & Tear |
| Comments | air horn great , steer wheel horn inoperable |
| Reverse Alarm / Backup Signal | <input checked="" type="checkbox"/> |
| Backup Camera | 0 |
| Other Electronic Devices | 0 |
| Fire Extinguisher | 1 - Service Required |
| Comments | 2 1/2lbs extinguisher not certified |

Inspection Report (On-Highway Truck Basic Template)

| | |
|--------------------------|---|
| Fire Extinguisher Photos |  |
| First Aid Kit | 0 |

Engine Inspection Points

Engine

| | |
|--|--|
| Engine Type (Make, Model, Cylinders, Hp) | PACCAR inline 6cyl. 485hp 12.9L |
| Engine Serial Number | A-29344 |
| Engine Fuel Type | Diesel |
| Engine Photos |  |

Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)

| | | |
|---|--|--|
| |  | |
| |  | |
| |  | |
| Blow-by (Visual Observation Check) | No | |
| Unusual Noises (Upon Start-up, Idle, Shutdown) | No | |
| Unusual Noise Notes | No unusual noises heard | |
| Engine Smoke (Upon Start-up, Idle, Shutdown) | No | |
| Engine Smoke Notes | No engine smoke issues observed | |
| Engine Exhaust Color | Clear | |




Inspection Report (On-Highway Truck Basic Template)

| | |
|--------------------------|--|
| Battery | 3 - Normal Wear & Tear |
| Battery Condition | Clean & dry appearance, tight connections, Other (see comments) |
| Comments | truck didn't start after sitting for a few days (per Chris) |
| Battery Condition Photos |  |
| Radiator | 4 - Like New, Recently Replaced |
| Radiator Condition | Radiator fins & components appear to be in good working order, no signs of damage or leaks |
| Radiator Photos |  |
| |  |

Inspection Report (On-Highway Truck Basic Template)

| | |
|-----------------------|--|
| |  |
| Belts | 3 - Normal Wear & Tear |
| Belt Condition | Other (see comments) |
| Comments | alternator belt signs of small cracks fan belt good |
| Belt Photos |  |
| |  |
| Hoses | 4 - Like New, Recently Replaced |
| Hose Condition | Firm, pliant hoses with no signs of wear or leaks |

Inspection Report (On-Highway Truck Basic Template)

| | |
|--------------------|---|
| <p>Hose Photos</p> |  |
| |  <p>WARNING AUTOMATICALLY STOPPING CLEAR WHEN ENGINE IS STARTING CAN START AND STOP BY ITSELF AND CAN CAUSE SERIOUS INJURY</p> |
| |  |



Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)






Inspection Report (On-Highway Truck Basic Template)

| | | |
|---------------------------------------|--|--|
| |  | |
| Water Pump | 4 - Like New, Recently Replaced | |
| Water Pump Condition | No unusual pump noises heard | |
| Water Pump Photos |  | |
| Cooling System Leaks | No | |
| Coolant Color / Appearance | 4 - Like New, Recently Replaced | |
| Coolant Color/Appearance Notes | Normal Translucent appearance, no visual signs of contamination | |
| Oil Leaks | Yes | |
| Oil Leak Notes | Dried oil seepages seen, Wet areas with drops forming due to oil leakage, Other (see comments) | |
| Comments | possible oil leak at rear of oil pan or left rear side of engine block | |

Inspection Report (On-Highway Truck Basic Template)

| | | |
|---|---|--|
| Oil Leak Photos |  | |
| |  | |
| Oil Color / Appearance | 3 - Normal Wear & Tear | |
| Oil Color / Appearance Notes | Appropriate oil level, Clean oil appearance, no signs of cross contamination | |
| Fuel Leaks | No | |
| Equipped with DPF (Diesel Particulate Filter) | Yes | |
| DPF Condition | 4 - Like New, Recently Replaced | |
| DPF Condition Notes | Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated | |
| DPF Photos |  | |

Inspection Report (On-Highway Truck Basic Template)


| | | |
|--|--|--|
| |  | |
| |  | |
| Requires DEF (Diesel Exhaust Fluid) | Yes | |
| DEF Tank | 4 - Like New, Recently Replaced | |
| DEF Tank Condition | Area around DEF tank cap is clean, fluid is clear & appears free of contaminants | |
| DEF Tank Photos |  | |
| Overall Engine Appearance | Clean & dry | |
| Overall Engine Comments | Besides the small oil leak, the Engine looks very well maintained! | |

Aux. Engine Inspection Points



Inspection Report (On-Highway Truck Basic Template)

| | |
|---------------------|--|
| Instructions | Assess the condition of the aux. engine / power unit. For items on a 4 point scale, evaluate using the following criteria: 4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required |
|---------------------|--|


Drivetrain Inspection Points

| Drivetrain | |
|---------------------------------------|---|
| Transmission Info (Make/Model) | Eaton transmission |
| Drive Type | 4X2 |
| Overdrive | N/A |
| Transmission | 4 - Like New, Recently Replaced |
| Transmission Condition | No unusual noises or vibrations |
| Transmission Condition Photos |  |


Inspection Report (On-Highway Truck Basic Template)

| | | |
|------------------------------------|--|--|
| |  | |
| Clutch | 4 - Like New, Recently Replaced | |
| Shift Lever | 4 - Like New, Recently Replaced | |
| Shift Lever Condition | Good forward and reverse function | |
| Differential | Check condition of the differential(s). Take photos and notes as relevant. | |
| Rear Differential | 4 - Like New, Recently Replaced | |
| Rear Differential Condition | Dry housing appearance, no unusual noises heard during operation | |
| Rear Differential Photos |  | |

Inspection Report (On-Highway Truck Basic Template)

| | |
|-----------------------------|--|
| |  |
| Front Differential | 0 |
| Brake System Type | Air Brakes |
| Air Brake System | 4 - Like New, Recently Replaced |
| Foot Brake | 4 - Like New, Recently Replaced |
| Foot Brake Condition | Good brake function |
| Engine Brake Configuration | 2 Position |
| Engine Brake | 4 - Like New, Recently Replaced |
| Parking Brake | 4 - Like New, Recently Replaced |
| Parking Brake Condition | Good brake function |
| Overall Drivetrain Comments | All air brakes in great working condition |




Chassis Inspection Points

| | |
|--------------|--|
| Frame | 4 - Like New, Recently Replaced |
| Frame Photos |  |




Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)

| | |
|-------------------|--|
| |  |
| |  |
| |  |
| Suspension | 4 - Like New, Recently Replaced |
| Comments | suspension great condition |




Inspection Report (On-Highway Truck Basic Template)

| | | |
|--------------------------|--|--|
| <p>Suspension Photos</p> |  | |
| |  | |
| |  | |

Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)




| | | |
|----------------------------|--|--|
| |  | |
| |  | |
| |  | |
| Steering Components | 3 - Normal Wear & Tear | |
| Comments | reservoir hose to gearbox wet (see page leak?) | |

Inspection Report (On-Highway Truck Basic Template)




Steering Components Photos



Inspection Report (On-Highway Truck Basic Template)

| | | |
|---|--|--|
| |  | |
| |  | |
| <p>Steer Axle Condition</p> | <p>4 - Like New, Recently Replaced</p> | |
| <p>Steer Axle Condition Photos</p> |  | |


Inspection Report (On-Highway Truck Basic Template)

| | | |
|----------------------------------|--|--|
| |  | |
| Wheels & Tires | 3 - Normal Wear & Tear | |
| Comments | all tires safe to use for operating | |
| Wheels & Tires Photos |  | |
| |  | |

Inspection Report (On-Highway Truck Basic Template)



Inspection Report (On-Highway Truck Basic Template)






| | |
|------------------------------------|--|
| Tire Brand | Hankook (rears are Michelin and continental mix) |
| Front Left Tire - Ratio Remaining | 30% |
| Front Right Tire - Ratio Remaining | 30% |
| Rear Right Tire - Ratio Remaining | 70% |
| Rear Left Tire - Ratio Remaining | 50% |




Additional Axle(s)

Additional Axle

Inspection Report (On-Highway Truck Basic Template)

| | |
|----------------------------------|--|
| Instructions | Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos. |
| Steerable? | No |
| Drop Axle? | No |
| Axle Condition | 4 - Like New, Recently Replaced |
| Comments | 3rd axle |
| Axle Condition Photos |  |
| Wheels & Tires | 3 - Normal Wear & Tear |
| Wheels & Tires Photos |  |
| |  |
| Tire Brand | rs continental ls michelin |

Inspection Report (On-Highway Truck Basic Template)

| | |
|--|--|
| Tire Size | 11R 22.5 |
| Left Tire(s) Ratio Remaining | 30% |
| Right Tire(s) Ratio Remaining | 70% |
| Overall Chassis | 4 - Like New, Recently Replaced |
| Overall Chassis & Undercarriage Photos |  |
| |  |
| |  |

Functional Test

Inspection Report (On-Highway Truck Basic Template)

| | |
|---|--|
| Instructions | Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate): 4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required |
| Forward & Reverse | 4 - Like New, Recently Replaced |
| Steering | 4 - Like New, Recently Replaced |
| Engine | 4 - Like New, Recently Replaced |
| Controls | 4 - Like New, Recently Replaced |
| Overall Functional Test Comments | Engine and transmission look well maintained. They operate normal with no signs of problems. |
| Operating Video | Click to Download |

Inspection Summary

| | |
|---------------------------------------|---|
| Exterior Rating | 4 - Like New, Recently Replaced |
| Interior Rating | 4 - Like New, Recently Replaced |
| Safety Rating | 4 - Like New, Recently Replaced |
| Quality Rating | 4 - Like New, Recently Replaced |
| Functionality Rating | 4 - Like New, Recently Replaced |
| Overall Rating | 4 - Like New, Recently Replaced |
| What's Great About the Machine | The truck has been maintained to top standards! All safety items on truck checked out solid. Brakes in really good shape with no air leaks found. For being 12 years old it's held together really well. |
| What Needs Work | *Small engine oil leak at rear of oil pan or coming from rear left side of engine area. *1 beacon light inoperable *batteries may need to be changed soon (Possible electrical draw with key off) *driver side seat belt won't retract easily |
| Inspector's Name | Mario Ramirez |
| Date/Time | 07-29-2022 |