

Inspection Report (On-Highway Lube Truck)

General Info

Year	2011
Make	Peterbilt
Model	367
Serial Number	1NPTLU0X1BD130009
Truck Odometer Reading	275,694miles 3,070hours
Current Inspection / State Cert / DOT	completed 4/20/22 @270,214 miles
Previous Application (e.g., earth moving, mining, demolition, etc)	asphalt and general construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	33' 2"
Width (ft and inches)	8' 4" with side handles/steps
Height (ft and inches)	11' 4"
Wheelbase (ft and inches)	12' 8"
GVWR (lbs)	60,000

Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans. Mounted Chelsea 489XHAHX-A3XD
Engine Break	Yes
Differential Lock	Yes
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Auxiliary Engine	No
Liftgate	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Lube Truck)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)





Inspection Report (On-Highway Lube Truck)






General Appearance Inspection Points

General Appearance

Front	4 - Like New, Recently Replaced
Front Condition	No visible damage
Front Photos	
	




Inspection Report (On-Highway Lube Truck)

		
Rear	3 - Normal Wear & Tear	
Rear Condition	Visible chipped paint or dents, Other (see comments)	
Comments	small dents on bottom corners of bumper	
Rear Photos		
		




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

		
Left	3 - Normal Wear & Tear	
Left Condition	No visible damage, Other (see comments)	
Comments	minor scuff marks, small paint chips, small rust area on diesel fuel tank (2")	
Left Photos		
		




Inspection Report (On-Highway Lube Truck)

		
		
Right	4 - Like New, Recently Replaced	
Right Condition	Other (see comments)	
Comments	minor paint scratches,	
Right Photos		

Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)

		
Upper	4 - Like New, Recently Replaced	
Upper Condition	No visible damage, Other (see comments)	
Comments	normal wear overall great condition	
Upper Photos		
		


Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

		
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear	
Body Panel Condition	No visible damage, good paint condition and panel fitment, Other (see comments)	
Comments	minor scuff marks on side cabinets	
Body Panels Photos		
		




Inspection Report (On-Highway Lube Truck)




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

	
	
Doors / Canopy Latches	4 - Like New, Recently Replaced
Doors / Canopy Latches Condition	No visible damage
Doors / Canopy Latches Photos	


Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

		
		
Glass Condition	4 - Like New, Recently Replaced	
Glass Condition Notes	Glass intact, no visible damage	
Glass Condition Photos		




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)

		
		
Mirrors	4 - Like New, Recently Replaced	
Mirror Condition Notes	Mirrors present and intact, no visible damage	
Mirrors Photos		

Inspection Report (On-Highway Lube Truck)




Inspection Report (On-Highway Lube Truck)

		
Lighting System	4 - Like New, Recently Replaced	
Lighting System Condition	No visible damage, lighting system is operational, Other (see comments)	
Comments	all auxiliary work lights functional!	
Lighting System Photos		
		

Inspection Report (On-Highway Lube Truck)




Inspection Report (On-Highway Lube Truck)






Cab Inspection Points

On Highway - Cab

Instructions	<p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <ul style="list-style-type: none"> 4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required <p>Take close-up photos of and leave comments.</p>
Serial Number Plate Photo	

Inspection Report (On-Highway Lube Truck)

Operator Cabin	3 - Normal Wear & Tear
Comments	normal wear and tear
Operator Cabin Photos	
	
	

Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)

	
Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Photos	
	
Seat Belt	3 - Normal Wear & Tear

Inspection Report (On-Highway Lube Truck)

<p>Seat Belt Photos</p>	
	
<p>Cabin Lights</p>	<p>3 - Normal Wear & Tear</p>
<p>Cabin Lights Photos</p>	




Inspection Report (On-Highway Lube Truck)

		
Controls & Switches	3 - Normal Wear & Tear	
Comments	A/C & Heater fan speed control only works in position #4 (1,2,3, inop.)	
Controls & Switches Photos		
		




Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)

	
Odometer Activity	3 - Normal Wear & Tear
Odometer Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Activity Photos	



Inspection Report (On-Highway Lube Truck)

	
Heater & A/C	4 - Like New, Recently Replaced
Comments	a/c exceeds 30° temperature drop
Heater & A/C Photos	
	

Inspection Report (On-Highway Lube Truck)

		
Fans / Vents	3 - Normal Wear & Tear	
Fans / Vents Photos		
		

Inspection Report (On-Highway Lube Truck)

	
Horn	4 - Like New, Recently Replaced
Reverse Alarm / Backup Signal	7
Backup Camera	0
Other Electronic Devices	0
Fire Extinguisher	4 - Like New, Recently Replaced
Comments	2 1/2 lbs. extinguisher expires May of 2023
Fire Extinguisher Photos	
First Aid Kit	0

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	CAT C13 /6 CYL. /12.5L./ 470hp
Engine Serial Number	LEE22162
Engine Fuel Type	Diesel

Inspection Report (On-Highway Lube Truck)

Engine Photos



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)




Inspection Report (On-Highway Lube Truck)





Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	4 - Like New, Recently Replaced	
Battery Condition	Like new, recently replaced, Other (see comments)	
Comments	batteries upgraded to Optima High Performance 10/2021	




Inspection Report (On-Highway Lube Truck)

Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

	
	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension, Other (see comments)
Comments	alternator serpentine belt showing signs of wear (belt cracks)
Belt Photos	

Inspection Report (On-Highway Lube Truck)

	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Hose Photos	
	



Inspection Report (On-Highway Lube Truck)




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

		
Water Pump	4 - Like New, Recently Replaced	
Water Pump Condition	No unusual pump noises heard, Other (see comments	
Comments	may have been recently replaced (looks new)	
Water Pump Photos		
Cooling System Leaks	No	
Coolant Color / Appearance	4 - Like New, Recently Replaced	
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination	
Oil Leaks	No	
Oil Color / Appearance	4 - Like New, Recently Replaced	
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level	

Inspection Report (On-Highway Lube Truck)

Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine in top notch condition with no visible issues or any fluid leaks!

Aux. Engine Inspection Points

Instructions	<p>Assess the condition of the aux. engine / power unit.</p> <p>For items on a 4 point scale, evaluate using the following criteria:</p> <p>4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required</p>
--------------	---

Drivetrain Inspection Points



Drivetrain	
Transmission Info (Make/Model)	Eaton 13spd
Drive Type	4X2
Overdrive	N/A
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations

Inspection Report (On-Highway Lube Truck)




Transmission Condition Photos






Inspection Report (On-Highway Lube Truck)

	
Clutch	3 - Normal Wear & Tear
Clutch Condition	Clutch is functioning as expected
Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function
Shift Lever Photos	
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation, Other (see comments)
Comments	both rear axles same condition

Inspection Report (On-Highway Lube Truck)

Rear Differential Photos	
	
	
Front Differential	0
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Air Brake System Leaks	No
Comments	brakes pass regular air brake inspection
Air Brake Hose Condition	3 - Normal Wear & Tear

Inspection Report (On-Highway Lube Truck)

<p>Air Brake System Photos</p>		
		
		




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)




		
		
Foot Brake	3 - Normal Wear & Tear	
Foot Brake Condition	Good brake function	
Foot Brake Photos		
Engine Brake Configuration	1 Position	
Engine Brake	3 - Normal Wear & Tear	
Parking Brake	4 - Like New, Recently Replaced	
Parking Brake Condition	Good brake function	
Overall Drivetrain Comments	All components above average condition Front right brake shoes at 50% life left	

Inspection Report (On-Highway Lube Truck)

Chassis & Axle Inspection Points

Chassis


Frame

Frame Condition	4
Frame Photos	
	
	


Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Suspension

Suspension	3
Suspension Photos	



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Steering

Steering Components	3
Steering Components Photos	
	




Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)





Inspection Report (On-Highway Lube Truck)

		
Steer Axle Condition	4	
Steer Axle Photos		
		




Inspection Report (On-Highway Lube Truck)






Wheels & Tires

Wheels & Hub Condition	3
Wheels & Hub Photos	
	




Inspection Report (On-Highway Lube Truck)

	
	
Tire Brand	Yokohama
Tire Size	315/80R/22.5 & 11R/22.5 for the rear
Front Left Tire - Ratio Remaining	50%
Front Left Tire Photos	
Front Right Tire - Ratio Remaining	70%




Inspection Report (On-Highway Lube Truck)

Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	30%
Rear Right Tire Photos	
	

Inspection Report (On-Highway Lube Truck)

		
		
		
<p>Rear Left Tire - Ratio Remaining</p>	<p>50%</p>	



Inspection Report (On-Highway Lube Truck)

<p>Rear Left Tire Photos</p>		
		
		

Inspection Report (On-Highway Lube Truck)




Brake Components

Brake Shoe Thickness	90%
Brake Shoe Photos	 A close-up photograph of the brake shoes inside a wheel hub. The shoes are dark and appear to be in good condition. A bright light source is visible on the right side of the image.
	 A close-up photograph of the brake assembly, showing the brake shoes, the brake drum, and the hydraulic lines with fittings. The components are dusty and show signs of use.


Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)



Overall Chassis Condition

Overall Chassis	4
Overall Chassis & Undercarriage Photos	




Inspection Report (On-Highway Lube Truck)

		
		
		
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.	




Lube Truck Inspection Points

Fuel Tanks	Describe the number, configuration, capacity, and contents of all fuel tanks equipped on the vehicle
Number of Tanks	3
Fuel Tank(s) Contents & Capacity	2 x 1000gal. diesel 1 x 250gal. Gas
Fuel Tank(s) Exterior Condition	3

Inspection Report (On-Highway Lube Truck)

Comments	small rust mark on exterior left side tank
Fuel Tank Exterior Photos	
	
	

Inspection Report (On-Highway Lube Truck)

		
		
		
Mounting Bolts	4	
Comments	all hardware intact	
Fuel Tank(s) Interior Condition	3	

Inspection Report (On-Highway Lube Truck)


Fuel Tank Interior Photos



Inspection Report (On-Highway Lube Truck)

	
Tank Baffles Intact?	Yes

Oil & Fluid Reservoir Tanks

Oil & Fluid Reservoirs	Check the condition of the vehicle's hydraulic system
Number of Tanks	6
Pumps Installed on Tanks	Yes
Number of Pumps	5
Tank Configuration (Contents, Capacities)	Tanks store Eng. oil, Antifreeze, Gear oil, Hydraulic oil, 50w. Oil., water and grease
Exterior Tank(s) Condition	3
Exterior Tank(s) Photos	




Inspection Report (On-Highway Lube Truck)





Mounting Bolts

3




Inspection Report (On-Highway Lube Truck)

Mounting Bolts Photos		
		
		




Inspection Report (On-Highway Lube Truck)

		
		
Interior Tank(s) Condition	3	
Comments	unable to capture picture, visually look okay	
Pump(s) Appearance	3	
Comments	air regulator gauges worn (unable to read psi properly)	




Inspection Report (On-Highway Lube Truck)

Pump(s) Photos	
	
	
Pump(s) Functionality	4
Grease Pump Installed	Yes
Grease Pump Condition	3
Grease Pump Functionality	5

Inspection Report (On-Highway Lube Truck)

Grease Pump Photos		
		
		
Hose Reels & Nozzles	3	




Inspection Report (On-Highway Lube Truck)

Hose Reels & Nozzles Photos		
		
		

Truck Hydraulics

Truck Hydraulics	Check the condition of the vehicle's hydraulic system
Hydraulic PTO	Yes
Mounting Type	transmission mounted, driveshaft driven
Hydraulic Tank Capacity	100 gallon?
Hydraulic Tank Condition	3


Inspection Report (On-Highway Lube Truck)

Hydraulic Tank Photos	
	
PTO Condition	3
Unusual Noises Heard	No
Leaks Found	No
Hydraulic Hoses & Fittings	3
Hydraulic Hoses & Fittings Photos	


Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Storage

Storage	Check the condition of all storage cabinets (interior & exterior), latches, locks, hinges, and slide out features if applicable.
Toolboxes & Cabinets	3
Comments	some left side toolbox latches (slide out tool storage) broken
Toolboxes & Cabinets Photos	




Inspection Report (On-Highway Lube Truck)






Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

	
	
	
Latches & Locks	3
Comments	door latches all good, left side tool storage internal latches broken




Inspection Report (On-Highway Lube Truck)

<p>Latches & Locks Photos</p>	
<p>Hinges</p>	<p>3</p>
<p>Hinges Photos</p>	
	

Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)

		
		
Slide Out Features	Yes	
Slide Out Configuration	oil filter waste drawer and left side tool storage	
Slide Out(s) Condition/Function	3	
Slide Out(s) Photos		

Inspection Report (On-Highway Lube Truck)



Additional Equipment

Additional Auxiliary Equipment	Add details and evaluate the condition of any additional specialty equipment the vehicle is equipped with including welders, air compressors, pressure washers, and auxiliary tanks or systems.
--------------------------------	---

Additional Equipment

Additional Attachments


Attachment Type	pto driven air compressor and waste oil suction and discharge pump
Attachment Make	n/a
Attachment Size / Specs	30 gallon
Attachment Condition	3 - Normal Wear & Tear



Inspection Report (On-Highway Lube Truck)



Inspection Report (On-Highway Lube Truck)



Functional Test

Instructions	Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate): 4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required
Forward & Reverse	4 - Like New, Recently Replaced
Steering	4 - Like New, Recently Replaced
Engine	4 - Like New, Recently Replaced
Controls	4 - Like New, Recently Replaced
Operating Video	Click to Download

Inspection Summary

Exterior Rating	4 - Like New, Recently Replaced
Interior Rating	3 - Normal Wear & Tear
Safety Rating	4 - Like New, Recently Replaced
Quality Rating	4 - Like New, Recently Replaced
Functionality Rating	4 - Like New, Recently Replaced

Inspection Report (On-Highway Lube Truck)

Overall Rating	4 - Like New, Recently Replaced
What's Great About the Machine	The Lube Truck has been well maintained. This truck is fully equipped and is ready to be put to work. Passes all safety items for a 90 day B.I.T. inspection.
What Needs Work	<ul style="list-style-type: none"> •A/C fan speed controller only works on max speed •Front R/S Brake shoes getting low •Alternator serpentine belt showing signs of wear •Small rust area on left side of Diesel fuel tank (1000gal)
Any Additional Info from the Seller?	Seller stated truck is fully operational
Inspector's Name	Mario Ramirez
Date/Time	08-04-2022